RADC-TR-82-87 Final Technical Report May 1982



STRESS SCREENING OF ELECTRONIC HARDWARE

Hughes Aircraft Company

A.E. Saari, R.E. Schafer and S.J. VanDenBerg

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.

ROME AIR DEVELOPMENT CENTER Air Force Systems Command Griffiss Air Force Base, NY 13441

REPRODUCED BY
NATIONAL TECHNICAL
INFORMATION SERVICE
U.S. DEPARTMENT OF COMMERCE
SPRINGFIEL DY. A 22161

UNCLASSIFIED

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
REPORT NUMBER 12, GOVT ACCESSION NO	
RADC-TR-82-87 -	•
A. TITLE (and Subunto) STRESS SCREENING OF ELECTRONIC HARDWARE	i. Type of Report a PERIOD COVERE Final Technical Report August 80 - September 81
	FR82-16-132
- AUTHOR(e)	B. CONTRACT OR SHANT NUMBER(S)
A.E. Saari S.J. VanDenBerg R.E. Schafer	F30602-80-C-0250
PERFORMING ORGANIZATION NAME AND ADDRESS Hughes Aircraft Company Ground Systems Group, P.O. Box 3310 Fullerton CA 92634	10. PROGRAM ELEMENT PROJECT, TASK AREA & HORK UNIT NUMBERS 62702F 23380242
CONTROLLING OFFICE NAME AND ADDRESS Rome Air Development Center (RBET)	May 1982
Griffiss AFB NY 13441	13. NUMBER OF PAGES
14. MONITORING AGENCY NAME & ADDRESS/II different from Controlling Office)	15. SECURITY CLASS, for this report;
_	UNCLASSIFIED
Same	154. DECLASSIFICATION/ DOWNGRADING N/A
16. DISTRIBUTION STATEMENT (of this Report)	
Approved for public release; distribution unlim	nited

17. DISTRIBUTION STATEMENT (of the obstract entered in Black 20, if different from Report)

Same

18. SUPPLEMENTARY NOTES

RADC Project Engineer: Eugene Fiorentino

19. KEY #ORDS (Continue on reverse side if necessary and identity by block number)
Screening

Stress Screening

Environmental Stress Screening

Stress Screening Model

20. ABSTRACT 'Continue on reverse side if necessary and identify by block number)

This report presents the results of a study to develop quantitative and qualitative techniques for planning, monitoring and evaluating stress screening programs during electronic equipment development and production. A screening and debugging optimization (SDO) model developed on a prior study, RADC-TR-78-55, was revised to include current thermal cycling and vibration screening experience and an adaptive feature was added to allow stress screening program changes based on screening results. Guidelines

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED FROM THE BEST COPY FURNISHED US BY THE SPONSORING AGENCY. ALTHOUGH IT IS RECOGNIZED THAT CERTAIN PORTIONS ARE ILLEGIBLE, IT IS BEING RELEASED IN THE INTEREST OF MAKING AVAILABLE AS MUCH INFORMATION AS POSSIBLE.

This report has been reviewed by the RADC Public Affairs Office (PA) and is releasable to the National Technical Information Service (NTIS). At NTIS it will be releasable to the general public, including foreign nations.

RADC-TR-82-87 has been reviewed and is approved for publication.

APPROVED:

Engline Ferrentin

EUGENE FIORENTINO Project Engineer

APPROVED:

EDMUND J. WESTCOTT, Technical Director Reliability & Compatibility Division

FOR THE COMMANDER:

JOHN P. HUSS

Acting Chief, Plans Office

If your address has changed or if you wish to be removed from the RADC mailing list, or if the addressee is no longer employed by your organization, please notify RADC (RBET) Griffiss AFB NY 13441. This will assist us in maintaining a current mailing list.

Do not return copies of this report unless contractual obligations or notices on a specific document requires that it be returned.

EVALUATION

- 1. The objective of this study was to develop methodologies and techniques for planning, monitoring and evaluating stress screening programs during electronic equipment development and production.
- 2. The study objectives have been successfully achieved. Both qualitative and quantitative guidelines have been developed for tailoring screening procedures to specific hardware development and production programs. A methodology for screen selection and placement and for monitoring the screening process through use of adaptive procedures has also been developed. In addition, a previously developed stress screening model has been simplified and updated to include more recent stress screening experience. The model establishes a quantitative basis for planning and control. All of the major variables and inputs required for planning and evaluating screening programs are addressed through use of the model. Application of the techniques should greatly enhance the stress screening practitioner's capability to plan and conduct screening programs in a cost-effective manner.
- 3. Use of the techniques and methodology contained in the report should hopefully foster the development of a broader data base for estimation of model parameters and input variables. Users are encouraged to provide feedback of information on their application experience and results.

in the territor

EUGENÉ FIORENTINO Project Engineer

FOREWORD

This study was conducted to develop quantitative and qualitative techniques for planning, monitoring and evaluating stress screening programs. The effort included investigation of technical and economic factors leading to the adoption of a screening program and identifying factors which influence the selection of particular screens and placement of screens at various assembly levels.

A product of this study effort is a set of three computer programs (comprising the Stress Screening Model) which are intended to aid the stress screening practitioner in selecting screens, setting screening parameters and adjusting screens on the basis of observed results. The function of the Stress Screening Model (SSM) is to exercise some mathematical routines designed to find an optimum set of screens to achieve the desired, (user-input) results, subject to the user-indicated constraints.

If the quantity and type of latent defects present in equipment during each level of manufacture were known and the ability of the various stress screens to precipitate those defects into hard, detectable failures was also known, the planning of stress screening programs would be greatly simplified. Actually, the nature and magnitude of defects present are unknown and changing with time; screening strengths are not well understood and appear to be hardware dependent. Much stress screening has been done in the past several years and general patterns are beginning to emerge. Screening appears to be cost-effective. Temperature cycling and random vibration are commonly used screens and appear to be effective screens. Temperature cycle screening effectiveness appears to increase with wider temperature range and greater rates of change. Random, or broadband, vibration appears more effective than single or swept frequency vibration. Constant temperature burn-in, power cycling, and low level single frequency vibration screens do not appear to be generally effective. These patterns form an industry consensus on stress screening effectiveness.

The Martin-Marietta temperature cycling curves (Ref. 7) and the Grumman vibration curves (Ref. 8) are combined into UAVMAT P-9492 and are generally representative of the industry consensus. Screening strength equations developed previously by Hughes were modified to reflect the Martin/Grumman data and further adjusted to satisfy other stress screening results. The screening strength equations should not be interpreted as scientifically derived equations of general applicability but rather as useful tools to serve as a quantitative basis for planning and controlling a stress screening program. Use of the stress screening equations in conjunction with the screen selection and placement guidelines will provide a sound planning basis.

Careful review of stress screening results will enable the proper adjustment of the screening strength equations to match the items being screened through use of the SSM adaptive feature.

The SSM is easy to use but this should not be interpreted as meaning that planning, monitoring and evaluating a stress screening program is simple. Rather, it is the intent of the authors to provide a model which accepts all the major variables as user inputs, when available, but which can be meaningfully used when some input data is not available. The SSM contains default values for all but two user inputs and while considerable data gathering and analysis was necessary to establish the default values, they must be considered applicable only to the source from which they were derived. Each user should establish his own set of input variables applicable to his production processes and hardware item characteristics to make best use of the SSM and to have the most confidence in the results.

TABLE OF CONTENTS

Paragraph	Title	Page
1.	Introduction and Summary	1
1.1	Introduction	1
1.1.1	Objective and Scope of Study	2
1.2	Summary of Study	2
1.2.1	Study Approach	2
1.2.2	The SDO Model	3
1.2.3	Screening Strength Equations	5
1.2.4	Adaptive Screening	
1.3	Summary of Industry Surveys	
1.3.1	Surveys Previously Conducted and Reviewed	
	for this Study	8
1.3.2	Martin-Marietta Survey (Ref. 7)	8
1.3.3	McDonnell Aircraft Company Survey (Ref. 11).	9
1.3.4	Institute of Environmental Sciences	
	(IES) Survey (Ref. 12)	11
1.3.5	Survey Consensus	
2.	Planning a Stress Screening Program	18
2.1	Introduction	18
2.2	Developing a Stress Screening Plan	19
2.2.1	Establishing an Objective	19
2.2.2	Determining if a Stress Screening Program	
,,	is Appropriate	19
2.2.2.1	Field Maintenance Cost Savings	
	through Stress Screening	20
2.2.2.2	Using Stress Screening to Achieve a	
	Reliability Requirement	23
2.2.2.3	Manufacturing Cost Savings through	
		24
2.2.3	Stress Screening	27
2.2.3.1	Part Failures in Field Use	27
2.2.3.2	Relationship of Part Fraction Defective	
	to Quality Grade	31
2.2.3.3	Incoming Receiving Inspection and Test	34
2.2.4	Manufacturing Process Defects	36
2.2.4.1	Sources of Defects	36
2.2.4.2	Distribution of Defects	
2.2.5	Screen Selection and Placement	
2.2.5.1	General Industry Consensus on Screen	
	Selection and Placement	39
2.2.5.2	Technical and Economic Factors to Consider	-
	in Selection and Placement of Screens	40
2.2.5.2.1	Factors to Consider in Assembly Level	
	Screen Selection	40
2.2.5.2.2	Factors to Consider in Unit Level Screen	
		47
2.2.5.3	Selection	48

TABLE OF CONTENTS (Continued)

Paragraph	Title	Page
2.2.6	Planning a Stress Screening Program	
	for the Development Phase	49
2.2.6.1	Characteristics of a Development Phase	49
2.2.6.2	Pro's and Con's of Stress Screening in a	
	Development Phase	49
2.2.6.3	Relationship of Stress Screening and	
2.2.0.5	Reliability Growth	50
2.2.7		50
2.2.1	Planning a Stress Screening Program for	E 0
2 2 2 1	the Production Phase	50
2.2.7.1	Using Development Phase Results to Guide	
	Production Phase Planning	50
2.2.7.2	Initial Production Phase Start-up	
	Problems	51
2.2.7.3	Planning for Subcontractor/Supplier	
	Stress Screening	51
2.3	Contractual Considerations in Stress	
	Screening	52
2.3.1	General Considerations	52
2.3.2	Contractual Flexibility to Permit Stress	
	Screening Program Adaptability	52
2.3.3	Failure Free Cycles	53
2.3.4	Incentives Associated with Stress Screening	53
2.3.4	incentives associated with beleas beleening	23
3.	Data Collection, Analysis and Reporting	55
3.1	Data Collection	55
3.1.1	Data Collection Requirements for Stress	
	Screening Program	55
3.1.2	The Role of Failure Analysis in Determining	
31212	Screening Effectiveness	57
3.1.3	Analysis of Stress Screening Data	5 <i>7</i>
3.1.3.1	Data Analysis for Monitoring the Stress	31
3.1.3.1	Screening Program	57
3.1.3.2	Date Analysis for Evaluating the Change	31
3.1.3.2	Data Analysis for Evaluating the Stress	=0
	Screening Program	58
3.1.3.3	Using the Chance Defective Exponential	
	(CDE) Model to EValuate Stress Screening	
	Results	59
3.2	Reporting of Results	61
3.2.1	Purpose of Reporting Results	61
3.2.2	Reporting Methods	61
3.2.3	Report Content	61
4.	Mho Chrose Carooning Model (CCM)	63
	The Stress Screening Model (SSM)	63
4.1	Description of the Model	63
4.1.1	Model Options	64
4.1.2	The MTBF Option	64
4.1.3	The Cost Option	65
4.1.4	The Trade-off Option	65
4.1.5	Description of User Inputs to SSM and Model	
	Defaults	65

TABLE OF CONTENTS (Continued)

Paragraph	Title	Page
4.1.6	Determining the Initial Fraction	
	Latent Defectives	71
4.2	Using the Model	73
4.2.1	General Instructions for User	73
4.2.2	IBM 370 TSO User Instructions	75
4.3	Thermales of COM Vice	
	Examples of SSM Use	79
4.3.1	MTBF Option Examples	79
4.3.1.1	Planning a Stress Screening Program to	
	Achieve a Certain MTBF, without Pre-	
	established Screens	79
4.3.1.2	Planning a Stress Screen Program to	
4.3.1.6		
	Achieve a Certain MTBF, with Pre-	
	established Screens	91
4.3.1.3	Planning a Stress Screening Program to	
	Achieve a Certain MTBF, No Solution	98
4.3.2	Cost Option Example	⊥ 09
4.3.3	Tradeoff Option Examples	118
	The lasting of Delating Course	
4.3.3.1	Evaluating an Existing Screen	118
4.3.3.2	Adapting Screens Based on Observed	
	Results	130
4.3.4	Example Using the CDE Model to Evaluate	
	Screening Results	140
	borooming acousted in the contract of the cont	1.0
DEFEDENCE	ES	151
REF ERENCI	ES	131
APPENDIX A:	Development of Screening Strength Equations	155
APPENDIX B:	Statistical Aspects of Adaptive Screening .	167
APPENDIX C:	The Chance Defective Exponential (CDE)	
ALLENDIA C.	Model	171
	model	1/1
_		
APPENDIX D:	Approximation of Screening Strength	
	Using Observed MTBF	175
APPENDIX E:	Long Term Reliability Through Natural Latent	
	Defect Reduction	177
		1//
APPENDIX F:	We led Course Developed	101
WLLEWNIY L:	Model Computer Program Listings	· rar

LIST OF TABLES

No.	Title	Page
1.1	Summary of Three Previous Surveys	14
2.1	Manufacturing Stress Screening Cost	
2.2	Analysis Example	27
	Test Microcircuit Rejects	35
2.3	Recent Receiving Inspection Test Results .	35
2.4	Interconnection Defects Detected at First	
	Test for Early Production PWAs	38
2.5	Part Defects Detected at First Test for	20
2.6	Production PWAs	39
2.6	Results of First Opportunity Wire Testing of Unit Wiring	39
2.7	Distribution of Screening Methods for	
,	Various Classes of Parts	42
2.8	Assembly Level Defect Types Precipitated	
	by Thermal and Vibration Screens	43
4.1	Stress Screening Model User Input Data	
	Requirements & Model Input Values	66
4.2	Test Parameter Cross Reference	69
4.3	Initial Fraction Latent Defective Parts	73
4.4	Parts Mix for Sample Generic Equipments	74

LIST OF FIGURES

Figure	Title	Page
1.1	A Typical Production Process. Finding defects at the lowest level of manufacture	
	is most cost effective	3
1.2	Screening Strength for a Random Vibration Screen	6
1.3	Screening Strength for a Swept-Sine Vibration Screen	6
1.4	Screening Strength for a Single (Fixed)	
1.5	Frequency Vibration Screen	
1.6	Cycling Screen (R=100)	7
	Temperature Screen	7
2.1	Latent Defect Flow for Process without Stress Screening	21
2.2	Field Maintenance Costs for Repair	
2.3	Resulting from Latent Defects Latent Defect Flow for Process with	22
2.4	Stress Screening	21
	Latent Defect Fallout (2,000-part system)	25
2.5	Field MTBF Improvement through Natural Latent Defect Fallout (10,000-part system) .	25
2.6	Field MTBF Improvement through Natural Latent Defect Fallcut (20,000-part system) .	25
2.7	Production Flow Model without Stress Screening	26
2.8	Production Flow Model with Stress	
2.9	Screening	26
	Assembly Repair Cost Analysis	. 28
2.10	Unit Repair Cost Analysis	29
2.11	Distribution of Failures by Classification and by Time for a Radar Development Project.	30
2.12	Distribution of Failures by Type for Three Recent Development Programs	. 32
2.13	Fraction of Defective Assemblies as a Function of Initial Part Fraction	. 3-
2.14	Defective	. 33
	track the chamber temperature very closely	45
2.15	Probability of Passing a Failure Free Period of Duration 0.1 x Specified MTBF	. 54
3.1	Temperature Cycling Data Fitted to the Chance Defective Exponential Model	. 60
4.1	Stress Screening Model Representation of the Production Flow Process	. 63
4.2	Flow Diagram of the Stress Screening Model	

'1. INTRODUCTION AND SUMMARY.

Introduction. The use of environmental stress screening of electronic hardware during development and production has increased significantly in the past few years among many military electronic equipment manufacturers. The basic intent of stress screening is to detect latent defects, by subjecting test items to specific conditions of environmental stress, so that such defects can be degraded to a detectable level. "Latent defects", as used here, represent weaknesses in parts, workmanship and to some extent design, which result in much higher failure rates than what may be indicated by predicted inherent failure rate Electronic equipment delivered to the field often contain latent defects traceable to the production process. Such defects result in abnormally high failure rates and excessive repair costs in the field. Early stress screening of modules and assemblies, during production, is a widely accepted, effective means of alleviating the problem. Screening programs may be, however, costly to perform and may not be fully effective, perhaps even detrimental, if improperly applied and controlled. The technology base, in addition, for screening test selection, effectiveness measurement, and cost control, is largely under developed.

Stress screening programs should be designed to precipitate and detect latent defects early in the production cycle when it is most cost-effective to do so. Early stress screening can increase the likelihood of the completed equipment passing final acceptance and reliability demonstration tests and may eliminate or reduce the need for costly burn-in or reliability growth programs at the system level. Early life stress screening of modules and subassemblies, therefore, can offer a cost-effective means of enhancing equipment reliability and reducing production and field support costs.

Due to the varied nature of military electronics equipment and their associated design, development and production program elements, it is difficult to "standardize" on a particular screening approach. A tailoring of the screening process to the unique elements of a given program is, therefore, required. Screening tests such as temperature cycling and random vibration appear to be the most effective tests. However, exposure levels, number of cycles, and test durations differ widely among users. Other, perhaps less costly, tests such as sinusoidal vibration, power cycled burn-in at ambient and temperature soak are also used, but, in general, their effectiveness is believed to be less than the former tests. Precise information of the effectiveness of the various available screening tests is not currently known. Screening tests therefore should be selected based upon estimates of cost and test effectiveness, early development program data and on equipment design, manufacturing, material and process variables, which at least, narrow consideration to the most

cost-effective choices. The screening process then should be continuously monitored and test results analyzed so that changes in the process can be made, as required, to optimize the cost-effectiveness of the screening program.

A survey of the current literature has shown that although the use of stress screening is on the increase, there is little general guidance as to how to best plan, monitor and control a stress screening program. The Institute of Environmental Sciences (IES), a professional organization of engineers and scientists, currently has a national program underway to develop a guideline document for Environmental Stress Screening of Electronic Hardware. Results of this effort were published in a guidelines document (Ref. 12).

Hughes Aircraft Company is also preparing a Stress Screening Guidelines document for internal use which is expected to be released in 1982.

1.1.1 Objective and Scope of Study. The objective of this study was to develop quantitative and qualitative techniques for planning, monitoring and evaluating stress screening programs during electronic equipment development and production. The work effort investigated methodologies for test selection and control which provide assurance that reliability growth is achieved in a cost-effective manner throughout the development and production process. The work performed was concerned primarily with the cost-effectiveness of stress screening at levels of assembly above the part level, i.e., assembly/module, unit/group and equipment/system. Part level screening considerations were included in the study only to the extent that the quality grade of components used influences the initial quantity of latent defects and therefore the planning of the stress screening program.

1.2 Summary of Study

The basis of stress screening is the 1.2.1 Study Approach. elimination of latent defects at a point in the production process when it is least costly to do so. Figure 1.1 depicts a typical production process where parts and printed circuit boards (PCB) or wired chassis comprise assemblies; then manufactured assemblies, purchased assemblies and associated wiring comprise units; and finally the units, other equipment and intercabling make up the completed system. Latent defects are introduced at each stage in the process and, if not eliminated, propagate through to field use. The cost of repair increases with increasing levels of assembly, being \$1 to \$5 at the part level and perhaps as high as \$1000 at the system level. Field repair cost estimates have been quoted as high as \$15,000. For economic reasons alone, it is desireable to eliminate latent defects at the lowest possible level of assembly and certainly prior to field use.




Figure 1.1. A Typical Production Process. Finding defects at the lowest level of manufacture is most cost effective.

Latent defects can be transformed into patent, or hard, defects through the application of environmental stresses such as elevated temperature operation, temperature cycling or vibration.

The probability that a stress screen will transform a latent defect into a hard failure (given that there is a latent defect present) and that failure will be detected by the screen is called "screening strength". Screening strength varies with the screen parameters, (e.g., the strength of a temperature cycle screen increases with increases in temperature extremes, temperature rate of change and number of cycles). But there is a cost associated with application of a stress screen and that cost varies with screening strength. There are then many possible combinations of screening strengths and screening costs at each level of assembly and the objective is to find the lowest cost set of screens that produces the desired results. A computer program is available to perform this "optimization" function and is discussed below.

1.2.2 The SDO Model. A prior study (Ref. 1) conducted by Hughes for RADC resulted in development of a Screening and Debugging Optimization (SDO) model which provides an optimum set of stress screens based on model inputs of estimated number of initial and process-induced defects and estimated screening costs. The model contains empirical screening strength equations for five stress screen types (constant temperature, constant power, cycled power, cycle temperature, and vibration) in which the screening strength is a function of screening parameters such as temperature extremes, number of cycles, rate of change of temperature, and screen duration. Since there are a very large number of combinations of stress screens and screen costs at each level of

assembly, e.g., at assembly/module, unit/group, and equipment/system levels, the SDO model utilizes a dynamic programming algorithm to find the optimum solution to either,

- 1) the set of screens which achieve a predetermined reduction of latent defects for the least cost, or
- 2) the set of screens which achieve the maximum reduction of latent defects for a fixed cost.

The SDO model was retained for this study because of its optimization capability. However, many changes were made to the model during the course of this study, as indicated below.

Previous SDO Model

Screening strength equations do not reflect recent stress screening experience.

- Vibration screening strength equation is only for single frequency vibration.
- 3) Model is difficult to use. Use lany user inputs are required. by:

Model Changes

More current equations were substituted for existing equations.

Equations were added for random vibration and swept-sine vibration. A new equation for single frequency vibration was substituted.

Use of the model was simplified 1. by:

- a. Minimizing user input requirements.
- b. Providing clear instructions for model use.
- c. Providing examples to aid the user.
- d. Making the model interactive for use on time-share terminals.
- e. Including user prompter and assist instructions.
- f. Output formats were improved to facilitate user understanding.
- 4) The solution of the optimum set of screens

The dynamic programming algorithm was altered to a

determined by the model was, occassionally, unrealistic (e.g. 5 different screens might be required sequentially at the same level of assembly).

contrained optimization solution to provide an optimum set of screens consistent with current practice.

5) Running of the model can be costly (much core is required and CPU time can become significant for large systems).

Unnecessary precision was eliminated. Instructions were reduced.

6) SDO model does not have "adaptive screening" capability.

Adaptive feature was added to allow an adjustment of stress screen parameters on the basis of results observed.

Screening strength and initial fraction defective estimates can be derived from observed results using the chance-defective exponential (CDE) model.

1.2.3 Screening Strength Equations. Screening strength equations were developed for random vibration, swept-sine vibration, single frequency vibration, temperature cycling, and constant temperature. The first three equations (those for vibration) were developed from the results of the vibration screening experiments conducted by Kube and Hirschberger (Ref. 8). Experiments conducted by Edgerton (Ref. 5) and Baker (Ref. 6) did not produce sufficient vibration induced latent defect precipitation to enable model development. No other controlled experiments with the effectiveness of vibration were identified by the literature search. The development of the vibration screening strength equations is described in detail in Appendix A. Figures 1.2, 1.3, and 1.4 show screening strength versus time for the three vibration types.

The temperature cycling screening strength equation is derived from the curves on page 6 of NAVNAT P-9492 (Ref. 9). It was assumed that the curves represented results primarily from AGREE testing of avionics equipment and represent -54 deg. C to +55 deg. C temperature extremes and a 5 deg. C/minute rate of change. The constant temperature screening strength equation is derived from the temperature cycling equation. Figures 1.5 and 1.6 show screening strengths for the temperature related equations. The derivation is described in Appendix A.

1.2.4 Adaptive Screening. Since the stress screening equations are empirically derived, they are only rough quantitative




Figure 1.2. Screening Strength for a Random Vibration Screen




Figure 1.3. Screening Strength for a Swept-Sine Vibration Screen




Figure 1.4. Screening Strength for a Single (Fixed) Frequency Vibration Screen




Figure 1.5. Screening Strength for a Temperature Cycling Screen (R = 100)




Figure 1.6. Screening Strength for a Constant Temperature Screen

approximations of the screens' ability to precipitate latent defects. Screening strength is also thought to depend on other factors such as equipment type, construction, size, part composition and degree of design and production maturity. Therefore, the equations are useful in establishing a starting point and serve as a basis for planning a screening program. As actual screening results become available they can be compared with the expected results as determined by the screening strength equations. If the actual results fall outside the 99 percent bounds on the expected results, the actual data can be entered into the model which will automatically adjust the "equipment-related" constants of the stress screening equations, thereby adapting the equations to the specific hardware characteristics. The 99 percent bounds are based on a statistical test of the hypothesis that the planned values are correct (with a probability of 1 - .99 = .01 of rejecting the hypothesis when it is true).

1.3 Summary of Industry Surveys

1.3.1 Surveys Previously Conducted and Reviewed for this Study. Three surveys previously conducted on the subject of stress screening were reviewed and the results of each are summarized in the following paragraphs.

The results of the three surveys show marked similarity because there are common respondents to the surveys reporting on the same experiences. Buch of the experience data reported shows striking similarity in stress screens used, screening parameters (e.g., temperature extremes, temperature rates of change, vibration levels) and in opinions as to which screens are most effective. This is attributed to the fact that much of the reported screening experience is the result of contractually required MIL-STD-731B AGREE testing, primarily on avionics "black boxes".

- 1.3.2 Martin-Marietta Survey (Ref. 7). This survey of twenty-six sources primarily reporting on AGREE testing experience indicate the following beliefs.
- NOTE: This survey represents experience and opinions of about ten years ago and a large amount of stress screening experience, apart from AGREE testing, has been accumulated since then.
- a. 6-10 thermal cycles are required for the elimination of incipient defects. As more complex the screened item becomes (i.e., by part count), more cycles are required.
- b. Hore than 10 cycles are required if screening is done at the assembly level, and unscreened parts are used. 16-25 cycles have been used.

- c. A temperature range of -54 deg. C to 55 deg. C is most commonly used. (AGREE temperature range for avionics). Best screening is provided by using the maximum safe temperature range and rate of change.
- d. Temperature cycling of soundly designed hardware does not degrade the hardware.
- e. Application of power during temperature cycling with continuous performance monitoring is recommended. Turning off power during the cool-down cycle allows a more rapid temperature rate of change and allows parts to reach the low temperature extreme.
- f. Failure-free cycles are sometimes used. The report recommends one failure-free cycle.
- g. Implementing temperature cycling is most compatible with printed circuit board (PCB) construction and least compatible with large, complex potted cordwood modules.
- h. Augmenting "black box" temperature cycling with additional cycling at the PCB level should be considered.
- i. An approximation of the types of failures detected in mature hardware by temperature cycling is:

Design-related 5% Manufacturing-related 33% Part-related 62%

- j. Temperature cycling is an effective screen, with the screening strength dependent on the temperature range, temperature rate of change and number of cycles. Temperature soaks and low-level vibration are not effective screens.
- 1.3.3 <u>McDonnell Aircraft Company Survey (Ref. 11)</u>. This survey was conducted during 1979-1980 of thirty-three avionic equipment manufacturers to determine the industry practice and opinions current at that time in the conduct of environmental screening. A summary of the survey results follows.
- a. The primary environmental stress screen used is a thermal cycle, with a high temperature limit of 55 deg. C or 71 deg. C most common and a low temperature limit of -55 deg. C most common, reflecting the test limits of MIL-STD-781B.
- Temperature cycle durations of six to eight hours are most common and probably reflect convenience in adapting to the 24-hour day rather than for screening effectiveness purposes.

- c. Four to ten temperature cycles is most common, with the last cycle being failure free.
- d. The most common temperature rate of change is 3 to 5 deg. C/minute.
- e. Vibration during temperature cycling was limited to MIL-STD-781B requirements (i.e., 2.2g, sinusoidal, 10 minutes/hour). Some random vibration was used as a screen, separate from the temperature cycling, using levels of 3 to 6.2g RMS for durations of 5 to 10 minutes in 2 or 3 axes.
- f. There was no concensus on when random vibration should be done when applied with temperature cycling (i.e., before, after, or in-between temperature cycling).
- g. The distribution of the types of failures detected as a result of temperature cycling is:

Design-related	ક્ક
Manufacturing-related	30%
Part-related	463
Other	15%

The above percentages are mean values with large variances, reflecting varying degrees of production maturity. Soldering defects were the most common manufacturing related defect.

h. Factors influencing the design of a screen for a new production item were:

	Factor	Percent of Respondents
1)	Previous experience on similar equipment	91
2)	Customer desires	67
3)	Equipment characteristics	67
4)	Reliability requirements	64
5)	Use environment	58
6)	Existing environmental facilities	48
7)	Test operating cost	36

- i. About 40% of the respondents reported that the screen had been changed after the start of production and the majority (80%) of the changes were to increase the screen (more temperature cycles, added burn-in, added random vibration, increased vibration level) as a result of poor reliability resulting from the initial screen.
- 1.3.4 Institute of Environmental Sciences (IES) Survey (Ref. 12). This survey was conducted during 1930-1931 by an IES-sponsored National Committee to develop an environmental stress screening guidelines document. The survey resulted in receipt of 85 detailed responses from 14 sources and over 50% of the responses were for avionics applications. Salient findings of the survey are as follows:
- a. Thermal cycling and vibration were the most common stress screening environments used at the module, unit and system levels. Survey respondents also believe that thermal cycling and vibration are the most effective stress screens.
- b. Equipment reliability can be improved by 25 to 90% by means of environmental stress screening. The range of reliability improvement varied widely depending on equipment type, screening environment and the levels of assembly at which screening was performed.
- c. Thermal cycling was found to be a more effective screening environment for electronics than vibration, by a factor of 3 or 4 to 1. Random vibration is more effective than swept sine, and swept sine is more effective than fixed sine.
- d. Both thermal cycling and vibration are needed for optimum screening effectiveness. It is inconclusive that it is more effective to perform thermal cycling or vibration in any specific sequence but there appears to be a synergistic effect of using both the environments.
- e. Module-level temperature cycling is generally 20 to 40 thermal cycles, with a temperature rate of change of 5 deg. C/minute most common, and no power applied to the module. There is no significant payoff to extend the number of cycles beyond 40. Increasing the temperature rate of change produces more effective screening. Application of power to the module during the screen does not increase screening effectiveness.
- f. Units and system level screening profiles used reflect the strong influence of MIL-STD-781B in temperature range and rate of change. 8 to 12 thermal cycles, with power applied, were most common.

- g. Some cases were noted where degradation was introduced in equipment at high levels (i.e., 6gRMS) of random vibration. There is also an indication that lower levels of random vibration can be as effective as higher levels in some applications.
- 1.3.5 Survey Consensus. Thermal cycling and vibration are thought to be the effective environmental stress screens for precipitating latent defects. A large part of the reported stress screening experience data is a result of contractually required AGREE tests in accordance with MIL-STD-781B, test levels E and F, for avionics equipment. The AGREE requirements have obviously strongly influenced the survey respondents with regard to temperature cycling and vibration. This, at least partly, explains the commonality in stress screening practice. Most screening experience is at the unit, or "black box", level and a range of 4 to 12 thermal cycles is believed to be sufficient to screen out latent defects. There is some belief that the more complex the unit (i.e., in part count), more thermal cycles are needed, although this belief is not universally accepted. The most common temperature range over which thermal cycling is done is -54 deg. C to +55 deq. C, again reflecting the influence of MIL-STD-731B. There is a common belief that greater temperature ranges provide more effective screening, provided that the temperature limits are within the safe operating limits of the unit being screened. The most common temperature rate of change appears to be 5 deg. C/minute and there is general agreement that higher rates of change provide more effective screening. Temperature cycling at the unit level is most often accomplished with power applied and close monitoring of performance at both temperature extremes is recommended. Fower is turned off during the cool down cycle. Application of power during temperature cycling at the module level does not appear to increase the effectiveness of unpowered There does not appear to be a clear consensus on the screening. use of failure-free cycles. While the practice of requiring the last cycle to be failure-free is used by some and supported by others, there is another group who believe that a failure-free requirement should be included with other acceptance criteria and kept separate from the stress screening process.

Random vibration is considered to be the most effective vibration screening process, followed by swept frequency sinusoidal vibration (swept sine) and fixed frequency sinusoidal vibration (fixed sine).

Fixed sine vibration at low levels (e.g., 2.2g) is almost universally believed to ineffective as a workmanship screen. Random vibration at levels of 3-6gRMS, for 5-10 minutes (per axis), and applying to 2 or 3 axes is currently thought to be the most effective screen. However, the application of random vibration is relatively new and the survey results were mostly reports of AGREE testing, using 2.2g fixed sine vibration. Vibration at the module level is not currently thought to be effective.

Screens other than temperature cycling and vibration (e.g., temperature soak, power CN-OFF cycling) are not considered to be effective screens. Combining screens, such as performing temperature cycling and vibration on the same unit simultaneously or sequentially is considered to be effective. Opinions are mixed, however, on whether simultaneous screening is more effective or has the same effectiveness as sequential screening. There is also no agreement on the most effective sequence of combined screens, i.e., vibrate before or after temperature cycle.

Table 1.1 summarizes the key issues of the three surveys.

TABLI 1.1 SUMMARY OF THREE PREVIOUS SURVEYS.

Topic	Nartin-Marietta Survey (Ref. 7)	McDonnell Air- craft Company Survey (Ref. 11)	IES Survey (Ref. 12)
Thermal Cycle Screening	6-10 cycles. More cycles are required for more complex units & when done at lower assembly levels.	4 and 10 cycles most common. No. of cycles used varies widely (2 to 70 cycles).	R-12 cycles, independent of unit part count. 20-40 cycles for module level temp.
Temperature Range	o o o o -54 C to +55 C most common. (influence of AGREE testing.) Maximum safe range is most effective.	o o -54 C to +55 C or +71 C (influ- ence of AGREE testing)	Not stated, but stress screening cycles strongly influenced by AGREE testing profiles.
Temperature Rate of Change	o o l F to 40 F/min. with higher rates more effective.	o o 3 c to 5 c/min.	o 5 C/minute. Higher rates (15-20 C/min.) at module level more effective.
Power ON vs. OFF	ON, with close monitoring of performance. OFF during cool- down portion.	Not stated, but expected to follow AGREE profile. (ON, except during cool-down portion.	ON, for Unit and System-Level. Functional testing at both extremes. OFF, for module-level.

TABLE 1.1 SUNMARY OF THREE PREVIOUS SURVEYS.

Topic	Martin-Marietta Survey (Ref. 7)	<pre>!/cDonnell Air- craft Company Survey (Ref. 11)</pre>	IFS Survey (Ref. 12)
Failure-Free Cycles	0-2 cycles FF. 1 FF cycle recommended.	Varies greatly, O to 22 FF cycles 1 FF cycles is most common.	Should be made part of acceptance criteria, separate from stress screening.
Random Vibration	Not addressed	3-6.2gRMS, 5-10 minutes per axis, 2 or 3 axes.	Various Levels. Many are using NAVMAT P-9492, 69RMS. Recom- mends tailoring to item being screened. Not effective at module-level.
Degradation	Temperature cycling does not degrade soundly designed hard- ware.	Not addressed.	Cases noted where high levels of random vibration (6q RMS) cause

TANLE 1.1 SUPPLIES OF THEFT PREVIOUS SURVEYS.

Topic	Martin-Marietta Survey (Ref. 7)	McDonnell Air- craft Company Survey (Ref. 11)	IES Survey (Ref. 12)
Fistribution of Defects: Part-related Sanufacturing- related Design-relited Other	6.28 3.38.88 5.3.88	462 309 82 159	Not addressed
Effectiveness of screens other than temperature cycling and random vibration	Low Level (2q) Fixed Sine Vib- bration and temperature soak are not effective screens.	Low level (2a) Fixed Sine Vib- bration not effective. Opinion mixed on effectiveness of temperature soak	All screens other than temperature cycling and vibration are less effective substitutes.
Combined Cemperature Cycling and Randon Vibration	Not addressed, except that AGREE vibration is not an effective screen.	Majority think combining the screens is more effective than applying singly.	Combined testing is no more effective than applying screens. singly. Using both temp. cycling and vibration singly is necessary and a synergistic effect is gained.

TABLE 1.1 SUMMARY OF THREE PREVIOUS SURVEYS.

, , , , , , , , , , , , , , , , , , ,	No preferred sequence. Applying either screen before and after the other screen shows additional fall-out.	Equipment relia- bility can be improved by 25- 90% through stress screening.
IES Survey (Ref. 12)	No preferred sequence. Applying either screen before an after the other screen shows additional fall-out.	Equipment reliability can be improved by 25-90% through stress screening
McDonnell Air- craft Company Survey (Ref. 11)	Respondents indicated various combinations, vibration before, after and in- between temp. cycling, with no concensus opinion on which is most effective.	Not specifically addressed, but there is general agreement that temp. cycling eliminates incipient defects (and it can be inferred that reliability will thereby improve)
Martin-Marictta Survey (Ref. 7)	Not addressed.	Not specifically addressed, but there is general agreement that temp. cycling eliminates incipient defects (and it can be inferred that reliability will thereby improve)
Topic	Sequence of Temperature Cycling and Vibration, when used singly.	Reliability Improvement through Stress Screening

- 2. PLAINING A STRESS SCREENING PROGRAM.
- 2.1 Introduction. The ultimate success of a stress screening program is strongly dependent on the care taken in planning and understanding the limitations of stress screening. The planning of a stress screening program involves a number of considerations which are addressed below. Two important considerations should be kept foremost in mind in the process of planning a stress screening program;
 - The quantitative aspects of stress screening, i.e., the expected number of latent defects and the ability of a specific screen to precipitate those defects, cannot be analytically determined, and any models purporting to do so must be recognized as approximation methods based on past experience.
 - Past experience may provide some guidance in stress screen selection in cases of similar equipment composition and construction and degree of production maturity. However, there are usually other factors involved (e.g., reliability improvement fixes may have been incorporated simultaneously with the start of stress screening) which may obscure the true source of improvement.

Other factors to consider are:

- What are the objectives of a stress screening program?
 (e.g., achieve a quantitative reliability goal, maximize reliability, reduce production costs, reduce warranty costs, minimize life cycle costs?)
- What are viable alternative stress screens for achieving objectives (which screens applied at which levels produce the desired results?)
- What are the costs associated with each of the alternative approaches? (consider both nonrecurring and recurring costs)
- How does one know if the screening program is going according to plan (data gathering, analysis, decision criteria)?
- How can a stress screening program be changed to achieve more cost effective screening?
- What are things that can go wrong, what early indications are there and what should be done to correct them?

How to and why keep management attention on benefits being derived from stress screening?

2.2 Developing a Stress Screening Plan

- 2.2.1 Establishing an Objective. The most common objective in establishing a stress screening program is to improve field reliability by eliminating latent defects in the factory prior to delivery. This objective includes motivation through warranty considerations as well as motivation to improve poor field reliability. Other objectives to consider are:
 - a. Meeting a contractual reliability demonstration requirement.
 - b. Achieving and maintaining a high field reliability level.
 - c. Assuring cost effectiveness in a Reliability Improvement Warranty (RIW) contract.
 - d. Reducing production costs.
 - e. Reducing field costs of operations and maintenance (O&M)

The cost of failing a reliability demonstration is high enough to negate most compromises. The amount of screening planned should be consistent with the specified MTBF and test decision risks. The same approach should be considered on a reliability improvement warranty (RIW) contract. It should be noted that more screening is not always better and the improvement per unit of time decreases with time.

Achieving and maintaining a high field reliability requires careful evaluation of problems which could adversely affect reliability levels and an understanding of how such problems can be eliminated or controlled.

2.2.2 Determining if a Stress Screening Program is Appropriate. The current popularity of stress screening might lead one to believe that it is a panacea for solving problems of low field reliability, high production rework costs and slipping production schedules. Unfortunately, there are many other causes of such problems and no simple solution exists for correcting (or preventing) them. The value of stress screening, i.e., the knowledge of what potential technical or economic benefits are derivable from stress screening, should be understood before a decision is made to apply it. Generally, on high volume production programs of complex hardware the cost-effectiveness of stress screening should be considered. It is not so obvious that

stress screening is cost-effective, or otherwise beneficial, on a single system, advanced development model, where the production phase is remote and the non-recurring costs for stress screening facilities and test equipment are not insignificant.

The construction and complexity of the development item are important considerations. A breadboard or brassboard model which has little resemblance to a future production model should not be screened for manufacturing/workmanship defects. A development model which is expected to undergo extensive productization changes falls in the same category. Pre-production models embodying new designs are prime candidates for stress screening in a development phase because the types of defects to be expected in production can be identified and a production stress screening program can be effectively planned.

To determine if a stress screening program is appropriate, consider the following:

- Does the reduced field maintenance cost justify the screening program cost?
- Is stress screening necessary for eliminating excessive latent defects?
- Is stress screening necessary to achieve a technical (e.g., reliability) requirement?
- Will stress screening (in a development phase) provide valuable information for planning the production stress screening program?
- Will stress screening save money in production (through reduced rework costs)?
- Is the improved production schedule resulting from stress screening worth the cost of screening?
- Does the goodwill derived from delivering latent defect-free products balance the cost of stress screening?

2.2.2.1 Field Maintenance Cost Savings through Stress Screening. Field maintenance costs resulting from latent defects can be calculated by multiplying the number of latent defects present by the average cost per field repair. Figure 2.1 is a simplified production flow process of an unscreened unit. Assume the unit has N=10,000 parts, of which p=.001 fraction defective, resulting in the introduction of 10 latent defective parts. Further, assume 20 workmanship defects are introduced at the assembly level and 10 more at the unit level. The normal assembly and unit operational testing is assumed to have screening strengths of

0.20 at the assembly level and 0.40 at the unit level. Then, only 6 latent defects are precipitated at the assembly level (0.20 x 30 defects) and 14 at the unit level. Since a total of 40 defects were introduced in the process and 20 were precipitated, a balance of 20 remain to fail in subsequent field use.




Figure 2.1. Latent Defect Flow for Process Without Stress Screening

Figure 2.2 shows the same unit with stress screening at both the assembly and unit levels and screening strengths of 0.70 are assumed. The same number of latent defects are introduced (40) but because of the increased screening strength, 34 defects are precipitated, leaving only 6 defects to be found in field use. The reduction of 20-6=14 defects saves \$140,000 in maintenance costs (at \$10,000 per repair). If the cost of doing the screening is less than the discounted value of \$140,000, the screening has been cost-effective.




Figure 2.2. Latent Defect Flow for Process with Stress Screening




Figure 2.3. Field Maintenance Costs for Repairs Resulting From Latent Defects

Figure 2.3 shows that, for this example, at \$10,000 per field repair a total of \$200,000 will be spent in maintenance as a result of the 20 latent defects (p=.001). The figure shows costs rise rapidly as the initial fraction defective increases.

2.2.2.2 Using Stress Screening to Achieve a Reliability Requirement. It is generally believed that large part populations are comprised of two subpopulations, viz., "good" parts with a low failure rate, λg , and "bad" parts with a high failure rate, λb . It is further believed, and empirical and experimental evidence supports, that the good subpopulation dominates. The fraction of good parts in the population may be from 0.9 to 0.999, depending on the part type and quality grade. There is increasing evidence (ref. 19) that failures occurring during the life of equipment are latent defectives precipitated to hard failures through the application of the normal field usage stresses over a period of time. The continuously decreasing subpopulation of bad (latent defective) parts results in an equipment life characteristic of a decreasing failure rate.

If the expected instantaneous failure rate of an equipment is the summation of the failure rates of the good and bad (defective) parts,

$$\lambda_{\text{equipment}} = (N-D) \lambda_g + Dk\lambda_g$$
 (2-1)

where, N = total part population

D = number of defective parts

 λ_g = good part failure rate

 $k \lambda g = defective part failure rate$

and if estimates of λg and k can be made, then the number of latent defects that corresponds to a desired equipment failure rate can be determined by solving (2-1) for D,

$$D = \frac{\lambda_{\text{equipment}} - II\lambda_g}{\lambda_g(k-1)}$$
 (2-2)

Equation 2-2 addresses only latent defective parts and thereby excludes latent workmanship defects, which can be included by expanding equation 2-1,

$$\lambda_{\text{equipment}} = (N-D)\lambda_g + Dk_1\lambda_g + (M-C)\lambda_c + Ck_2\lambda_c$$
 (2-3)

1

where, M = total number of electrical connections

C = number of latent defective connections

 λc = good connection failure rate

 $k_2 \lambda_c$ = defective connection failure rate 2

Equation 2-3 can be used in planning and monitoring a stress screening program for determining the necessary reduction in the initial number of defective parts and the number of latent defective connections that yield a value of λ equipment that corresponds to the desired equipment failure rate. At the conclusion of stress screening, there are still some residual latent defects. As these latent defects are precipitated by field use, the reliability will improve because the latent defects are replaced (with high probability) with good parts. See Appendix E for a theoretical discussion of long term field reliability improvement through latent defect elimination. Figures 2.4, 2.5 and 2.6 show this reliability improvement for systems of 2,000, 10,000, and 20,000 parts and initial fraction defective rates of .001, .005, and .01. The figures represent systems of three different part counts, and undergo a natural screening of latent defects (no stress screening) in which the good part failure rate is 10^{-7} and the bad part failure rate is 2×10^{-4} . The curves in Figures 2.4, 2.5, and 2.6 were derived from a simulation program which simulates failures of good and bad parts and keeps track of cummulative MTBF as the number of failures due to bad parts decreases with time.

2.2.2.3 Manufacturing Cost Savings through Stress Screening. Consider the production model shown in Figure 2.7. The figure shows a moderately large production operation involving 100,000 parts. This may represent a single, large system of that many parts or multiple systems whose total part count is 100,000. Assume that, without stress screening, the natural screening strengths of the assembly, unit and system levels are 0.2, 0.4 and 0.6, respectively. If the incoming part defect rate is 0.5 percent and induced workmanship defect rates (as a fraction of the number of parts) are as shown in the figure, a total of 850 latent defects are introduced into the process and 672 of them are precipitated, detected and removed in the process, with the balance of 178 remaining to be discovered in field use.

If stress screening is employed at the assembly and unit levels, each with screening strengths of 0.70, the resulting defect fallout at each level is as shown in Figure 2.8.




Figure 2.4. Field MTBF Improvement Through Natural Latent Defect Fallout (2000 Part System)




Figure 2.5. Field MTBF Improvement Through Natural Latent Defect Fallout (10,000 Part System)




Figure 2.6. Field MTBF Improvement Through Natural Latend Defect Fallout (20,000 Part System)




Figure 2.7. Production Flow Model Without Stress Screening




Figure 2.8. Production Flow Model With Stress Screening

The figure shows that there is significant increase in the number of defects precipitated at the assembly level, a moderate decrease at the unit level and a significant decrease at the system level.

The cost analysis of the effect of the stress screening for this example is shown in Table 2.1.

The table shows that the total manufacturing cost of repair without stress screening is \$354.2K and the cost of repair with stress screening is \$175.6. This indicates that if the cost of screening is less than \$178.6K, a manufacturing cost savings results. (Also, the reduction in number of latent defects escaping to field use from 178 to 57 results in a potentially significant field maintenance cost savings).


Table 2.1 Manufacturing Stress Screening Cost Analysis Example.


	Assembly	y Level	Unit	Level	System	Level
	W/O SS	W/SS	W/O SS	W/SS	W/O SS	W/SS
Number of Defects Preci- pitated	140 ·	490	264	217	268	86
Cost per Repair	\$50	\$50	\$300	\$300	\$1,000	\$1,000
Repair Cost (\$K)	7.0	24.5	79.2	65.1	268.0	86.0

Since the cost per repair estimates are expected to vary with type and complexity of hardware, Figure 2.9 shows the total assembly repair costs (per 1000 assemblies) as a function of cost per assembly repair. Figure 2.10 shows the total unit repair costs (per 100 units) as a function of cost per unit repair. is the product of cost per repair and expected num-Total cost ber of repairs. The expected number of repairs is determined by the expected fraction of assemblies defective as a function of the initial part fraction defective, number of parts per assembly and number of assemblies per unit, explained in paragraph 2.2.3, below. Both figures show the repair costs incurred if all latent defects entering that level are precipitated, detected and eliminated at that level, which is unlikely since screening strengths are not expected to approach 100 percent. Some latent defects will escape to subsequent stages where repair costs are higher. Therefore, the repair costs shown represent the lowest cost to eliminate latent defects entering that level.

2.2.3 The Role of Part Level Screens

2.2.3.1 Part Failures in Field Use. The major portion of failures that occur in field use appears to be part failures as compared to workmanship failures, although during early life the split between part and workmanship failures is about equal. Figure 2.11 shows the changing distribution in failure types with time for a system development program. The early portion of the figure represents the later development stages and the later portion represents the final field testing stages.








Figure 2.11. Distribution of Failures by Classification and By Time for a Radar Development Project

Design-related failures are a small fraction of the total number of failures in mature production systems. During development, however, the distribution is quite different as indicated by Figure 2-12. The figure shows the distribution of defects for three recent, large scale (25,000 to 47,000 parts/system) development programs over 2-3 years of field operation.

Part failures during production results in rework costs as described earlier. If parts are procured without screening and subjected to sample receiving inspection, the fraction defective may range from .01 to .20, depending on part type and quality grade. Even if the fraction defective is as low as .01 and the parts are installed on assemblies averaging, say, 50 parts, then about 40 percent of all assemblies produced will be defective (only one defective part can make an assembly defective). Figure 2.13 shows the expected fraction of assemblies defective as a function of number of parts per assembly and part fraction defective.

2.2.3.2 Relationship of Part Fraction Defective to Quality The failure rate of different populations of microcircuits, operating under identical conditions, can vary over an order of magnitude, depending on quality grade (Class S versus C-1). Yet, the major differences between the Class S die and the class C-1 die are the visual inspection acceptance criteria, of process controls, and part-level screens and electrical tests to which the dice are subjected. Since screens and tests do not make devices more reliable (they improve lot quality by eliminating some latent defective parts), a "good" class C-1 die is as "good" as a class S die. Perhaps this can be extended to "good" class D-1 die as well. Therefore, it can be postulated that difference in failure rate of populations due solely to quality grade is a direct measure of the difference in fraction defective of those populations.

For example, consider a class S, hermetic flatpack MSI device of, say, 40 gates operating with $T_i = 25 \text{ deg.} C_2$ in a benign ground environment. A failure rate of 0.0032x10⁻⁶ failures per hour is calculated. Let 5,000 of such devices be used in an end item expected to operate 50,000 hours. The expected number of device failures during the end item life is less than 1. For this application, this device can be considered "good" and if the population exhibited its calculated failure rate by having 0, 1, or even 2 failures, the population might be considered to be free of latent defectives. If a class C-1 device were used on the end item instead of the class S device, an additional 20 failures could be expected to occur during the same end item life, due solely to the difference in quality grade. Perhaps the additional 20 failures represent latent defectives in the population. If the class S parts were operated with T; = 100 deg. C instead of 25 C deg. the increase in failure rate would result in an additional two failures during the 50,000 hours. This may indicate that the




Figure 2.12. Distribution of Failures by Type for Three Recent Development Programs




Figure 2.13. Fraction of Defective Assemblies as a Function of Initial Part Fraction Defective

class S lot contains latent defectives that were precipitated by the increased operating temperature. There can be no precise definition for a latent defective part because the inherent flaw which makes a part defective can range from a minor flaw (which may not be subjected to sufficient stress to cause degradation of the flaw to a hard failure) to a major flaw which requires only a slight stress. One view is that if a part fails during the life of the end item in which it resides it is, by definition, a latent defective part (excluding wearout failures). A device population containing a small fraction of defectives whose flaws range uniformly from minor to major would exhibit a decreasing failure rate until it reached a limiting population fraction defective,

$$p^* = \frac{p}{k(1-p) + p}$$
 (2-5)

k = ratio of defective part failure rate to good part failure rate

See Appendix E for a discussion of the limiting fraction defective. References 19 and 21 also discuss the decreasing failure rate characteristic relationship to defectives.

2.2.3.3 Incoming Receiving Inspection and Test. Microelectronic devices procured to the quality requirements of MIL-STD-883 receive 100% final electrical testing by the part manufacturer but, nevertheless, typically about 1 percent, and as much as 4 percent of the parts will not pass a similar electrical test performed at receiving inspection. There are several possible reasons for this, including:

- the seller's and buyer's tests are different
- seller testing errors
- buyer testing errors
- device damage or degradation in handling and transportation
- inspection and sorting errors

To determine what fraction of incoming microcircuit test rejects are actually defective, one manufacturer performed a retest of 525 rejects from a population of 75,981 devices tested. Results indicate that about 50% of the rejects are defective. Results are summarized in Table 2.2. Other studies indicate that without receiving inspection test, 60% of the defectives will be detected at the printed circuit board test, 10% will be detected at higher levels and 30% will not be detected (device applications not manifesting the defect).

TABLE 2.2 Results of Retesting Incoming Receiving Test Microcircuit Rejects

. 1	# of 1	Total	Total Rejects			Verified	(See Note)
Supplier	Lots	Qty.	Total	7.	Pass	Fail	% Fail
A	25	8525	100	1.17	62	32	0.38
В	8	8435	22	.26	15	7	0.08
С	17	21826	166	.76	120	46	0.21
D	30	27295	144	.53	35	102	0.37
E	22	9471	96	1.01	31	63	0.67
F	2	429	6	1.40	4	2	0.47
TOTALS	104	75,981	534	0.70	267	258	0.34

NOTE: 525 of the 534 rejects were retested. Percent failed shown in last column is the percent of the total quantity tested.

Table 2.3 shows recent experience with receiving inspection testing. The results in Table 2.3 for microcircuits show a slight increase in percent rejects over the figures in Table 2.2 due primarily to increased testing at elevated temperature (0.97% vs. 0.70%).

Table 2.3 Recent Receiving Inspection Test Results.

Part Type	Quantity	Average Quality	Rejects	Percent Rejected
Microcircuits	1,419,581	B-1	13,779	0.97
Discrete Semiconductors	343,000	TX	2,008	0.59
Passives	1,296,200	ER-M	8,539	0.66

The implication of the data in tables 2.2 and 2.3 is that populations of parts, even high quality parts contain defectives and if incoming receiving test is not performed then the estimate of the initial fraction defective (PDEF) must be appropriately adjusted when using the Stress Screening Model.

2.2.4 Manufacturing Process Defects

2.2.4.1 Sources of Defects. Both patent and latent defects are introduced during the fabrication, assembly and test processes of equipment in manufacture. The patent defects pass through the various assembly stages until detected by a test of sufficient thoroughness and all but the most subtle are detected and eliminated prior to shipment. Patent defects include the following:

Parts

- Broken or damaged in handling
- Wrong part installed
- Correct part installed incorrectly
- Part failed due to EOS/ESD
- Missing part

Interconnections

- Incorrect wire termination
- Open wire due to handling damage
- Wire short to ground due to misrouting or insulation damage
- Missing wire
- Open etch on PWB
- Open plated-through hole
- Shorted etch (solder bridge, loose wire strand)

Latent defects cannot be detected until they are transformed to patent defects through stress and time and stress screening is intended to effect this transformation. Latent defects include the following:

Parts

- Latent material or process defects
- Partial damage through EOS/ESD
- Partial physical damage in handling

- Partial damage during soldering (excessive heat)
- Interconnections
 - Cold solder
 - Inadequate/excessive solder
 - Broken wire strands
 - Insulation damage
 - Loose screw termination (lugs)
 - Improper crimp
 - Unseated connector contact
 - Cracked etch
 - Contact contamination
 - Loose conductive debris
- 2.2.4.2 Distribution of Defects. The quantity and distribution of manufacturing process defects are dependent on three basic factors;
 - Density. Equipment with high part and/or wiring density is more susceptible to induced process defects due to smaller error margins and increased rework difficulty.
 - Naturity. New production requires time to identify and correct planning and process problems, train personnel, etc. Maturity rate is dependent on volume and time. Low volume over a long time period has a low maturity rate.
 - Process Control. Even with good process controls, low maturity and high density may result in sufficient process induced latent defects to justify stress screening. Maturity, with good process control, may eliminate the need for stress screening.

Because each manufacturer's production process is unique in terms of product types, technology, skills, and management and worker attitudes towards process control, there can be no single set of guidelines for process defect elimination with general applicability. Each manufacturer must examine his own conditions to determine the magnitude and nature of process induced defects and decide the appropriate, perhaps cost-effective, course for their elimination.

Table 2.4 shows a typical distribution of interconnection defects for printed wiring assemblies in early production, showing a 70/30 relationship of solder/etch defects and an overall defect rate of 0.2% defects per part. The table shows the defects that were detected without stress screening at the first opportunity (first assembly test).

Table 2.4 Interconnection Defects Detected at First Test for Early Production PWAs.

DMA Tomo	00	Average Parts	Average IC's	Def Solder		Detect		Defects Per Assy	Defects
PWA Type	Qty.	Per Assy.				Other	-		
Digital	8,160	85.73	41.33	1,343	638	7	1,988	0.244	0.0028
Analog	3,839	172.2	15.00	450	152	2	604	0.157	0.0009
TOTALS	11,999	113.4	32.91	1,793	790	9	2,592	0.216	0.0019

If it is assumed that the number of PWA interconnection defects per part increases linearly with an increasing percentage of integrated circuits, a reasonable assumption because IC's have more solder connections per part and solder defects dominate, then the data in Table 2.4 for digital and analog assemblies can be used to derive the linear relationship,

$$y = mx + b$$

$$m = \frac{\Delta \text{ in defects/part}}{\Delta \text{ in fraction IC's}}$$

$$= \frac{.0028 - .0009}{.4821 - .0871} = .0048$$

$$y - .0028 = .0048(x - .4821)$$

$$y = .0048 x + .00049$$

where y is the interconnection defects per part and x is the IC fraction. The bounding values are .00049 when the PWA contains no ICs and .0053 when all parts are ICs.

Table 2.5 shows the distribution of part defects over a one-year period for multiple projects in various stages of maturity.

Table 2.5. Part Defects Detected at First Test for Production PWAs.

		Parts	ICs		cts Dete		Defects	Detects
PWA Type	Qty.	Per Ass'y.	Per Assy.	Broken	Defectiv	e Other	Per Assy.	Per Part
Digital	41,879	108	35	876	14,426	15,532	0.736	0.00682
Analog	39,831	208	10	1,391	17,288	21,152	1.321	0.0048
Totals	81,710	157	23	2,267	31,714	36,684	0.865	0.0055

Using the same methodology as above, the defects per part as a function of the fraction of ICs is,

y = .00743x + .00444

where y is the part defects per part and x is the IC fraction. A review was made of unit wiring defects covering a one-year period. Results are shown in Table 2.6.

Table 2.6. Results of First Opportunity Wire Testing of Unit Wiring.

	Qty. Wires	Qty. Wiring	Fraction	Defec	t Type
Time Period	Tested	Defects	Defects	Cont.	Leak
Jun-Dec 1980	1,175,663	12,183	.0104	8,517	3,666
Jan-July 1981	1,104,211	11,830	.0107	7,584	4,246
Total	2,279,874	24,013	.0105	16,101	7,912

Tables 2.2 through 2.6 represent a relatively small sample of the nature and magnitude of defects to be expected in the manufacturing process and are provided only to allow the SSM user to establish starting points for part and workmarship defect values (PDEF and ADEF) where better information is not available.

2.2.5 Screen Selection and Placement

2.2.5.1 General Industry Consensus on Screen Selection and Placement. Because the origin of environmental stress screening was in AGREE testing, specifically temperature cycling and vibration of avionics "black boxes", the current general industry consensus is that temperature cycling is the most effective

stress screen, followed by random vibration (Ref. 12). The vibration used in AGREE testing done in the past was single frequency and relatively low level (2.2g). In search of more effective screens, the Grumman experiments (Ref. 8) indicated that random vibration was more effective than either swept-sine or single frequency sine vibration. The results of thermal cycling in eliminating parts and workmanship defects (primarily during AGREE testing) were collected and summarized by Martin-Marietta (Ref. 7). The results of the two studies (Ref. 7, 8) were combined into NAVMAT P-9492 (Ref. 9) to serve as a starting-point quideline document.

At the module/assembly level, thermal cycling is believed to be an effective screen for both part and workmanship defects. The rate of change of temperature is thought to be an important parameter, with higher rate of change being more effective. Between 20 and 40 temperature cycles are generally recommended. There are two opposing schools of thought on whether power should be applied or not during the thermal cycling. There also is no general agreement on the effectiveness of vibration at the module/assembly level. Experiments conducted at Hughes (Ref. 5, 6) indicated that vibration was not effective for printed wiring assemblies (PWAs). Ref. 20 states that PWAs can be effectively screened with broadband random vibration for certain defects.

At higher levels of assembly, i.e., units, groups, thermal cycling and random vibration are effective screens. Less thermal cycles are thought to be necessary at these levels, varying from 4 to 12 cycles. Power on is generally accepted as more effective and an increasing number of practitioners are recommending a performance verification test (PVT) at each temperature extreme. One report states that 80% of all defects detected during stress screening were found during PVT at the low temperature extreme. Several practitioners using random vibration at these levels cite power on and continuous monitoring as essential to detect intermittents. Low level single frequency vibration is widely accepted as being an ineffective screen.

There is some disagreement on the effectiveness of some screens at certain levels of assembly, the source of which may lie in differences in hardware type, construction, part content and degree of design and production maturity. Also, the definitions for the various levels of assembly (subassembly, assembly, module, unit, group, etc.) are not clear descriptions of the items they represent.

- 2.2.5.2 Technical and Economic Factors to Consider in Selection and Placement of Screens
- 2.2.5.2.1 Factors to Consider in Assembly Level Screen Selection. Assembly level screens are intended to accomplish two things,

- 1) precipitate latent defects which have escaped the part manufacturer's screens and receiving inspection tests, and
 - 2) precipitate workmanship defects introduced in the process of assembly manufacture.

The types of latent part defects expected to be present depends on several factors, including,

- types of parts comprising the assembly (i.e., microcircuits, discrete semiconductors, passive parts, low population parts, microwave parts, etc.)
- quality grade of the parts

7...

- 3) extent to which the parts were previously screened (e.g., receiving inspection tests and screens)
- 4) testability of the parts (e.g., microprocessor and other LSI devices are difficult to test completely and therefore precipitated defects may go undetected).

Table 2.7 is a summary of the expected types of defects for common part types. The table may be used to assist in the determination of the most effective screen to be selected based on the types of components that comprise the assembly to be screened. If, for example, the assembly consisted mostly of passive components, the table indicates that temperature cycling is the most effective screen, followed closely by burn-in. In this case, the choice of temperature cycling or burn-in should probably be made on a cost basis. Ref. 7 provides detailed breakdowns of typical failure modes and mechanisms for each major part type.

The types of latent workmanship defects expected to be present also depends on several factors, including,

- 1) assembly type (i.e., PWA or hard wired assembly)
- 2) assembly complexity (e.g., number of printed wiring layers, PTH density, metallization spacing, number of parts, wiring density, technology type)
- type of parts used (flat pack vs DIP, hybrids vs discretes)
- 4) wire termination type (hand solder, wave solder, wire wrap, crimp)
- 5) design and production maturity.

Table 2.7. Distribution of Screening Methods for Various Classes of Parts. (Ref. 7)

Percent	Failure	Modes :	Screened
---------	---------	---------	----------

General Screening Method	Passive Components	Discrete Semiconductors	Monolithic ICs	Hybrid ICs	All Parts
Mechanical Shock	0	2.6	0	1.4	10.0
Particle Impact (PIND)	0	7.9	0	5.1	3.3
Random Vibration	10.4	7.9	15.6	10.9	11.0
Burn-In	63.6	36.8	35.6	43.5	51.9
Temperature Cycling	70.1	31.6	24.4	38.4	48.6
Temperature Soak	7.8	31.6	28.9	30.4	22.9
Temperature Shock	13.0	13.2	0	3.6	2.4
Power Cycling (ON/OFF)	13.0	13.2	0	3.6	7.1
High Pot.	2.6	0	0	0	1.0
Short Term Overload	39.0	0	0	0	14.3

The recommended method for estimating the expected quantity and type of latent assembly workmanship defects is to use experience data on assemblies of similar characteristics produced under similar conditions. Table 2.8 provides a brief listing of typical latent defect categories applicable to the assembly level and the types of screens thought to be effective in precipitating the defects. Table 2.8 may be used to assist in the selection of a screen type based on knowledge of prior workmanship defect types present in similar assemblies. The table indicates that vibration screens are effective for loose contacts, debris, loose hardware and mechanical flaws while thermal screens are not ef-Also, thermal screens are effective for defects relatfective. ing to improperly installed parts, wire insulation, improper crimp and contamination while vibration screens are not effective. For other types of workmanship defects identified in the table, both thermal and vibration screens are effective.

Table 2.8. Assembly Level Defect Types Precipitated by Thermal and Vibration Screens

Defect Type Detected	Thermal Screens	Vibration Screens
Defective part	x	x
Broken part	x	x
Improperly inst. part	x	
Solder connection	x	x
PCB etch	x	x
Loose contact		X
Wire Insulation	X	
Loose wire termination	x	x
Improper crimp	x	
Contamination	x	
Debris		x
Loose hardware		X
Mechanical flaw		X

- If a thermal screen (temperature cycling or constant temperature burn-in) is selected for the assembly level, the following screen parameters must be determined:
 - 1) Maximum temperature The maximum temperature to which the assembly will be exposed should not exceed the lowest of the maximum ratings of all the parts and materials comprising the assembly. Non-operating ratings for parts are higher than the operating ratings.
 - 2) Minimum temperature The minimum temperature to which the assembly will be exposed should not exceed the highest of the minimum ratings of all the parts and materials comprising the assembly.
 - NOTE: 1) and 2), above, must be carefully selected to assure that maximum screening effectiveness is achieved. Exceeding the maximum ratings may result in damage to non-defective parts or materials which is contrary to the principle of stress screening. If the operating temperature for a power-on screen cannot be readily determined analytically, a thermal survey of the item to be screened should be performed to determine the maximum and minimum screening temperatures.
 - 3) Temperature rate of change Screening effectiveness increases with increasing temperature rate of change. The maximum rate of change is dependent on the thermal chamber characteristics and the thermal mass of the items to be screened.
 - 4) Dwell at temperature extremes During a temperature cycle it is sometimes necessary to maintain the chamber temperature constant once it has reached the maximum (or minimum) temperature, sometimes referred to as dwell. Dwell may be required to allow the item being screened to achieve the chamber temperature. The item thermal lag depends on thermal mass and most PWAs have a low thermal mass. Figure 2.14 shows the part case temperatures tracking the chamber temperature very closely, therefore eliminating the need for dwell. PWAs with more mass may require some dwell or dwell may be required if a PVT or a vibration screen is to be imposed at a temperature extreme.
 - 5) Number of Cycles Ref. 12 recommends 20 to 40 thermal cycles for the assembly level. If the SSM is used, the number of cycles is determined by the required screening strength. (See Section 4).




Figure 2.14. Card Thermal Survey. Part temperatures track the chamber temperature very closely. (Ref 5)

The determination of whether or not to apply power to assemblies being screened and whether or not to perform a functional test during the screen requires consideration of the following factors:

- Predominant type of defect present If the predominant type of defect is expected to be a weak interconnection which is transformed to an open circuit by the screen, (cold solder joint, weak wire bond) then a post-screen test will detect the open circuit and power-on is not required.
 - If, on the other hand, the predominant type of defect is expected to be of an intermittent nature, then power-on with continuous performance monitoring is necessary.
- Economics A fixture and associated test equipment to house assemblies, apply power, provide stimuli, and monitor assembly performance can be costly. The tradeoff of fixture and test equipment cost and potential benefits may prove difficult.
 - If a vibration screen is selected for the assembly level, the type of vibration (i.e., random, sweptsine or fixed-sine) must be selected and the following two parameters must be determined.
 - 1) Vibration level Ref. 9, 12 and 20 recommend random vibration and suggest a level of 2 .04-.045 g /Hz provided that the assembly can withstand that level without damage. If the assembly dynamic response characteristics to the vibration excitation are not known, a careful vibration survey should be conducted to properly establish the acceleration spectrum and level. Ref. 20 provides a procedure for conducting a vibration survey. Ref 12 suggests use of swept-sine as a second choice if random vibration cannot be performed. Single frequency vibration at the assembly level is considered as ineffective.
 - 2) Vibration duration Pef. 9 and 12 suggest 10 minutes per each of three axes. The need for multiaxis excitation may vary from one assembly to another and therefore it is desireable to determine fallout per axis during initial screens to allow screen adjustments.

Some other factors to consider in determining the desireability of a PWA vibration screen are the PWA size and stiffness. Larger PWAs will flex more and precipitate such latent defects as cracked etch, cold solder and embedded conductive debris. Smaller PWA, particularly if conformally coated, are stiff and not amenable to vibration screening.

2.2.5.2.2 Factors to Consider in Unit Level Screen Selection. It is the intent of assembly level screens to precipitate latent part escapes and assembly workmanship defects. Unit level screens are then intended to precipitate unit workmanship defects and assembly level escapes. Unit level defect types vary with unit construction but typically include interconnection defects such as,

- 1) PWA Connector (loose, bent, cracked or contaminated contacts, cracked connector)
- 2) Backplane Wiring (loose connections; bent pins, damaged wire insulation, debris in wiring)
- 3) Unit Input/Output Connectors (loose or cracked pins, damaged connector, excessive, inadequate or no solder on wire terminations, inadequate wire stress relief)
- 4) Intra-Unit Cabling (Improperly assembled coax connectors; damaged insulation).

Units may also contain wired assemblies integral to the unit and not previously screened such as Power Control and BIT Panels, and purchased assemblies such as modular low voltage power supplies. The latent defects associated with those assemblies should be considered in the selection of screens.

Thermal screens are more effective than vibration screens in precipitating latent defective parts. Thermal cycling and vibration screens are both effective in precipitating latent workmanship defects although one screen may be more effective than the other for certain defect types. The unit composition and knowledge of prior screening will dictate the expected types of defects and aid in screen selection.

If a thermal screen is selected, the same process as described for the assembly must be followed. Differences are outlined below.

1) Units have greater thermal mass and therefore the higher temperature rates of change may be more difficult to achieve. A dwell at temperature extremes is probably required.

- 2) Power-on screening is usually easily accomplished and widely recommended. A functional test (PVT) at temperature extremes has been shown in several cases to be effective in detecting defects not detectable at room ambient temperature. As stated previously, one project reported finding 80 percent of the total defects during PVT at low temperature.
- 3) Less temperature cycles appear to be required at the unit level. A range of 4 to 12 cycles is common.

If a vibration screen is selected, it is very important that competent engineering personnel evaluate the unit to be vibrated to determine the appropriate vibration type, level of excitation and whether or not a vibration survey should be performed. There is some evidence that for large, massive units, low levels of vibration are effective screens.

2.2.5.3 Pre- and Post-Screen Testing Considerations. If an item is subjected to an unpowered screen, testing subsequent to the screen may reveal part or workmanship defects requiring correction. If the item was not tested prior to entering the screen it cannot be determined, even if a detailed failure analysis were performed, if the defects found were precipitated by the screen or were present in the item before the screen. If all the necessary information relating to the effectiveness of the screen were known, i.e., the average number of latent defects entering the screen and the average screening strength in precipitating those defects, it would not be necessary to know the condition of the item prior to screening. However, stress screening has not yet advanced to the point where quantity and type of latent defects can be accurately predicted and screening strengths calculated therefore some degree of experimentation is necessary to precisely derive reasonable defect rate and screening strength estimates. Testing before entering a screen establishes a baseline upon which post-screen testing results can be used to measure the screening strength. The pre-screen testing should be done immediately before the screen to eliminate the uncertainty of latent defect introduction during such processes as cleaning, conformal coating, handling and storage which may follow the initial item testing.

Once the screening effectiveness has been established the value of both pre-screen and post-screen testing has diminished and it may prove cost effective to perform only post-screen testing. When major perturbations take place, such as production line changes, fabrication/assembly process changes, personnel changes or alterations to the stress screening process, it may be advisable to reinstitute pre-screen testing until the process has stabilized.

For long term production programs, the normal learning curves result in process improvements and the quantity and distribution of latent defects is expected to change accordingly. There will be a predominance of workmanship and manufacturing process related defects in early production and component related defects dominate mature production. Stress screens have a different degree of effectiveness for different defect types and therefore screens that may have been effective during early productions should be periodically re-evaluated to assure their continued effectiveness.

2.2.6 Planning a Stress Screening Program for the Development Phase

- 2.2.6.1 Characteristics of a Development Phase. A development phase may consist of a very advanced development in which a technical concept is being validated and the hardware used in the validation bears little resemblance to the production hardware. At the other extreme, a development phase may be late engineering development and the hardware is intended to be production. Most often, a development phase will be somewhere in prototype. between the above extremes. When a high volume production program follows development, there may be a productization or production engineering phase (PEP) in which major hardware design changes are made to enhance producibility. Also, suppliers/vendors used in development may change for production. In short, if stress screening program is considered for a development phase primarily for the purpose of gaining information for planning the production phase stress screening program, consider the amount of hardware changes expected and the relevancy of development phase screening results.
- 2.2.6.2 Pro's and Con's of Stress Screening in a Development As mentioned in the previous paragraph, one good reason for stress screening development hardware is to gain information about the nature and magnitude of latent defects in complex This knowledge is valuable in planning how to hardware items. cope with the problem in production. If a reliability demonstration test is required during development when a large number of latent defects are present in the hardware, a stress screening program may be the best way to reduce the number of defects and give a high probability of passing the test. On the other hand, the benefits to be derived from stress screening in development may not be worth the cost of implementation. During development there are many design related problems. About one-half of all failures are design or engineering-related. Also, there are many manufacturing related problems but may have no relationship to production problems because the development hardware may have been fabricated in an engineering model shop, from engineering sketches, with soft tooling, etc. Manufacturing-related problems are about 30% of the total. Only one of five confirmed failures in development is component related and many of these failures

are a result of low quality part substitution for long-lead hi-rel parts. The hectic integration and checkout activity and the lack of disciplined electrostatic discharge/ electrical overstress (ESD/EOS) controls results in a predominance of electrical overstress failures. The combination of the above (numerous design and fabrication problems and electrical overstress failures) may tend to overshadow the latent defects during development and make stress screening of questionable value.

2.2.6.3 Relationship of Stress Screening and Reliability Growth. Reliability growth is achieved through the process of eliminating correctable defects. All design problems and some workmanship and component problems are correctable. When the proper corrective action is taken on correctable problems, the resultant hardware failures will not recur and the hardware manifests an improved MTBF, called reliability growth. Reliability growth in development can be enhanced through stress screening by precipitation of latent defects (early in the growth process). The latent defects eliminated through stress screening will not occur as random failures during later stages of the growth process.

2.2.7 Planning a Stress Screening Program for the Production Phase

- 2.2.7.1 Using Development Phase Results to Guide Production Phase Planning. As was pointed out in the preceding paragraph, determination of the effectiveness of stress screening in a development phase is difficult because latent defect failures are masked by a predominance of other failure types. Therefore, it is probably unrealistic to expect that accurate screening parameters can be derived for production phase screening from development phase screening results. However, valuable information can be gathered for the development phase which can be used to guide the planning for production. The most valuable information is:
 - Identification of hardware items (parts, assemblies, units, equipments, ...) which exhibited known or potential latent defects.
 - 2) Identification of suppliers/vendors whose products show potential latent defect problems.
 - 3) Assessment of the effectiveness of corrective actions taken to eliminate latent defects.
 - 4) Known defective items, eliminated from production, the substitutes for which may require qualification testing and stress screening to assure the absence of latent defects.

5) The cost and schedule estimating factors for stress; screening during development, and their applicability to production.

2.2.7.2 <u>Initial Production Phase Start-up Problems</u>. Typical start-up problems to be expected include the following:

- 1) Production personnel unfamiliarity with stress screening requirements.
- 2) Facilities and test equipment unavailable for stress screening.
- 3) Production planning errors result in incorrect screening and stress screening omissions.
- 4) Required stress screening data is not recorded or recorded incorrectly.
- 5) Schedule priorities preempt stress screening priorities.
- 6) Loss of failed parts preclude a sufficiently thorough analysis.
- 7) Excessive lag time from screened item failure to repair, making timely analysis of screening results difficult.
- 8) Factory test equipment breakdowns.

It is optimistic to state that all of the above problems can be avoided through careful planning but it is nevertheless correct to state that careful planning is the only hope to minimize them. The planning requires that all organizational activities in manufacturing involved in the stress screening be made aware of their roles and responsibilities at a time early enough that they are able to plan their functions and acquire the necessary resources to execute their responsibilities.

- 2.2.7.3 Planning for Subcontractor/Supplier Stress Screening. If it is determined that certain subcontractor/supplier items will require stress screening, the first decision to be made is whether the items are to be screened at the subcontractor's/ supplier's facility or screened by the prime contractor, either at receiving inspection/test or at a higher level of assembly. There are several benefits to screening at the subcontractor's/ supplier's facility,
 - 1) Subcontractor/supplier concern for yield at screening, translated to profits, may force process improvements to minimize latent defects.

- 2) Screening at receiving inspection/test requires return of defectives to the subcontractor/supplier, and may result in shortages and concomitant schedule slips.
- 3) Special stress screening facilities and test equipment do not have to be acquired/supported/ operated by the prime contractor.

Few benefits of stress screening of a subcontractor/supplier item by the prime contractor can be identified.

To assure that the subcontractor/supplier is able to perform the required stress screening, it is important that the requirements are made known at an early enough time to allow him to acquire the necessary capability, or alternatively, arrange for an external laboratory to plan to perform to the requirements. This early planning is required to assure that the subcontractor/supplier is contractually required to perform the specified stress screening and record and report the results.

2.3 Contractual Considerations in Stress Screening

2.3.1 General Considerations. There are two views on stress screening that relate to contractual considerations. One view is that a stress screen or stress screening program is similar to a formal qualification or acceptance test, requiring contractual terms, formal test plans, procedures and reports. Contractually required failure free periods are appended to screens in this view and strong considerations are being given to coupling incentives to screening results. The second view is that stress screening is just another step in the production process to be applied selectively and temporarily as an effective method of eliminating latent defects and achieving cost savings and/or schedule improvement in the process.

It is not surprising that the first view is widely held by consumers while the second view is more common among producers. Consumers are primarily concerned with elimination of latent defects prior to acceptance to avoid the high cost of field repairs and to improve operational readiness. The producers primary concern is to optimize the production process by eliminating latent defects at the lowest possible assembly level, thereby effecting cost savings and avoiding schedule delays. If the producers process does not satisfy the consumers objectives, contractual terms must be executed to enhance the process.

2.3.2 Contractual Flexibility to Permit Stress Screening Program Adaptability. In early production, a number of unknowns preclude adoption of optimum stress screening. Some of the more significant unknowns are:

- 1) residual design deficiencies
- 2) manufacturing planning errors
- 3) worker training
- 4) new suppliers
- 5) latent defects in new part lots
- 6) new process capability
- 7) stress screening effectiveness
- 8) testability (for defect detection)

The stress screening program, even if carefully planned, may produce unexpected results which should be addressed though modification of the screens. The principle of adaptive screening is to adjust the screens on the basis of observed screening results so that the screens are always most cost-effective. Contract terms should be flexible enough to permit a modification of screens or screen parameters when such modification is shown to be beneficial to the consumer.

In long term production the quantity and distribution of latent defects changes with time and therefore contract terms should contain provisions for periodically reassessing the individual screens and the overall screening program. The overriding criterion for change should be the most cost-effective achievement of consumer objectives while remaining consistent with the optimum production process.

- Failure Free Cycles. While currently used in some stress screening programs and apparently gaining in popularity, all that can be meaningfully said about failure free cycles is that some small measure of confidence is gained that the product is not totally devoid of merit. End-items being screened, say inherent MTBFs of 500-5000 hours. units, typically have Failure-free periods may range from 1-10 percent of the inherent MTBFs. Figure 2.15 shows the probability of passing a failure free period in 1, 2, or 3 tries as a function of the True MTBF-to-Inherent MTBF ratio. The figure clearly shows that items with low ratios (indicating many remaining latent defects) have a good chance of passing a failure free period. For example, an item which has only 1/10 of its specified MTBF has a 75 percent chance of passing a failure free period in 3 or less attempts.
- 2.3.4 Incentives Associated with Stress Screening. Many commercial products exhibit extremely good "field" reliability without having been contractually required to perform stress screening. For commercial producers, the producers objective

stated in 2.3.1 is modified to include in the process optimization the least repair cost during the warranty period. Significant losses that might accrue through excess field repairs resulting from latent defect escapes must be avoided. Some commercial manufacturers employ forms of stress screening to precipitate latent defects while others concentrate more on process control and worker training and motivation.




Figure 2.15. Probability of Passing a Failure Free Period of Duration 0.1 x Specified MTBF

The producers concern for potential losses (which may be stronger than his concern for potential gains) resulting from excessive maintenance in early fielding may be the necessary motivation for delivery of defect-free products, be it through stress screening or other means. The further pursuit of warranties, RIW contracts, guaranteed reliability, full contractor maintenance, etc., seems strongly justified.

3. DATA COLLECTION, ANALYSIS AND REPORTING

- 3.1 Data Collection. A stress screening program conducted during a development or early production phase will be concurrent with many other activities such as reliability improvements through design changes, quality improvements through manufacturing process changes, and supplier corrective action programs. The simultaneous activities will, collectively, result in a product improvement the credit for which may be difficult to assign. To gain assurance that the stress screening measures taken to improve reliability (or just to precipitate latent defects) are cost effective, it is important that the proper data be gathered and analyzed. This is particularly true if an adaptive stress screening program, where screening results are compared with pre-determined criteria, is employed. Data other than screening results is important for use in conjunction with the analysis of screening data, and includes,
 - Qualification test results
 - Supplier acceptance test results
 - Part receiving inspection/test results
 - Failure history
 - Item inspection and test records.
- 3.1.1 Data Collection Requirements for Stress Screening Program. The determination of the specific data elements to be collected during a stress screening program can be made on the basis of the program objectives. Simple stress screening programs require little data other than the number of defects precipitated by the When adaptive stress screening is conducted, conscreen(s). siderably more data is required. The principle of adaptive stress screening is the change of the stress screens applied, on the basis of observed results, to achieve the most cost-effective of latent defects. Therefore, adaptive stress elimination screening requires data related to the effectiveness of the applied screens and the actual costs incurred.

The effectiveness of a stress screen can be measured by its screening strength, i.e., the probability that, given that a latent defect is present, the stress screen will transform the latent defect into a patent, or hard, defect and that defect will be detected by the screen. However, only the total number of defects found as a result of the screen is observable, which is insufficient to determine screening strength. The expected number of latent defects, F, precipitated by a screen is,

F = D x Screening Strength

or the product of the screening strength and the number of latent defects entering the screen. The true values of D and screening strength are unknown. Further, the observed number of defects may not be totally comprised of precipitated latent defects but may include patent defects which have escaped prior screens. Another complicating, yet important, factor is that screening strength is a combination of the ability of the screen to raise a latent defect to a detectable level and the ability of the screen The probability that a patent defect will be to detect it. detected by the test to which the item being screened is subjected is called probability of detection, Pd, or detection ef-The value for Pd varies with the equipment complexity and the thoroughness of the test. Modern equipment comprised of microprocessors, large memory devices and other LSI devices may contain patent defects so subtle that only the most thorough of tests will detect them. The screening strength equations in the SSM are derived from screening experience with less complex equipment and therefore the screening strengths can be expected to be somewhat reduced for modern, complex equipments. Because there are many unknowns (e.g., initial part fraction defective, number of manufacturing defects introduced at each stage of assembly, the effectiveness of screens to precipitate the various types of latent defects, and the ability of equipment tests to detect precipitated flaws) in the art of stress screening, it is important to collect as much meaningful data as possible during the screening process so that analyses of the data may be helpful in developing better estimates for the unknowns. Some of the essential data elements are,

- 1) Defect data: Number of defects observed, time-to-failure or cycle-of-failure, failure classification (part, design, workmanship) and failure cause (to assist in discriminating between latent and patent defects and in determining corrective actions).
- Screen Parameter Data: Recording of chamber temperature and the temperature of the item being screened during temperature cycling and constant temperature screens are important, at least initially, to ascertain that the chosen screen is actually being applied. For vibration screens, the vibration input and test item response are needed.
- 3) Cost data: Data related to the cost of conducting the screens and the cost of repairs due to precipitated latent defects, including, chamber/facility usage hours; labor hours; labor classifications.

Ref. 17 provides an extensive discussion of data collection during production with emphasis on the aspects of environmental stress screening.

3.1.2 The Role of Failure Analysis in Determining Screening Effectiveness. The effectiveness of a screen can be measured by the number of latent defects that are precipitated by the screen (fallout) and the number of latent defects precipitated at subsequent screens. The fallout at one level of screening is insufficient as a measure of effectiveness because the number of latent defects entering the screen is unknown. A comparison of fallout at successive screens provides a basis for estimating the initial quantity of latent defects and, therefore, effectiveness.

The total number of failures occurring during a screen (or detected at a post-screen test) are not all precipitated latent defects. Some are patent defect escapes from lower level testing. Examples of such patent defects would be manufacturing errors such as missing components, improperly installed components and wiring errors which were not detected at prior test/inspection levels. A failure analysis of the "fallout" data is necessary to segregate the manufacturing errors from the true part and workmanship defects and to further segregate the screen-induced defects (precipitated latents) from the patent escapes. In some cases a detailed failure analysis, including part autopsy, may be required to distinguish latents from patents and should be done if economically justifiable. Analysis in conjunction with test thoroughness investigation will help in establishing the assembly level at which the defect was introduced.

3.1.3 Analysis of Stress Screening Data.

3.1.3.1 Data Analysis for Monitoring the Stress Screening Program. Since a stress screening program is established for the purpose of precipitating latent defects and thereby improving early field reliability and, perhaps, saving production costs in the process, it is highly desireable, if not absolutely necessary, to gather and analyze stress screening data to determine if latent defects are being precipitated at the expected rate. An extensive review of stress screening literature conducted during the course of this study confirms that data collection and analysis is the most neglected aspect of stress screening. Inasmuch as it is widely recognized that estimating the number of latent defects present is, at best, difficult and there is considerable uncertainty about the ability of various stress screens to precipitate those defects, the importance of carefully examining the initial screening results cannot be over-emphasized.

The SSM can be used to assist in the analysis of data. The model calculates the expected fallout F, of any screen i by,

$$F = (D_1 + ADEF_1) \cdot SS_1$$

where D_i = number of latent defects entering the screen at the ith assembly level

ADEF_i = number of latent workmanship defects introduced at the ith assembly level

SS_i = screening strength of the ith screen

The SSM also calculates a probability interval, i.e., upper and lower bounds on the expected fallout. A .99 probability interval is computed by the model unless a different interval is requested by the user. See Appendix B for a theoretical discussion of the probability interval calculation. If the actual number of defects precipitated by the screen is within the desired probability interval, it can be concluded that the stress screening is proceeding as expected. If, on the other hand, the actual fallout lies outside the interval, an analysis of the data is indicated. The fallout data may either exceed the upper bound or fall short of the lower bound. When the upper bound is exceeded, four possibilities exist:

- the screening strength may be greater than calculated by the model,
- 2) the estimate of the initial part fraction (PDEF) may be low,
- 3) the estimates of induced assembly defects (ADEF) may be low, or
- . 4) the fallout may include patent defects that escaped detection in prior process steps.

To be able to determine which of the four possibilities is most likely, a thorough analysis of the actual fallout data is required. If the fallout data is predominantly part defects as compared to assembly defects, possibility 2) seems likely. Conversely, if assembly defects predominate, possibility 3) seems more likely. If the part and assembly defects are in the expected proportion but high, possibilities 1) or 4) may be selected. the same type of reasoning can be applied when the actual fallout falls short of the lower bound.

3.1.3.2 Data Analysis for Evaluating the Stress Screening Program. Stress screening programs may be costly to implement, and are justified by the resulting subsequent savings. Caution should be exercised to avoid committing to a fixed stress screening regimen for a long production run on the basis of the initial cost-effectiveness analysis and early screening results. Time may bring about changes that impact on the cost-effectiveness of screening, such as changes in the magnitude and distribution of latent defects, cost of conducting screens, cost of repairs, and improved estimates of screening strengths. The SSM, with its optimization feature, can be used to determine a new set of

screens or revised screening parameters that are more cost effective. Refer to the examples in Section 4.0 to see how the SSM can be used for this purpose.

The data analyses required for cost-effectiveness evaluation are,

- 1) revised estimates of part and assembly defects
- 2) adjusted equipment-related parameters of screening equations (using the adaptive feature),
- 3) revised estimates of screening cost (at this point, the fixed cost is sunk cost and may be excluded from the analysis),
- 4) revised estimates of repair costs at each level of assembly.

Data analysis during a production screening program serves another vital purpose besides determining the cost-effectiveness of the screening. Proper analysis of fallout data aids in identification of "correctable" defects which, if corrective action is taken to eliminate their source/cause, will not recur in subsequent production items. Elimination of correctable defects results in reduced fallout and lower production costs, which may indicate a need to alter the screens. Sufficient elimination of correctable defects may result in no further need for screening.

3.1.3.3 Using the Chance Defective Exponential (CDE) Model to Evaluate Stress Screening Results. Ref. 11 provides a method of temperature cycle screening data analysis which gives estimates of screening strength, initial fraction defective and constant failure rate. Figure 3.1 is an extract from Ref. 11 showing a sample histogram plot of unit average failure rate per temperature cycle. The per cycle data is used to develop maximum likelihood estimates (MLE), for parameters a₀, a₁ and a₂ using a constrained optimization computer program developed by McDonnell Aircraft Company.

The parameters of the CDE model (a₀, a₁, and a₂) are directly related to key unknowns (initial fraction defective, screening strength, latent defective fallout rate) vital to planning, monitoring and evaluating stress screening programs. Therefore, the CDE model is considered to have potential as an analytical tool for evaluating a screening program. The parameters are;

 $a_0 = N\lambda g$, where N is the total number of parts in the item(s) subjected to stress screening

and λg is the failure rate of good parts, i.e., parts without latent defects. a_0 then provides a measure of failure rate of the good parts subjected to the screen.

- a₁ = Np, where p is the fraction of the part population that is latent defective. a₁ is then a measure of the total number of latent defective parts entering the screen.
- $a_2 = k \lambda g$, where k is the ratio of the failure rate of latent defective parts to the good parts. a_2 is then a measure of the rate at which latent defectives precipitate into patent defects under the conditions of the stress screen, and therefore is a measure of the screening strength.

Obtaining estimates of a_0 , a_1 , and a_2 , from actual screening fallout data allows the estimation of the vital screening program parameters. Since $a_0 = N \lambda g$, an estimate of a_0 provides an estimate of λg because N is known. Similarly, since a_1 , = Np, an estimate of a_1 provides an estimate of p (fraction defective). Finally, an estimate of a_2 provides an estimate of k since an estimate for λg is derived from a_0 .




Figure 3.1. Temperature Cycling Data Fitted to the Chance Defective Exponential Model (Ref 11)

3.2 Reporting of Results

- 3.2.1 Purpose of Reporting Results. Timely reporting of the results of stress screening to cognizant management personnel is important to provide the necessary visibility regarding progress toward achieving the stress screening program objectives (achievement of a reliability requirement, manufacturing cost savings, field maintenance cost savings, or combinations thereof). Timely and accurate reporting allows decisions to be made regarding changes to the stress screening program for improved effectiveness or enhanced cost savings. Reporting also serves as a forcing function on the important tasks of stress screening data collection and analysis.
- 3.2.2 Reporting Methods. There are three basic methods of reporting results to management,
 - 1) Periodic verbal reporting with visual aids,
 - 2) Periodic written reports, ranging from informal, internal correspondence to formal, contractually required reports, and
 - 3) Computer generated reports, either in hard copy form or image form on graphics terminals.

The verbal reporting method is most common and has the advantage of facilitating a question/answer exchange for report clarification. The disadvantage of this method is that it is more time consuming than the preparation of an informal report but this may be justified by the more effective information transfer. The verbal reporting is most desireable at the beginning of the stress screening program when there is the highest degree of uncertainty and highest management interest. As the stress screening program initial adjustments are effected and screening results are consistent with expectations, reporting should transfer to informal internal correspondence (e.g., weekly reports) and, perhaps, a formal monthly or bi-monthly report to the customer. The third reporting method is most efficient and is applicable during any phase of the stress screening program.

- 3.2.3 Report Content. The content of the reports should be tailored to the specific objectives of the stress screening program. If the primary objective is to achieve a reliability requirement, a reliability projection based on screening results is most appropriate. Cost data is always an appropriate reporting element and may include planned versus actual screening costs, manufacturing costs, or field maintenance costs. Below are some other typical reporting elements:
 - Assemblies screened to date (total number of)

- Assemblies passed screen without failure
- Assembly workmanship defects expected
- Upper and Lower Bounds
- Assemblies with 1, 2, ... defects
- Parts on assemblies screened
- Part defects detected
- Part defects expected
- Upper and Lower Bounds
- Assembly workmanship defects detected
- (Repeat of above for units, systems)
- Assembly yield
- Assembly repair costs
- Unit repair costs
- System repair costs
- Estimated part fraction defective
- Correctable failures
- Corrective action status

4. THE STRESS SCREENING MODEL (SSM)

4.1. Description of the Model. The SSM is a modified version of the Screening and Debugging Optimization (SDO) Model (Ref. 1), the changes to which are described in paragraph 1.2 of this report. A simplified flow diagram depicting the stress screening is shown in Figure 4.1 below. The figure shows process (INCOMING) the total number of parts and number of defective parts entering a screening process. At level 1, some workmanship defects (ADEF) are introduced and the screen at level 1 has some screening strength (SS) which acts on the incoming part and workmanship defects to produce an expected fallout of part defects (PRT) and workmanship defects (WKM). The total number of defects entering a level minus the fallout is the number of residual defects passed on to the next level (DEF PASSED). After passing through the three screening levels, there are still some defective parts remaining (DEF P REM) and some workmanship defects remaining (DEF W REM), resulting in some instantaneous outgoing MTBF value. At each level there is an expected fallout and because of random variations in defect quantities and screening strengths, a probability interval with upper and lower bounds (UPPR BND, LOWR BND) is computed for monitoring purposes.




Figure 4.1. Stress Screening Model Representation of the Production Flow Process

- 4.1.1 Model Options. The SSM has three options, as follows:
- 1) MTBF Option (Option A). The SSM provides an optimum set of stress screens to precipitate the required number of latent defects to achieve a desired instantaneous MTBP at the termination of the screening.
- 2) <u>Cost Option (Option B)</u>. The SSM provides a set of screens to precipitate the maximum number of latent defects for a fixed cost.
- 3) <u>Trade-off Option (Option C)</u>. The SSM provides the capability to evaluate existing screens and to identify equivalent screens for trade-off purposes.
- 4.1.2 The MTBF Option. In this option, the user must input the desired MTBF of the item(s) to be screened and must also input the total number of parts comprising the item(s) and the expected number of latent defects. User input requirements and model default values are described in paragraph 1.5 below. The MTBF value must be a series MTBF (i.e., the sum of the failure rate of all parts subjected to the stress screen). The model may be used for a single system or for multiple systems. The total number of parts and MTBF must be adjusted accordingly. The model assumes that the MTBF is comprised of the reliability characteristics of good parts, with a failure rate λg , and latent defective parts, with a failure rate $k\lambda g$, good connections with a failure rate $k\lambda g$, as follows:

$$MTBF = [(N-D)\lambda_g + Dk_1\lambda_g (M-C)\lambda_c + Ck_2\lambda_c]^{-1}$$
 (4-1)

where N = Total number of parts

D = Number of latent defective parts

k = Defective part failure rate multiplier
1

M = Total number of connections

C = Number of latent workmanship (connections) defects

k = Defective connection failure rate multiplier
2

The SSM uses equation (4-1) to determine the optimum set of screens that result in an MTBF equal to or greater than the desired MTBF.

- The Cost Option. In this option, the user must input a fixed cost amount for which the SSM will identify a set of stress screens removing the largest number of defects.
- The Trade-off Option. In those cases where a stress screening program has already been defined, the user may want to compare the overall cost and composite screening strength of the pre-defined screens with the optimum screens selected by the SSM. In this option, the user inputs the stress screen types and screen parameters and the SSM will compute the total cost and composite screening strength. This option also allows the determination of equivalent screens, i.e., if a given screen has some undesirable characteristics, an alternate screen of equivalent strength can be determined.
- Description of User Inputs to SSM and Model Defaults. Table 4.1 lists the SSM data requirements and default values. The model prompts the user for the necessary data for the option chosen.

A ceiling cost (CREQD) for the screening program is necessary only for Option B. The model optimizes removal of the largest number of latent defects while staying under the ceiling cost.

The total number of parts, the failure rate of good parts, the failure rate of good connections, and the fraction of parts which are defective are necessary for all options. Defaults are available for all but the number of parts. Expected latent defects are discussed in Paragraph 4.1.6 below.

The screen sequence is entered by use of the screen numbers as indicated below:

Screen No.	Screen
1	Constant Temperature
2	Cycled Temperature
3	Random Vibration
4	Sine Sweep Vibration
5	Sine Fixed Vibration

Model defaults are:

Level 1 Cycled Temperature (1)

Level 2 Random Vibration (3)

Level 3 Constant Temperature (2)

TABLE 4-1. STRESS SCREENING MODEL USER INPUT DATA REQUIREMENTS

6

MODEL INPUT VALUES

					MODEL INPUT VALUES	TES		
Data	Data Requirements	11V	Option A B	ပ	Program Symbol	Input Format	Units	Model Default Value
1 :	Desired Series MTBF		×		FRF	Integer	Hours	None,"(User Input Req.)
2.	Cost Budget		×		CREQD	Real	Dollars	None
	Total Part Population	×			NPARTS	Integer		None
4	Failure rate of good parts	×			XLAMP1	Real	Failures/ hour	1.x 10 ⁻⁷
٠,	Failure Rate of Good Connections	×			XLAM01	Real	Pailures/ hour	1x10 ⁻¹⁰
•	Fraction of Parts Latent Defective	×			PDEF	Real	Fraction of total parts	.001
7.	Screen Sequence	×			ISCR	Integer	٠.	ISCR(1)=2 ISCR(2)=3 ISCR(3)=1
&	Screen Parameters a) Constant Temp i) Temperature ii) Time	* **			APAX 11 APAX 12	Real Real	°C Houre	70°C 48 hours

* If a particular screen is used.

TABLE 4-1. STRESS SCREENING MODEL USER INPUT DATA REQUIREMENTS &

					MODEL INPUT VALUES	UES		
0100	d		1		£			Model
Req	rata Requirements	A11	Option A B	ပ	Frogram Symbol	Input Format	Units	Default Value
	b) Temp. Cycling							; ;
	i) Upper Temp.				AMAX 12	Real	ပ္	71° C
	11) Lower Temp.				AMAX 22	Real		–54° C
	111) Rate of Change	ge X			AMAX 23	Real	.c/Min.	10° C/Min.
	tv) No. of cycles				AMAX 24	Real	No. Cycles	20
	C) Random Vibration	uo *			200	Lood		
	1) g-rever	< ×			AMAX 32	Real	Minutes	10 Min.
67	d) Sine-Sweep Vib				AMAY A1	Real	a o	9
,	TA RATE OF	4 :			Th year	near near	M	10 M2
	11) Time	×			AMAX 42	кеат	Minutes	TO MIN.
	e) Sine-Fixed Vib							
	1) g-level				AMAX 51	Real	້ 8	8 9
	11) Time	×			AMAX 52	Real	Minutes	10 Min.
9.	Fixed Test Cost	×			A1	Real	Dollars	\$0.00
10.	10. Variable Test Cost	×			B1	Real	Dollars/hr	\$30/hour
11.	ll. Repair Cost	×			B3	Real	Dollars	Level 1 = \$45 Level 2 = \$300 Level 3 = \$990
•		>			gaur	Pool	Fraction	
. 71	Assembly Delects	∢			3	1899	of total	ADEF(1)= .002 ADEF(2)= .001 ADEP(3)= .0005
*	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		•					

^{**} If using to analyze fallout data.

TABLE 4-1. STRESS SCREENING MODEL USER INPUT DATA REQUIREMENTS

					MOM	MODEL INPUT VALUES			
Data Requi	Data Requirements	A11	Option A B	ပ ဗ ဆ		Program Symbol	Input Format	Units	Model Default Value
13.	13. Number of Dropouts at each level **	×				AFALL or 1f analyzing parts & workman- ship separately) APFALL AWFALL	Integer		None
14.	14. Probability for probability interval.	a1.	×	••	×	PER	REal		66.0
15.	No. of Faults Detected (Frllout)	×				NMF	REa 1		None
16.	Times to Failure	×				Н	REal		None

The SSM prompts the user for the test parameters in the chosen test. Table 4.2 identifies the parameters for each test.

TABLE 4.2 TEST PARAMETER CROSS REFERENCE

		TEST PA	RAMETER	
	No. 1	No. 2	No. 3	No. 4
1. Constant Temperature	Temp. Extreme (°C)	Test Time (Hrs.)	-	-
2. Cycled Temperature	Upper Temp. (°C)	Lower Temp. (°C)	Temp. Rate Change (OC/Min.)	Number Cycles
3. Random Vibration	Vibration G-level (g's)	Test Time (Min)	-	-
4. Sine Sweep	Vibration G-level (g's)	Test Time (Min)	-	<u>-</u>
5. Sine Fixed Vibration	Vibration G-level (g's)	Test Time (Min)	-	-

In Options A and B (MTBF and Cost) the user chooses all but the last parameter for all desired screens. An upper limit for a range is chosen for the final parameter. The model examines a grid of 5 points on each range. It then finds the optimal set of time and/or cycle parameters.

In Option C (Tradeoff) all parameters are fixed at user inputs. The model computes test strengths, costs, fallouts, etc.

When the screen equivalency capability is utilized only two screens are considered. All parameters in the given screen are fixed by the user. All but one selected parameter are fixed in the desired screen. The model finds the value for the

variable parameter. This value yields a strength for the desired test equal to the strength for the given test. If this value cannot be achieved, a message is written and the user may enter new parameters.

The basic cost equation for each test is of a linear nature where:

test cost = fixed cost + (variable cost x test duration).

The default used for fixed cost in the SSM is zero due to the assumption that test equipment, etc. are already available to the user. For assembly and unit levels the actual time on test is multiplied by 15% since it was found in a previous study (RADC-TR-78-55) that this yields an approximation of actual labor hours. If the user wishes to alter the 15% constant its location is given in Appendix F.

Test duration is a test parameter in all but temperature cycling screens. The time required to reach the temperature extremes is computed by using the temperature rate of change parameter. It was found that the function

$$t_{d} = 4/dT \tag{4-2}$$

where $t_d = dwell time$

dT = temperature rate of change (in oC/minute)

with units adjusted to yield hours, gave a good approximation of dwell time. Thus, test duration for temperature cycling is expressed.

$$d = 2N_{\text{cyc}} \left(t_{\text{t}} + t_{\text{d}}\right) \tag{4-3}$$

where d = test duration

N_{cyc} = number of cycles

 t_t = temperature transition time (minimum

temperature to maximum temperature)

td = dwell time

In all cases test duration is computed in hours and the input or default variable cost is in dollars per hour. If the user does not input a variable test cost the default of \$30/hour per hour is used.

The average cost to repair a defect found at each level may be input. The default repair costs are \$45 at level 1, \$300 at level 2, and \$990 at level 3.

Total costs at each level are given by the linear equation;

$$C_{\underline{i}} = C_{\underline{T}\underline{i}} + F_{\underline{i}} \cdot C_{\underline{R}} \tag{4-4}$$

where $C_i = \text{Total cost at level } i$

 $C_{T_i} = Test cost at level i$

F = Number of latent defects precipitated (fallout) at level i

C_p = Cost to repair at level i (one repair per defect)

Workmanship defects introduced at each assembly level (ADEF (i), i=1, 2, 3)) are entered as a fraction of the number of parts.

If the SSM is being used to analyze fallout data this data can be entered for each screening level. The model examines the number of defects detected at each level to determine if it is consistent with the expected number. Parts and workmanship fallout can be analyzed separately at each level or a total can be used.

A probability value (PER) can be entered to change the 0.99 probability interval about expected fallout automatically assumed by the model. A smaller probability yields a narrower interval. That is, if the expected mean is the true mean, the band which contains 80% of the actual fallout is narrower than the band which contains 99%. It is suggested that the probability interval not be made too narrow (PER not less than .80). An overly narrow interval may frequently result in instructions to change the screen when a change is not required. If the planned mean is the true mean, then (1-PER) is the fraction of the time actual fallout will still be outside the interval. That is, (1-PER) of the time instructions will be given to change the screen even though no change is needed.

- 4.1.6 Determining the Initial Fraction Latent Defectives. An incoming lot of parts contains three subpopulations, viz.,
 - o parts that are "good", i.e., free of defects and are expected to survive the useful life of the end item of

which they are a part, given that they are not subjected to stress beyond their ratings,

y /-

 parts that are "bad", i.e., containing a patent defect which precludes them from achieving their specified performance, and,

and the same and the same of t

 parts that are "marginal", i.e., containing a latent defect which when initially tested appear to be "good" parts but when subjected to normal operating stresses and time will transform to "bad" parts.

If an electrical test is performed on a received lot of parts, the fallout from the test is expected to be all or most of the "bad" parts. The "marginal" parts are not expected to fail unless the operating stresses applied during the test and the test duration are sufficient to transform the "marginal" part to a "bad" part.

There is expected to be a good correlation between the quality grade of parts used and the initial quantity of "bad" and "marginal" parts. That is, higher quality grade parts are expected to have fewer "bad" and "marginal" parts. This is particularly true for microcircuits because the processing and final test and inspection requirements on the part supplier increase in severity for increasing quality grades, which serves to reduce the quantity of marginal parts and preclude delivery of bad parts.

Table 4.3, Initial Fraction Latent Defective Parts, is intended to provide the user with default values in those cases where better information is not available. The table contains values for type of equipment and quality level. The type of equipment is characterized by percentage of microcircuits,

number of microcircuits x 100 total number of parts

Quality levels range from 1 to 8 and indicate the general quality grade of the equipment in terms of the various microcircuit, discrete semiconductor and passive part quality grades. The table values are derived through direct application of the values of MIL-HDBK-217C, Notice 1, for a typical part mix.

Table 4.4 provides a sampling of generic equipment types of recent vintage to aid the user in estimating the percentage of microcircuits that an equipment or system might contain if it can be related to one of the generic equipments.

TABLE 4.3 INITIAL FRACTION LATENT DEFECTIVE PARTS

Part Type				Quality (Grades		<u> </u>	
Microcircuits	S	В	B-1	B-2	C	C-1	D	D-1
Semiconductors	JTXV	JTX	Mixed	JAN/JTX	JAN	Mix. JAN	/Non-Mil	
Passives	S	R	P	M/P	M	L/M	L	Com'1
Level	1	2	3	4	5	6	7	8
Percent Microcircuits								
100	.00086	.00173	.00520	.01120	.01378	.02240	.03015	.06030
90	.00101	.00229	.00683	.01427	.01935	.03442	.04871	.09084
80	.00116	.00284	.00846	.01735	.02492	.04644	.06726	.12138
70	.00130	.00340	.01009	.02042	.03048	.05846	.08582	.15192
60	.00145	.00395	.01172	.02349	.03605	.07048	.10437	.18246
50	.00160	.00451	.01335	.02657	.04162	.08250	.12293	.21300
40	.00175	.00506	.01498	.02964	.04719	.09452	.14148	.24354
30	.00190	.00562	.01661	.03271	.05276	.10654	.16044	.27408
20	.00204	.00617	.01824	.03578	.05832	.11856	.17859	.30462
10	.00219	.00673	.01987	.03886	.06389	.13058	.19715	.33516
0	.00234	.00728	.02150	.04193	.06946	.14260	.21570	.36570

4.2 Using the Model.

4.2.1 General Instructions for User. The Stress Screening Model consists of three programs designed to run interactively on a terminal.

NOTICE: The third program, "Adapt", must be link-edited to the single precision IMSL library in order to run in its present form. See Step 5 of Section 4.2.2.

If a user has access to the IBM 370 TSO system (or equivalent) refer to paragraph 4.2.2. If not, the following general instructions describe the use of the Stress Screening Model.

TABLE 4.4 PARTS MIX FOR SAMPLE GENERIC EQUIPMENTS

			QUANTITY OF PARTS	STATS		٠
GENERIC EQUIPMENT TYPE	PERCENT MICROCIRCUITS	MICROCIRCUITS	DISCRETE SEMICONDUCTORS	PASSIVES	LATION POPU-	TOTAL
SHIPBOARD DISPLAY CONSOLE	54.5	4228	1528	1889	137	7782
MILITARIZED LARGE COMPUTER	44.0	4598	428	\$90\$	354	10,443
MILITARIZED MINI COMPUTER	39.0	814	23	1180	12	2,088
SHIPBOARD INTERFACE UNIT	37.8	4785	1016	8556	1300	12,657
RADAR OPERATIONS VAN	35.5	5361	1051	8294	888	15,094
RADAR VIDEO PROCESSOR	34.4	3206	385	4837	896	9324
SUBMARINE DISPLAY CONSOLE	32.2	5963	1807	10,270	450	18,490
TORPEDO GUIDANCE AND CONTROL	31.9	6806	1483	12,653	412	21,354
SHIPBOARD INTERFACE UNIT	29.4	7787	2367	15,126	1200	26,480
AIRBORNE COMMUNICATIONS TERMINAL	24.7	3864	1352	9752	705	15,673
SHIPBOARD SEARCH RADAR	19.2	3713	2381	10,522	2700	19,316
COMPUTER PERIPHERAL (MAG TAPE UNIT)	18.6	214	194	737	•	1149
SHIPBOARD SEARCH RADAR	16.2	2420	1794	10,139	571	14,924
AIR DEFENSE DISPLAY CONSOLE	16.0	1685	1074	6637	1104	10,500
GROUND MOBILE RADAR	14.9	878	798	3882	*	2065
SUBMARINE INTERFACE UNIT	9.6	\$15	2657	2484	354	6010
TOTALS		56,837	20,338	109,021	10,990	197,186

The three FORTRAN IV programs (PREFIX, SDO1, and ADAPT) comprise the SSM and together require nine working data sets for operation. These data sets should be "card image" (i.e., record length of 80 characters) with appropriate blocking (consult your installation requirements) and should be assigned FORTRAN IV data set reference numbers 2, 4, 8, 9, 10, 11, 12, 13, and 17. While the names assigned to these data sets are irrelevant to the operation of the programs, the naming conventions used in paragraph 4.2.2 are recommended. They are consistent with the data sets in a previous version of the SSM (RADC-TR-78-55).

The next step is to assemble the required input data using Table 4.1 as a guide. Having allocated the working data sets, the next step is to run the programs PREFIX, SDO1, and ADAPT, in that order. The programs will prompt the user for all input data which has been assembled.

- 4.2.2 IBM 370 TSO User Instructions. Figure 4.2 is a simplified flow diagram of the SSM. The following instructions describe the five steps necessary for initial use of the SSM.
- Step 1. Using the program listings in Appendix F, create PREFIX.SDO.LOAD, SDO1.LOAD, and ADAPT.LOAD. Recall that ADAPT.OBJ should be link-edited to the single precision IMSL library when forming ADAPT.LOAD. ADAPT.OBJ is the object program compiled from the source program ADAPT.FORT.
- Step 2. Create the empty data sets PROGRM.DATA, PD.DATA, F.DATA, R.DATA, AB.DATA, LIMITS.DATA, OPS.DATA, FTIME.DATA, and ADAPT.DATA. The user is not required to enter data directly into these files. All data is entered interactively. The data files are reused each time the model is executed. Thus, once they are created, they may be ignored by the user. They are only used to transfer data from one program to the next.
- Step 3. Assemble required data. Using Table 4.1 as a guide, determine user-unique values, default values, etc. Also see the examples which follow.

Step 4. Execute the CLIST:

```
000010 FREEALL
000012 ALLOC FI(FT02F001) DA(ADAPT.DATA)
000020 ALLOC FI(FT04F001) DA(PROGRM.DATA)
000030 ALLOC FI(FT11F001) DA(PD.DATA)
000040 ALLOC FI(FT08F001) DA(F.DATA)
000050 ALLOC FI(FT09F001) DA(R.DATA)
000060 ALLOC FI(FT10F001) DA(AB.DATA)
000070 ALLOC FI(FT12F001) DA(LIMITS.DATA)
000080 ALLOC FI(FT13F001) DA(OPS.DATA)
000085 ALLOC FI(FT17F001) DA(FTIME.DATA)
```




Figure 4.2. Flow Diagram of the Stress Screening Model

000090 CALL PREFIX.SDO.LOAD(TEMPNAME) 000100 CALL SDO1.LOAD(TEMPNAME) 000105 CALL ADAPT.LOAD(TEMPNAME) 000110 END

Step 5. Enter data as prompted. Once data is input, the optimization and flow chart output will be printed without further action from the user. If there is actual fallout data to be analyzed, the user will be prompted. If equivalent screens are to be found, the parameters will be called for.

For subsequent use, only steps 3, 4, and 5 will be necessary for use of the model since the load modules and data sets are on file. The examples which follow illustrate some of the possible options.

Two proprietary routines are used in the model. If IMSL is not already available the user may wish to contact

International Mathematical and Statistical Libraries, Inc. Sixth Floor - NBC Building 7500 Bellaire Boulevard Houston, Texas 77036

Telephone (713) 772-1927 Telex 79-1923 IMSL INC HOU.

The IMSL routine MDCH is used in the computation of the bounds for actual fallout in this program. As stated previously, ADAPT.OBJ needs to be link-edited to the single precision IMSL library in order to run in its present form.

The use of MDCH is as follows:

CALL MDCH(CS, DF, P, IER)

where

- DF = input value containing number of degrees of freedom of the chi-squared distribution. DF must be greater than or equal to .5 and less than or equal to 200,000.
 - P = output value containing probability.
- IER = error parameter. Terminal error = 128 + N. N=1
 indicates that CS or DF was specified incorrectly.

Warning error = 32 + N. N=2 indicates that the normal PDF would have produced an underflow.

MDCH computes the probability P that a random variable X which follows the chi-squared distribution with continuous parameter DF, is less than or equal to CS.

Any chi-squared routine with similar input and output parameters could be substituted if access to the IMSL library is not available.

The two lines -

CALL MDCH (X1,B(I),P,IER)

BOUN 300

CALL MDCH (X1,B1,P1,IER)

BOUN 360

found in ADAPT.FORT would be the only program lines changed if a different library routine is used.

A Newton-Raphson root-finding technique is used to obtain the degrees of freedom since no available routine could do that directly.

The IMSL Routine ZXSSQ is used for the least squares fit of failure times to the CDE model. Parameters a₁ and a₂ of the CDE model are estimated. Fairly extensive rewriting will be necessary if a different curve-fitting routine is to be used. However, if times to failure for level III are not to be analyzed, ZXSSQ is not needed. The line calling ZXSSQ (OPT 200 in ADAPT) may be removed in this case.

- 4.3 Examples of SSM Use
- 4.3.1 MTBF Option Examples
- Planning a Stress Screening Program to Achieve a Certain MTBF, without Pre-established Screens. The user in this example specifies an MTBF of 1200 hours and selects the model default screens at the assembly, unit and system levels. The least cost Thermal cycling screen at the assembly level and random vibration screen at the unit level to achieve the desired MTBF is determined by the SSM. A screen at the system level is determined not necessary to achieve the 1200 hour MTBF value.

***** SELECTION OF PROGRAM INPUTS AND OPTIONS *******

IF THE MODEL DEFAULT IS DESIRED, ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A GIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTIMIZES PRODUCT RELIABILITY GIVEN A FIXED COST

OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

DESIRED SERIES HTBF OF NEW SYSTEM (OPTION A ONLY, FOR OPTIONS B OR CENTER ZERO)

1200

TOTAL PART POPULATION(NO DEFAULT AVAILABLE)

5000

FAILURE RATES OF GOOD PARTS: GOOD CONNECTIONS=

?

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS=

Λ

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
- 2. CYCLED TEMPERATURE
- 3. RANDOM VIBRATION
- 4. SINE SWEEP "IBRATION
- 5. SINE FIXED VIBRATION

DEFAULTS ARE:

LEVEL 1 LEVEL 2 LEVEL 3
TEMP. CYCLING RAN. VIB CONST. TEMP.
(2) (3) (1)

IF YOU WISH DEFAULT SCREENS ENTER ZERO, IF NOT, ENTER 1:

: ^

*******LEYEL |*******

TEMPERATURE CYCLING, LEVEL 1
THE DEFAULT VALUES ARE:
LOWER TEMP=-54 DE6 C
UPPER TEMP=71 DEG C
TEMP. RATE OF CHANGE=5 DE6 C/NIN
RANGE OF CYCLES TO BE INVESTIGATED=0 TO 20
IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:

: 0

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 1

IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN DOLLARS=

0

VARIABLE TEST COST IN DOLLARS PER HOUR=

0

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

(

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

0

*******LEYEL 2******

RANDOM VIBRATION, LEVEL 2
THE DEFAULT VALUES ARE:
6-LEVEL=6 G
RANGE OF TIME TO BE INVESTIGATED=0 TO 10 NIN.
IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:

?

ENTER THE FOLLOWING MANUFACTURING PROCESS BATA, LEVEL 2

IF MODEL BEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN DOLLARS=

?

VARIABLE TEST COST IN DOLLARS PER HOUR=

?

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

9

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

0

*******LEVEL 3******

CONSTANT TEMPERATURE, LEVEL 3
THE DEFAULT VALUES ARE:
TEMPERATURE=70 DE6 C
TIME RANGE TO BE INVESTIGATED=0 TO 48 HOURS
IF YOU WISH THE DEFAULT VALUES, ENTER ZERO, IF NOT, ENTER 1:

? ^

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 3

IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN DOLLARS=

?

VARIABLE TEST COST IN DOLLARS PER HOUR=

?

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

?

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

•

IF YOU WISH A TABLE OF INPUTS ENTER 1, IF NOT, ENTER ZERO:

ì

PROGRAM DATA

NF	PARTS	LEVELS	(PDEF X	MPARTS)	CREOD	MTBI	
	5000	3		5.	0.0		1200.
				ASSEMBLY DA	TA		
**************************************	ASSEMBLY	LEVEL	EXPECT	ED NUMBER OF	ASSEMBLY	DEFECTS	
	1 2 3				10. 5. 3.		
~ ~ ~ ~ ~ ~ ~ ~				REWORK COS	ST		
		LEVEL 1 LEVEL 2 LEVEL 3				45. 300. 990.	

TEST SEQUENCE TYP	'E RU. 1	NO. 2	NO. 3	NO. 4	TOTAL COST(\$)
LEVEL NO. 1					450.
TEST NO. 2 CYT	71.00	-54.00	5.00	5.00	450.
LEVEL NO. 2					1955.
TEST NO. 3 RV	IB 6.00	7.50	1.0	0.0	1 <i>9</i> 55. 0.
TEST NO. 1 CT	0.0	0.0	1.0	0.0	0.

INSTANTANEOUS HTBF FOR REMAINING FLAUS AT END OF SCREENING

			L	IORKMANSHI	P			
PARTS	1	5.	6.	7.	8.	9.	10.	11.
0.	:	1956.	1955.	1955.	1955.	1954.	1954.	1954.
0.	1	1956.	1955.	1955.	1955.	1954.	1954.	1954.
1.	:	1586.	1584.	1586.	1586.	1585.	1585.	1585.
2.	1	1204.	1204.	1204.	1204.	1204.	1204.	1204.
3.	:	971.	971.	971.	970.	970.	970.	970.
4.	;	813.	813.	813.	813.	813.	813.	813.
5.		499.	699.	699.	499.	699.	699.	699.

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER ZERO IF YOU WISH TO ENTER A SMALLER PROBABILITY (FOR A NARROWER INTERVAL) ENTER ONE:

ENTER PROBABILITY DESIRED:

1

.8

STRESS SCREENING FLOW DIAGRAM

: INCONING :	: LEVEL 1 :	! LEVEL 2 !	: LEVEL 3 !	: OUTGOING :
		ABEF= !		
		5.1		
! !!);		
: #DEFECTS: :	its= i	:TS= :		IDEF B REN:
: 5.:	: 0.403;	: 0.466:	: 0.0 :	: 8.:
: :	; ;	1 1	:	:
1		:DEF PASSED:		
;	9.1	7.1	10.;	1204.
; ;	:	: :	:	: :
	•	;	:	
	;	:	:	
	V	V	•	

	:	1 1	!	
		: EXPECTED :		
	: FALLOUT: :	: FALLOUT: : :	FALLOUT: :	
	: :	1 1 1	!	
	· · · · · · · · · · · · · · · · · · ·	PRT WEN TOT:		
	1 2. 4. 6.1	1 1. 6. 7.1	0. 0. 0.	
	1	1		
		SUPPR BND FOR:		
	IDDS FALLOUT:	IOBS FALLOUT:	UBS FALLOUT:	
	i i	i		
	i J. 8. 10.i	3. 9. 11.	. V. V. V.	
	I I I I I I I I I I I I I I I I I I I	: :Lour BND For: :	i Ilaun bar cort	
		COBS FALLOUT:		
	OPS PRELOUIS:	IVDO PHELUUIII	OPS THELBUILL	
		0. 2. 2.		
	• V• I• Z• i	. V. Z. Z.i i	, v. v. v. i	
	1			

INTERVAL HIBF

TIME	1	NTBF
2000.	!	1219.
4000.	;	1233.
6000.	:	1247.
8000.	:	1261.
10000.	:	1275.
12000.	i	1288.
14000.	ŀ	1302.
16000.	:	1314.
18000.	:	1327.
20000.	!	1339.

```
IF YOU HAVE FALLOUT DATA ENTER 1, IF NOT ENTER ZERO:

IF YOU HAVE SEPARATE FALLOUT FOR PARTS AND WORKHANSHIP ENTER ONE IF YOU HAVE TOTAL FALLOUT ONLY AT EACH LEVEL, ENTER ZERO:

ENTER, IN ORDER, ACTUAL FALLOUT:
DUE TO (A) PARTS (B) WORKHANSHIP, AS PROMPTED:
FOR LEVEL 1:

FOR LEVEL 2:

FOR LEVEL 3:
```

0 0

STRESS SCREENING RESULTS:

	•			-								-				•
: INCOMING		: LE	VEL 1	:	LE	VEL 2	2 :		LEV	EL 3	!		001	60	ING	
: #PARTS:	:	: ADE	F =	1	ADE	F≠	:		ABE	=	:		DEF	P 1	REN:	:
			10.	!	t		5		•	•	1.1		<u> </u>			
		:		>	:			>				>				•
: #DEFECTS:				•	:TS=			!	:TS=	•	i		DEF		REM:	:
			0.067	1	1	0.4	166		:	0.0	•		1		10.	
:	•	:		:	;		;		:		:	1	;			!
:	:	: DEF	PASSE	1	DEF	PASS	ED:		DEF	PASS	ED:		HTB			ľ
1	:	:	14.	1	1	1	10.	1	:	13	3.:		:		901.	1
:	:	:		:	:		:	!	:		i		:			;
	-			-				•				•				-
			;			;				ŀ						
			i .			:				:						
			V			V				V						
	-											•-				
	;			1 1				: :				1				
	i		PECTED								_					
	i	FA	LLOUT:		FA	LTO8.	T:	! !	FA	LLOUT	:	•				
	i															
	i		WKM T													
	i	V.	1.	• i i	2.	/•	γ,	• • •	v.	U.	٧.	í				
	•	11000	BND F	i i 1 191	1100	DM2	501	, i	11099	240	CUB					
	-	• • • • • • • • • • • • • • • • • • • •	FALLOU		• • • •				•			•				
	•	750	. 46600			. ALL			4 54 (4 7 4	:				
		0.	3. :	.	5.	11.	14	. i	0.	٥.	٥.	:				
		- •	•••	1	;	•	• •		•		•	•				
		LOUR	BND F	OR:	LOWA	BND	FOI	ti i	LOUR	BND	FOR					
		ODS	FALLOU'	Te:	OBS	FALL	OUT	: :	035	FALLE	UT:	P				
	:			: :	}			: :				;				
	:	0.	0.).: :	0.	3.	4.	.: :	0.	0.	0.					
	1			: :	}			: :				;				
												-				

INCREASE NUMBER OF CYCLES ON LEVEL 1 TO 40.00

4.3.1.2 Planning a Stress Screen Program to Achieve a Certain MTBF, with Pre-established Screens. In this example the user is constrained to apply a pre-established screen (perhaps required by contract) at the Unit level. The SSM determines the minimum number of thermal cycles necessary to achieve the desired MTBF.

****** SELECTION OF PROGRAM INPUTS AND OPTIONS *******

IF THE MODEL DEFAULT IS DESIRED, ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A GIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTIMIZES PRODUCT RELIABILITY GIVEN A FIXED COST

OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

DESIRED SERIES HTBF OF NEW SYSTEM (OPTION A ONLY, FOR OPTIONS B OR C ENTER ZERO)

? 900

TOTAL PART POPULATION (NO DEFAULT AVAILABLE)

? 5000

FAILURE RATES OF 600D PARTS; 600D CONNECTIONS=

0 0

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS=

Ó

```
1
FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:
1. CONSTANT TEMPERATURE
2. TEMPERATURE CYCLING
3. RANSON VISRATION
4. SINE SWEEP VIBRATION
5. SINE FIXED VIBRATION
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN SCREEN:
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO DESIRED SCREEN:
4
ENTER PARAMETERS FOR SIVEN SCREEN:
ENTER 6 LEVEL AND TIME IN MINUTES
6 7.5
ENTER PARAMETERS FOR DESIRED SCREEN:
 ENTER ZERO FOR PARAMETER TO BE FOUND:
ENTER B LEVEL AND TIME IN MINUTES
0 60
TEST STRENGTH FOR GIVEN SCREEN= 0.4658
PARAMETER FOR DESIRED VIBRATION SCREEN=
                                              5.8
IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO:
?
0
```

IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO:

IF YOU HAVE TIMES TO FAILURE FOR LEVEL III ENTER 1,

IF NOT, ENTER ZERO:

0 REABY

*******LEVEL 2******

```
TEMPERATURE CYCLING, LEVEL 2
    THE DEFAULT VALUES ARE:
    LOVER TEMP=-54 DEG C
    UPPER TEMP=71 DEG C
    TEMP. RATE OF CHANGE=5 DE6 C/MIN
    RANGE OF CYCLES TO BE INVESTIGATED=0 TO 20
    IF YOU WISH THE BEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:
    ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES:
    UPPER TEMP., LOWER TEMP., TEMP. RATE OF CHANGE, NO. OF CYCLES:
    (TEMPERATURE RANGE MUST BE WITHIN -55 TO +75 DEG C
    AND RATE OF CHANGE BETWEEN 1 AND 20 DES C/MIN)
75 -40 5 24
    ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 2
    IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:
    FIXED TEST COST IN DOLLARS=
10000
    VARIABLE TEST COST IN DOLLARS PER HOUR=
?
0
    AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=
?
0
    ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=
.002
```

.

*******TEST AND PARAMETER SELECTION******

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
- 2. CYCLED TEMPERATURE
- 3. RANDON VIBRATION
- 4. SINE SUEEP VIBRATION
- 5. SINE FIXED VIBRATION

DEFAULTS ARE:

LEVEL 1 LEVEL 2 LEVEL 3
TEMP. CYCLING RAN.VIB CONST. IEMP.
(2) (3) (1)

IF YOU WISH DEFAULT SCREENS ENTER ZERO, IF NOT, ENTER 1:

1

ENTER YOUR SCREEN SEQUENCE AS PRONPTED USING NUMBERS FROM ABOVE LISTING:
IF YOU DO NOT WISH TO SCREEN AT A PARTICULAR LEVEL, ENTER ZERO:

FOR LEVEL 1 THE SCREEN NUMBER DESIRED IS:

?

FOR LEVEL 2 THE SCREEN NUMBER DESIRED IS:

?

FOR LEVEL 3 THE SCREEN NUMBER DESIRED IS:

?

0

TEST DESCRIPTION

			P	ARAMETE	R VALUE		
TEST SEQUENC	E 	TYPE	NO. 1	NO. 2	NO. 3	NO. 4	TOTAL COST(
LEVEL NO. 1							1.
TEST NO.	1		0.0	0.0	0.0	0.0	0.
LEVEL NO. 2							12071.
TEST NO.	2	CYT	75.00	-40.00	5.00	6.00	12071.
LEVEL NO. 3							٥.
TEST NO.	1		0.0	0.0	0.0	0.0	0.

INSTANTANEOUS NTBF FOR REMAINING FLAUS AT END OF SCREENING

WORKMANSHIP

			¥	1 11 2 7 18 11 1 1 1 1 1 1	F			
		3.						
		1957.						
		1436.						
2.	:	1116.	1115.	1115.	1115.	1115.	1115.	1115.
3.	:	912.	912.	912.	912.	912.	912.	912.
4.	:	771.	<i>77</i> 1.	771.	771.	<i>7</i> 71.	<i>7</i> 71.	771.
5.	:	668.	668.	668.	448.	668.	668.	668.
6 -	:	590.	590.	590.	590.	589.	589.	581

	IF	108	ui sh	A	TABLE	OF	INPUTS	ENTER	1,	IF	WOT,	ENTER	ZERO:
7									·		-		
1													

PROGRAM DATA								
NPARTS	LEVELS	(PBEF X NPARTS)	CREQD	ATDF				
5000	3	5.	•.0	700.				
		assenbly	DATA					
ASSENDI	LY LEVEL	EXPECTED NUMBER	OF ASSEMBLY DI	EFECTS				
1 2			0. 10.					
3			0.					
		REVORK	COST					
	LEVEL			45.				
	LEVEL	2 3		300. 990.				

INTERVAL ATBF

TIME	:	MIBF
2000.	:	944.
4000.	:	176.
4000.	:	1007.
8000.	1	1037.
10000.	;	1066.
12000.	:	1094.
14000.	;	1122.
16000.	:	1148.
18000.	;	1174.
20000.	:	1199.

IF YOU HAVE FALLOUT DATA ENTER 1, IF NOT ENTER ZERO:
?
O
IF YOU WISH TO ANALYZE EQUIVALENT SCREENS ENTER ONE
IF NOT ENTER ZERO:
?
O
READY

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER IERO
IF YOU WISH TO ENTER A SHALLER PPOBABILITY (FOR A MARROWER INTERVAL)
ENTER ONE:

0

STRESS SCREENING FLOW DIAGRAM

: INCOMING :	: LEVEL 1 :	: LEVEL 2 :	LEVEL 3	: ONTOOTHO:
; 5000:	ADEF=	10.1		1 3.1
: #DEFECTS: :		:TS= :	:1S= :	DEF W REM
	: : :Def passed: : 5.:		: JEF PASSED:	
: :::::::::::::::::::::::::::::::::::::	: : :	: : : : : : : : : : : : : : : : : : :		
		: EXPECTED : FALLOUT: :	: EXPECTED : FALLOUT: :	
		PRT UKN TOT: 2. 4. 6.:	· · · · · · · · · · · · · · · · · · ·	
		UPPR BND FOR!		
	1	7. 11. 14.	1	
		:LOWR BND FOR: :OBS FALLOUT::	:086 FALLOUT::	
	1 0. 0. 0.1	0. 0. 0.	1 0. 0. 0.1	

********TEST AND PARAMETER SELECTION*******

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
- 2. CYCLED TEMPERATURE
- 3. RANDON VIBRATION
- 4. SINE SUEEP VIBRATION
- 5. SINE FIXED VIBRATION

DEFAULTS ARE:

LEVEL 1 LEVEL 2 LEVEL 3
TEMP. CYCLING RAN.VIB CONST. TEMP.
(2) (3) (1)

IF YOU WISH DEFAULT SCREENS ENTER ZERO, IF NOT, ENTER 1:

Planning a Stress Screening Program to Achieve a Certain MTBF, No Solution. In this example, the desired MTBF cannot be achieved by stress screening alone. The SSM determines that maximum strength screens will not precipitate enough latent defects to achieve the desired MTBF. Other measures are required, such as reducing the incoming part fraction defective (by using higher quality grade parts or performing incoming receiving screening) or by reducing the workmanship defects induced at one or more stages. The SSM prints out the best possible solution for the conditions given.

****** SELECTION OF PROGRAM INPUTS AND OPTIONS ******

IF THE MODEL DEFAULT IS DESIRED, ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A GIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTIMIZES PRODUCT RELIABILITY SIVEN A FIXED COST

OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

DESIRED SERIES HIBF OF NEW SYSTEM (OPTION & ONLY, FOR OPTIONS B OR CENTER ZERO)

! 1300

. .'

TOTAL PART POPULATION(NO BEFAULT AVAILABLE)

8000

FAILURE RATES OF GOOD PARTS; GOOD CONNECTIONS=

: 0 0

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS=

Ò

*******LEVEL 2******

RANDON VIBRATION, LEVEL 2 THE DEFAULT VALUES ARE: 6-LEVEL=6 G RANGE OF TIME TO BE INVESTIGATED=0 TO 10 MIM. IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1: ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES: 6 LEVEL, TIME IN MIN: (G LEVEL HUST BE BETWEEN .6 AND 7.5) ? 6 40 ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 2 IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO: FIXED TEST COST IN BOLLARS= VARIABLE TEST COST IN DOLLARS PER HOUR= AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL= 0 ASSEMBLY BEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

*******LEYEL 1******

TEMPERATURE CYCLING, LEVEL 1
THE DEFAULT VALUES ARE:
LOWER TEMP=-54 DEG C
UPPER TEMP=71 DEG C
TEMP. RATE OF CHANGE=5 DEG C/NIN
RANGE OF CYCLES TO BE INVESTIGATED=0 TO 20
IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:

.

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 1

IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN BOLLARS=

0

VARIABLE TEST COST IN DOLLARS PER HOUR=

?

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

?

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

IF YOU WISH A TABLE OF INPUTS ENTER 1, IF NOT, ENTER ZERO:

PROGRAM DATA

NPARTS LEVELS (PDEF X NPARTS) CREAD MTBF

8000 3 8. 0.0 1300.

ASSEMBLY DATA

ASSEMBLY LEVEL EXPECTED NUMBER OF ASSEMBLY DEFECTS

1 16.
2 8.
3 4.

REWORK COST

REQUIREMENT CANNOT BE MET

LEVEL 1 LEVEL 2 LEVEL 3

*******LEVEL 3*****

CONSTANT TEMPERATURE, LEVEL 3 THE BEFAULT VALUES ARE: TEMPERATURE=76 BES.C TIME RANGE TO BE INVESTIGATED=0 TO 48 HOURS IF YOU WISH THE DEFAULT VALUES, ENTER ZERO, IF NOT, ENTER 1: ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES: TEMP IN DEG C, TIME IN HRS: (TEMP MUST BE LESS THAN +75 DEG C) 70 96 ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 3 IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO: FIXED TEST COST IN DOLLARS= 0 **VARIABLE TEST COST IN DOLLARS PER HOUR=** AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL= 0 ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

STRESS SCREENING FLOW DIAGRAM

				'				
INCOMINE :	•	: LEVEL 1	- !	: LEVEL 2	-	: LEVEL 3	- !	: OUTEOINE
			•		-		_	
		:ABEF=						:DEF P REH:
		: 16.						1.
•	•					•	!>	*
DEFECTS:					•			DEF W REM
8.;		0.615	i !	i V.05 3	i I	i V.314 !	į	. • • • • • • • • • • • • • • • • • • •
		:Def passed:	! !	:DEF PASSED	:	:DEF PASSED	:	:NTBF:
		9.		: 5.		. 6.		1051.
:		:	}	:	:	:	:	:
*******	•		-		-		-	
						:		
		i U		i M		10		
		· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·		
	;		: :		; ;		;	
	:	EXPECTED	: :	EXPECTED	::	EXPECTED	1	
	1	FALLOUT:	1 1	FALLOUT:	1 1	FALLOUT:	1	
	•				_: :	im=	_	
	i			PRT UKM TO				
	•	7. 11. 15.		2. 10. 12	• • • •	v. s. s	• i	
	i	UPPR BND FOI	: i	MPPR BND FO	R: :	UPPR BND FO	R:	
		DBS FALLOUT						
	;		: :		: :		;	
	;	11. 21. 26.		7. 20. 22	.	0. 9. 9	. !	
		0110 DED 501						
		LOWR BWD FOI DBS FALLOUT:						
	:	DBS THILBUIT	1 1	DDS FMLLWUI		DIO PRELUCI	*	
		0. 2. 5.		0. 2. 3	. ; ;	0. 0. 0	. :	
	:		1 1				1	

	T E				10, 1	
	TYPE	• •			1 0. 4	TOTAL COST(\$)
						1375.
2	CYT	71.00	-54.00	5.00	20.00	1375. 3557.
3	RVIB	6.00	40.00	•.0	0.0	3557. 5824.
1	CT	70.00	94.00	0.0	0.0	5824.
					s	10754.
	2	2 CYT 3 RVIB	2 CYT 71.00 3 RVIB 6.00	PARAMÈTE TYPE NO. 1 NO. 2 2 CYT 71.00 -54.00 3 RUIB 6.00 40.00	PARAMÈTER VALUE TYPE NO. 1 NO. 2 NO. 3 2 CYT 71.00 -54.00 5.00 3 RVIB 6.00 40.00 0.0	TYPE NS. 1 NO. 2 NO. 3 NO. 4 2 CYT 71.00 -54.00 5.00 20.00 3 RUIB 6.00 40.00 0.0 0.0

INSTANTANEOUS HTBF FOR REMAINING FLAUS AT END OF SCREENING

			u	ORKMANSHI	P			
PARTS	:	3.	4.	5.	6.	7.	8.	7.
0.	;	1223.	1223.	1223.	1223.	1223.	1222.	1222.
0.	:	1223.	1223.	1223.	1223.	1223.	1222.	1222.
٥.	:	1223.	1223.	1223.	1223.	1223.	1222.	1222.
1.	1	1051.	1051.	1051.	1051.	1051.	1051.	1050.
2.	:	869.	869.	868.	848.	8 68.	868.	848.
3.	;	740.	740.	740.	740.	740.	740.	740.
4.	:	645.	645.	645.	645.	645.	645.	644.

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER ZERO IF YOU WISH TO ENTER A SMALLER PROBABILITY (FOR A MARROWER INTERVAL) ENTER ONE:

```
IF YOU HAVE FALLOUT DATA ENTER 1, IF NOT ENTER ZERO:
IF YOU WISH TO ANALYZE EQUIVALENT SCREENS ENTER ONE
IF NOT ENTER ZERO:
1
FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:
1. CONSTANT TEMPERATURE
2. TEMPERATURE CYCLING
3. RANDOM VIBRATION
4. SINE SWEEP VIBRATION
5. SIME FIXED VIBRATION
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO SIVEN SCREEN:
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO DESIRED SCREEN:
2
ENIER PARAMETERS FOR SIVER SCREEN:
ENTER ABSOLUTE VALUE OF DIFFERENCE BETWEEN TEMP IN DEG C AND 25 DEG C
 AND TIME IN HOURS
45 96
ENIER PARAMETERS FOR DESIRED SCREEN;
EITER ZERO FOR PARAMETER TO BE FOUND:
ENIER RANGE IN DES C
TIMP RATE OF CHANGE IN DEG C/MIN
AID NUMBER OF CYCLES
100 3 0
```

8.0

TEST STRENGTH FOR GIVEN SCREEN= 0.3143

PAIANETER IN DESIRED TEMP CYCLING SCREEN=

INTERVAL STOF

	•••	
TIME	:	NTBF
2000.	:	1054.
4000.	;	1457.
4000.	:	1060.
8000.	;	1063.
10000.	:	1065.
12000.	;	1048.
14000.	i	1071.
16000.	;	1073.
18040.	:	1076.
20000.	;	1078.

4.3.2 Cost Option Example

In this example, the user desires a set of screens which precipitate the maximum number of latent defects for a fixed dollar amount of \$40,000.

***** SELECTION OF PROGRAM INPUTS AND OPTIONS ******

IF THE MODEL DEFAULT IS DESIRED, ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A SIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTIMIZES PRODUCT RELIABILITY GIVEN A FIXED COST

OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

DESIRED SERIES HTBF OF NEW SYSTEM (OPTION & ONLY, FOR OPTIONS B OR C ENTER ZERO)

0

COST BUDGET(OPTION B ONLY, FOR OPTION A OR C ENTER ZERO)

40000

TOTAL PART POPULATION (NO BEFAULT AVAILABLE)

? 7000

FAILURE RATES OF GOOD PARTS; GOOD CONNECTIONS=

?

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS=

Ó

IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO: ?

FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:

- 1. CONSTANT TEMPERATURE
- 2. TEMPERATURE CYCLING
- 3. RANDON VIBRATION

ï

- 4. SINE SWEEP VIBRATION
- 5. SIME FIXED VIBRATION

ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN SCREEN:
?
2
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO BESIRED SCREEN:
?
2

ENTER PARAMETERS FOR SIVEN SCREEN:

ENIER RANGE IN BES C
TEMP RATE OF CHANGE IN DEG C/HIN
AID NUMBER OF CYCLES
T
125 5 20

ENTER PARAMETERS FOR BESIRED SCREEN; ENTER ZERO FOR PARAMETER TO BE FOUND:

ENIER RANGE IN BES C
TEMP NATE OF CHANGE IN DEG C/MIN
AID NUMBER OF CYCLES
?
100 3 0

TEST STRENGTH FOR GIVEN SCREEN= 0.6145

PARAMETER IN DESIRED TEMP CYCLING SCREEN= 61.4

*******LEVEL 1******

```
TEMPERATURE CYCLING, LEVEL 1
    THE DEFAULT VALUES ARE:
    LOBER TEMP=-54 DES C
    UPPER TEMP=71 DEG C
    TEMP. RATE OF CHANGE=5 DE6 C/NIN
    RANGE OF CYCLES TO BE INVESTIGATED=0 TO 20
    IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:
?
0
    ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 1
    IF HODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:
    FIXED TEST COST IN DOLLARS=
10000
    VARIABLE TEST COST IN DOLLARS PER HOUR=
40
    AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=
?
0
    ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=
0
```

********TEST AND PARAMETER SELECTION******

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
 2. CYCLED TEMPERATURE
 3. RANDOM VIBRATION

- 4. SINE SHEEP VIBRATION
 5. SINE FIXED VIBRATION

DEFAULTS ARE:

LEVEL 1 LEVEL 2 LEVEL 3 TEMP. CYCLING RAN.VIB CONST. TEMP. (2) (3) (1)

IF YOU WISH DEFAULT SCREENS ENTER ZERO, IF NOT, ENTER 1:

********LEVEL 3******

```
CONSTANT TENPERATURE, LEVEL 3
    THE DEFAULT VALUES ARE:
    TEMPERATURE=70 DES C
    TIME RANGE TO BE INVESTIGATED=0 TO 48 HOURS
    IF YOU WISH THE DEFAULT VALUES, ENTER ZERO, IF NOT, ENTER 1:
0
    ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 3
    IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:
    FIXED TEST COST IN DOLLARS=
10000
    VARIABLE TEST COST IN DOLLARS PER HOUR=
50
    AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=
1000
    ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=
0
```

********LEYEL 2******

```
RANDON VIBRATION, LEVEL 2
    THE DEFAULT VALUES ARE:
    G-LEVEL=4 &
    RANGE OF TIME TO BE INVESTIGATED-0 TO 10 MIN.
    IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:
0
    ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 2
    IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:
    FIXED TEST COST IN DOLLARS=
10000
    VARIABLE TEST COST IN DOLLARS PER HOUR=
50
    AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT BETECTED AT THIS LEVEL=
500
    ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=
?
0
```

TEST DESCRIPTION PARAMETER VALUE

		P	ARAMETE	R VALUE		
	TYPE	KO. 1	NO. 2	NO. 3	NO. 4	TOTAL COST(
			-			
						11529.
2	CYT	71.00	-54.00	5.00	20.00	11527.
						13094.
3	RUIB	4.00	5.00	4.0	0.0	13094.
-		••••	••••	•••		15341.
1	CT	70.00	48.00	0.0	0.0	15341.
					•	19944.
	2	2 CYT	TYPE NO. 1 2 CYT 71.00 3 RUIB 6.00	TYPE RO. 1 NO. 2 2 CYT 71.00 -54.00 3 RVIB 6.00 5.00	TYPE NO. 1 NO. 2 NO. 3 2 CYT 71.00 -54.00 5.00 3 RVIB 6.00 5.00 0.0	TYPE NO. 1 NO. 2 NO. 3 NO. 4 2 CYT 71.00 -54.00 5.00 20.00 3 RVIB 6.00 5.00 0.0 0.0

INSTANTANEOUS HTBF FOR REMAINING FLAWS AT END OF SCREENING

				ORKMANSHI	P			
PARTS	;	5.	6.	7.	8.	7.	10.	11.
0.	!	1397.	1397.	1397.	1397.	1397.	1396.	1396.
0.	:	1397.	1397.	1397.	1397.	1397.	1396.	1396.
0.	ŧ	131 <i>7</i> .	1317.	1317.	1317.	1317.	1317.	1316.
1.	:	1043.	1043.	1043.	1042.	1042.	1042.	1042.
2.	:	863.	863.	863.	843.	163.	863.	862.
3.	1	736.	736.	734.	736.	736.	736.	736.
4.	1	642.	642.	641.	641.	641.	641.	641.

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER ZERG IF YOU WISH TO ENTER A SMALLER PROBABILITY (FOR A MARROWER INTERVAL) ENTER ONE:

115

ENTER PROBABILITY DESIRED:

.8

IF TOU WISH A TABLE OF INPUTS ENTER 1, IF NOT, ENTER ZERO:

PROGRAM BATA									
MPARTS LEVELS	(PDEF X MPARTS)	CREQI	HTBF	-					
7000 3	7.	40000.00	0.						
ASSENDLY DATA									
ASSEMBLY LEVEL	EXPECTED NUMBI	ER OF ASSEMBLY I	EFECTS	•					
1 2		14. 7.							
2 3		4.							
REBORK COST									
				-					
LEVEL LEVEL	2		45. 500. 1000.						

INTERVAL NTBF

TIME	:	HTBF
2000.	:	1049.
4000.	1	1056.
6000.	:	1062.
8000.	:	1069.
10000.	ľ	1075.
12000.	:	1081.
14000.	ŀ	1087.
16000.	:	1093.
18000.	1	1098.
20000.	:	1104.

```
IF YOU HAVE FALLOUT DATA ENTER 1, IF NOT ENTER ZERO:

O
IF TOU DISH TO ANALYZE EQUIVALENT SCREENS ENTER ONE
IF NOT ENTER ZERO:

O

IF YOU HAVE TIMES TO FAILURE FOR LEVEL III ENTER 1,
IF NOT, EXTER ZERO:
```

O READY

STRESS SCREENING FLOW DIAGRAM

	•				•			
: INCONING	}	: LEVEL 1 :		: LEVEL 2		: LEVEL 3 :		: ONTEOING :
7000	}	:ABEF= :	}	7.8		: 40EF= : 4.1		1.1
IDEFECTS:	:	TS= 1.615		:TS= :		:TS= :		DEF U REN:
	: : :	DEF PASSED		DEF PASSED:		DEF PASSED:		: HTBF: :
	-	; ; V		; ; V		;		
	!			EXPECTED FALLOUT:			!	
		PRT WKW TO: 4. 9. 13.		PRT #K# TO				
		UPPR BND FOI OBS FALLOUT						
		:	1 3	3. 9. 10	; ;		•	
		LOUR BND FO OBS FALLOUT	:: :	OBS FALLOUT	1 1	OBS FALLOUT	1	
		: 1. 4. 7 :	.; ;	0. 1. 2	• • • •	0. 0. 0.	• !	

********TEST AND PARAMETER SELECTION******

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
- 2. CYCLED TEMPERATURE
 3. RANDOM VIBRATION
- 4. SINE SUEEP VIBRATION
 5. SINE FIXED VIBRATION

ENTER YOUR SCREEN SEQUENCE AS PROMPTED USING NUMBERS FROM ABOVE LISTING: IF YOU BO NOT WISH TO SCREEN AT A PARTICULAR LEVEL, ENTER ZERO: FOR LEVEL 1 THE SCREEN NUMBER DESIRED IS: FOR LEVEL 2 THE SCREEN NUMBER DESIRED IS: FOR LEVEL 3 THE SCREEN NUMBER DESIRED IS:

4.3.3 Tradeoff Option Examples

4.3.3.1 Evaluating an Existing Screen. The user has an existing screen and wishes to have the SSM-determine the cost and test strength of that screen. After having evaluated an existing screen, the MTRF Option should be exercised to allow the SSM to determine an optimum screen to achieve the same MTBF. Alternatively, the Cost Option may be exercised to determine what MTBF is achievable for the same cost as the existing screen.

****** SELECTION OF PROGRAM INPUTS AND OPTIONS *******

IF THE MODEL DEFAULT IS DESIRED, ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACNEIVE A GIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTINIZES PRODUCT RELIABILITY SIVEN A FIXED COST
OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

BESIRED SERIES HTBF OF NEW SYSTEM (OPTION A ONLY, FOR OPTIONS B OR CENTER ZERO)

COST BUDGET(OPTION B ONLY, FOR OPTION A OR C ENTER ZERO)

TOTAL PART POPULATION(NO BEFAULT AVAILABLE) ? 5000

0

٥

0 0

0

FAILURE RATES OF 600D PARTS; 600D CONNECTIONS=

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS=

*********EYEL 2******

TEMPERATURE CYCLING, LEVEL 2
ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES:
UPPER TEMP., LOWER TEMP., TEMP. RATE OF CHANGE, NO. OF CYCLES:
(TEMPERATURE RANGE MUST BE WITHIN -55 TO +75 DEG C
AND RATE OF CHANGE BETWEEN 1 AND 20 DEG C/NIN)

. 70 -40 10 12

?

?

?

?

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 2 IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN BOLLARS=

WARIABLE TEST COST IN DOLLARS PER HOUR=

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT BETECTED AT THIS LEVEL=

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

*******LEYEL 1******

CONSTANT TEMPERATURE, LEVEL 1
ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES:
TEMP IN DES C, TIME IN HRS:
(TEMP MUST BE LESS THAN +75 DEG C)

: 70 96

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 1

IF NODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN BOLLARS=

? 0

VARIABLE TEST COST IN DOLLARS PER HOUR=

•

AVERAGE COST IN DOLLARS FOR REPAIR OF BEFECT DETECTED AT THIS LEVEL=

7

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL FARTS=

Ó

PROGRAM DATA

		r r	USKAN PAIA			
PARTS	LEVELS	(PDEF X NPA	RTS) (READ .	ATDF	
5000	3	5.		MA	IA	
		AS:	SEMBLY DATE	1		
SSEMBI	LY LEVEL	EXPECTED	NUMBER OF	SSEIBLY	DEFECTS	*****
1				Α		
				5.		
				••		
		RE	WORK COST			************************************
	LEVEL 1				45.	
	LEVEL 2	!			300.	
	LEVEL 3	I			990.	
		TEST	DESCR	IPTI	: O N	
	1 2 3	SSEMBLY LEVEL 1 2 3 LEVEL 1 LEVEL 2 LEVEL 3	PARTS LEVELS (PDEF X NPA SSEMBLY LEVEL EXPECTED I 1 2 3 RE LEVEL 1 LEVEL 2 LEVEL 3	ASSEMBLY DATA SSEMBLY LEVEL EXPECTED NUMBER OF A SEMBLY LEVEL EXPECTED NUMBER OF A REWORK COST LEVEL 1 LEVEL 2 LEVEL 3	PARTS LEVELS (PBEF X MPARTS) CREAD SOME SEMBLY BATA ASSEMBLY LEVEL EXPECTED NUMBER OF ASSEMBLY 1 10. 2 5. 3 3. REMORK COST TEST DESCRIPTIPARAMETER VALUE	ASSEMBLY DATA ASSEMBLY DATA SSEMBLY LEVEL EXPECTED NUMBER OF ASSEMBLY DEFECTS 1 10. 2 5. 3 3. RENORK COST LEVEL 1 45. LEVEL 2 300. PARAMETER VALUE

		TE	• • •	E S C F Arametei		ION	
TEST SEQUENCE		TYPE				NO. 4	TOTAL COST(6)
I ENEL NO. 1							7000
LEVEL NO. 1 TEST NO.	1	£.T	70.00	9A. 00	8.0	0.8	3092. 3092.
LEVEL NO. 2	•	•	,,,,,	,0.00	***	***	3380.
TEST NO.	2	CYT	70.00	-40.00	10.00	12.00	3380.
LEVEL NO. 3							2751.
TEST NO.	4	SSVB	6.00	20.00	0.0	0.0	2751.

*******LEVEL 3******

SIME SWEEP VIBRATION, LEVEL 3 ENTER IN ORDER, SEPARATED BY COMMAS OR SPACES: 8-LEVEL, TIME IN MIN: (G LEVEL BETWEEN 0 AND 10)

. 6 20

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 3

IF MODEL DEFAULTS ARE DESIREP FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN DOLLARS=

: 0

VARIABLE TEST COST IN DOLLARS PER HOUR=

7

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

?

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

?

IF YOU WISH A TABLE OF INPUTS ENTER 1, IF NOT, ENTER ZERO:

STRESS SCREENING FLOW DIAGRAM

: INCOMINS :	LEVEL 1	: LEVEL 2 :	: LEVEL 3 :	: OUTGOING :
#PARTS:	ADEF	ADEF=	ADEF =	DEF P REM:
#BEFECTS:	:TS=	:TS= :	TS= 0.381	IBEF U REN:
	DEF PASSED:	DEF PASSED:	DEF PASSED:	MTBF:
	; ;	; ; v	 	
		: EXPECTED : FALLOUT:	EXPECTED :	
		PRT UKN TOT:	• • • • • • • • • • • • • • • • • • • •	
		UPPR BND FOR:		
	1	7. 18. 21.	1	
	OBS FALLOUT:	LOUR BND FOR: OBS FALLOUT: 	IOBS FALLOUT:	
	i 0. 0. 0.;	1 0. 1. 2.1	: 0. 0. 0.:	

INTERVAL NTBF

TIME	1	ATBF					
2000. 4000. 6000.	ŀ	1564. 1573. 1582.					
8000. 10000.	:	1591. 1599.					
12000. 14000. 16000.	!	1607. 1615. 1623.					
18000. 20000.	:	1430					
125							

INSTANTANEOUS NTBF FOR REMAINING FLANS AT END OF SCREENING

PARTS :	1.	2.	3.	4.	5.	6.	7.
0. :	1957.	1957.	1957.	1956.	1956.	1955.	1955.
0. :	1957.	1957.	1957.	1954.	1956.	1955.	1955.
0. :	1957.	1957.	1957.	1956.	1956.	1955.	1955.
1. :	1556.	1555.	1555.	1555.	1555.	1554.	1554.
2. :	1187.	1184.	1186.	1186.	1186.	1186.	1184.
3. :	959.	959.	959.	959.	159.	959.	951.
4. 1	805.	805.	805.	205.	805.	804.	804.

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER ZERO
IF YOU WISH TO ENTER A SHALLER PROBABILITY (FOR A MARROWER INTERVAL)
ENTER ONE:

:

IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO: ?

FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:

- 1. CONSTANT TEMPERATURE
- 2. TEMPERATURE CYCLING
- 3. RANDOM VIBRATION
- 4. SINE SWEEP VIBRATION
- 5. SINE FIXED VIBRATION

ENIER NUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN SCREEN:

2
ENIER NUMBER FROM ABOVE LIST CORRESPONDING TO BESIRED SCREEN:

?

ENIER PARAMETERS FOR SIVEN SCREEN:

ENTER RANGE IN DEG C
TEMP RATE OF CHANGE IN DEG C/MIN
AND NUMBER OF CYCLES
?
110 10 12

ENTER PARAMETERS FOR DESIRED SCREEN; EITER ZERO FOR PARAMETER TO DE FOUND:

ENTER RANGE IN DEG C
TEMP MATE OF CHANGE IN DEG C/MIN
AND NUMBER OF CYCLES
?
100 5 0

TEST STRENGTH FOR GIVEN SCREEN= 0.6887

PARAMETER IN DESTRED TEMP CYCLING SCREEN= 43.8

```
IF YOU HAVE FALLOUT DATA ENTER 1, IF NOT ENTER ZERO:
7
IF YOU WISH TO ANALYZE EQUIVALENT SCREENS ENTER ONE
IF NOT ENTER ZERO:
1
FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:
1. CONSTANT TEMPERATURE
2. TEMPERATURE CYCLING
3. RANDON VIBRATION
4. SINE SUEEP VIBRATION
5. SINE FIXED VIBRATION
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN SCREEN:
ENIER NUMBER FROM ABOVE LIST CORRESPONDING TO DESIRED SCREEN:
2
ENTER PARAMETERS FOR GIVEN SCREEN:
ENIER ABSOLUTE VALUE OF DIFFERENCE BETWEEN TEMP IN DEG C AND 25 DEG C
 AND TIME IN HOURS
45 96
ENTER PARAMETERS FOR DESIRED SCREEN;
 ENTER ZERO FOR PARAMETER TO BE FOUND:
ENTER RANGE IN DES C
 TIMP RATE OF CHANGE IN DEG C/HIN
 AND NUMBER OF CYCLES
100 5 0
TEST STRENGTH FOR GIVEN SCREEN= 0.3143
```

3.4

PARAMETER IN BESIRED TEMP CYCLING SCREEN=

```
IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO:
FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:
1. CONSTANT TEMPERATURE
2. TEMPERATURE CYCLING
3. RANDON VIBRATION
4. SIME SMEEP VIDRATION
5. SINE FIXED VIBRATION
ENIER MUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN SCREEN:
ENIER WINBER FROM ABOVE LIST CORRESPONDING TO DESIRED SCREEN:
3
ENTER PARAMETERS FOR SIVEN SCREEN:
ENTER & LEVEL AND TIME IN MINUTES
6 20
ENTER PARAMETERS FOR DESIRED SCREEN;
 EITER ZERO FOR PARAMETER TO BE FOUND:
ENTER G LEVEL AND TIME IN MINUTES
5 0
TEIT STRENGTH FOR GIVEN SCREEN= 0.3814
PARAMETER FOR DESIRED VIBRATION SCREEN=
                                        4.3
IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO:
?
0
 IF YOU HAVE TIMES TO FAILURE FOR LEVEL III ENTER 1.
 IF NOT, ENTER ZERO:
```

O READY

```
IF YOU WISH ANOTHER EQUIVALENCY ENTER ONE, IF NOT, ENTER ZERO:
```

FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE:

- 1. CONSTANT TEMPERATURE
- 2. TEMPERATURE CYCLING
- 3. RANDOM VIBRATION
- 4. SINE SHEEP VIBRATION
- 5. SINE FIXED VIBRATION

ENIER NUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN SCREEN:

4
ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO DESIRED SCREEN:

7
3

ENIER PARAMETERS FOR GIVEN SCREEN:

ENTER & LEVEL AND TIME IN MINUTES ? 6 20

ENTER PARAMETERS FOR DESIRED SCREEN; ENTER ZERO FOR PARAMETER TO BE FOUND:

ENTER G LEVEL AND TIME IN HINUTES ? 0 15

TEST STRENGTH FOR GIVEN SCREEN= 0.3814
SOLUTION CANNOT BE FOUND BY INTERNAL METHOD.
TRY A GRID OF POSSIBLE SOLUTIONS.

********TEST AND PARAMETER SELECTION******

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
- 2. CYCLED TEMPERATURE
- 3. RANDON VIBRATION
- 4. SINE SWEEP VIBRATION
- 5. SINE FIXED VIBRATION

ENTER YOUR SCREEN SEQUENCE AS PRONPTED USING NUMBERS FROM ABOVE LISTING:

IF YOU DO NOT WISH TO SCREEN AT A PARTICULAR LEVEL, ENTER ZERO:

FOR LEVEL 1 THE SCREEN NUMBER DESIRED IS:

?

4

FOR LEVEL 2 THE SCREEN NUMBER DESIRED IS:

?

1

Adapting Screens Based on Observed Results. In this example, the user has actual screen data which falls outside the bounds of the selected probability interval. Note on the Stress Screening Flow Diagram at level 2 that the expected number of workmanship defects is 8, with an 80 percent probability interval of 3 to 12. The actual number of workmanship defects observed is 2 which is entered into the SSM. A new screening strength is computed (0.158) based on observed results and an increase in vibration time from 20 minutes to 60 minutes is recommended to achieve the desired screening strength.

****** SELECTION OF PROGRAM INPUTS AND OPTIONS *******

IF THE MODEL BEFAULT IS DESIRED. ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A GIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTINIZES PRODUCT RELIABILITY SIVEN A FIXED COST

OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

BESIRED SERIES MIDF OF NEW SYSTEM (OPTION A ONLY, FOR OPTIONS B OR CENTER ZERO)

?

COST BUDGET(OPTION B ONLY, FOR OPTION A OR C ENTER ZERO)

?

TOTAL PART POPULATION(NO DEFAULT AVAILABLE)

9000

FAILURE RATES OF SOOD PARTS; SOOD CONNECTIONS:

0 0

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS:

*******LEVEL 2******

SIME SUEEP VIBRATION, LEVEL 2
ENTER IN ORBER, SEPARATED BY COMMAS OR SPACES:
6-LEVEL, TIME IN NIN:
(G LEVEL BETWEEN 0 AND 10)

6 20

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 2

IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN BOLLARS=

20000

VARIABLE TEST COST IN DOLLARS PER HOUR=

? 50

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

?

500 ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

?

*******LEVEL |******

TEMPERATURE CYCLING, LEVEL 1
ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES:
UPPER TEMP., LOWER TEMP., TEMP. RATE OF CHANGE, NO. OF CYCLES:
(TEMPERATURE RANGE MUST BE WITHIN -55 TO +75 DES C
AND RATE OF CHANGE BETWEEN 1 AND 20 DES C/NIN)

70 -40 4 8

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 1

IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN BOLLARS=

10000

VARIABLE TEST COST IN DOLLARS PER HOUR=

? 40

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

? 50

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

PROGRAM DATA

MPA	RTS	LEVELS	(PBEF Y	MPARTS)	CREQD	ATBF
90	00	3		7.	NA	MA

ASSEMBLY DATA

ASSEMBLY LEVEL	EXPECTED NUMBER OF ASSEMBLY DEFECTS

1	18.
2	9.
3	5.

REWORK COST

LEVEL	1	50.
LEVEL	2	501.
LEVEL	3	1000.

T E				I 0 N	
TYPE	NO. 1	NO. 2	NO. 3	NO. 4	TOTAL COST(\$)
					10962.
CYT	70.00	-40.00	4.00	8.00	10962.
					24856.
SSVB	6.00	20.00	0.0	0.0	24854.
					37921.
CT	75.0€	48.00	0.0	0.0	37922.
	1 2	·			73740.
	CYT	TYPE NO. 1 CYT 70.00 SSUB 6.00 CT 75.00	PARAMETER TYPE NO. 1 NO. 2 CYT 70.00 -40.00 SSVB 6.00 20.00	PARAMETER VALUE TYPE NO. 1 NO. 2 NO. 3 CYT 70.00 -40.00 4.00 SSUB 6.00 20.00 0.0 CT 75.00 48.00 0.0	PARAMETER VALUE TYPE NO. 1 NO. 2 NO. 3 NO. 4 CYT 70.00 -40.00 4.00 8.00 SSVB 6.00 20.00 0.0 0.0 CT 75.00 48.00 0.0 0.0

1

*********EYEL 3*******

CONSTANT TEMPERATURE, LEVEL 3
ENTER, IN ORDER, SEPARATED BY COMMAC OR SPACES:
TEMP IN DEG C, TIME IN HRS:
(TEMP MUST BE LESS THAN +75 DEG C)

. 75 48

ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LETEL 3
IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:

FIXED TEST COST IN BOLLARS=

. 30000

VARIABLE TEST COST IN DOLLARS PER HOUR=

. 60

AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=

? 1000

ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

?

IF YOU WISH A TABLE OF INPUTS ENTER 1, IF NOT, ENTER ZERO:

1

STRESS SCREENING FLOW DIAGRAM

: INCOMING	- !	: LEVEL 1		LEVEL 2	:	: LEVEL 3	- !	: OUTGOING :
		: ADEF=						DEF P REH:
9000	i !)	i 18.	: !>			i 5.		
#DEFECTS:		:TS=				: TS=		DEF W REN:
9.	!	0.394	}	0.381	!	1 0.250	:	13.
•	•	: :DEF PASSED	 	; !DEE DACCED	;	: !BEC BASSED!	; ,	i i
) 	16.				1 15.		701.
	1	•	}	:	:	1		
	•		•		-		•	
		•		; !		į		
		Ü		ÿ		ÿ		
			-					
	:	EXPECTED	: :	EXPECTED	: :	EXPECTED	:	
		FALLOUT:	1 !	FALLOUT:	1 1	FALLOUT:	!	
	į	PPT UKM IN		DET UKM TO	 	PRT EKN TOT	;	
	;					0. 5. 5.		
	:		: :		: :		:	
	-	UPPR BND FOI OBS FALLOUT:					• •	
	i	OPO T NEEDOT.	1	UDO TRECOGT		000 1 4220011	:	
	:	6. 12. 16.	1 1	5. 12. 15	.: :	0. 9. 9.	. :	
	:	LOUR BND FOR	; ;				:	
		OBS FALLOUT:						
	i					, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
	:	0. 3. 6.	: :	0. 3. 5.	.: :	0. 1. 1.	. 1	
	:		: :		: :		:	

INSTANTAMEDUS NTBF FOR REMAINING FLAUS AT END OF SCREENING

			U	ORKMANSH 1	P			
PARTS	:	10.	11.	12.	13.	14.	15.	16.
0.	;	1086.	1084.	1086.	1086.	1084.	1086.	1084.
1.	;	974.	974.	974.	973.	973.	973.	973.
2.	ł	815.	815.	815.	815.	815.	815.	815.
3.	ŀ	701.	701.	701.	701.	701.	701.	701.
4.	:	615.	615.	615.	415.	615.	615.	615.
5.	ł	547.	547.	547.	547.	547.	547.	547.
6.	:	493.	493.	493.	493.	493.	493.	493.

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER ZERO IF YOU WISH TO ENTER A SHALLER PROBABILITY (FOR A MARROWER INTERVAL) ENTER ONE:

ENTER PROBABILITY DESIRED:

.8

?

STRESS SCREENING RESULTS:

: INCOMING :	: LEVEL 1 :	: LEVEL 2 :	I LEVEL 3 !	: OUTGOINS :
: WPARTS:	ADEF= 1	IADEF= 1		IDEF P REMI
; 9000;	: 18.1	9.1	: 5.:	; 5.:
: : : : : : : : : : : : : : : : : : :	->; ; !TS= !	-> 15=);	:DEF U REM:
9.1	1 0.3941	0.158		
:	I A BACCERI	I DEE BARCEDI	I AAAAAAA	I I
	1 16.1	idef Passed: : 21.:	19.1	521.1
:	:	1 1	: :	1
	;	. !	!	
	1	•	1	
*	V	y	V	
	1	1	1	
		EXPECTED :		
	: PALLUUIS :	: FALLOUT: :	i PALLUUII i	
		I PRT WKH TOT!		
	1 3. 8. 11.1	0. 4. 4.	1 1. 6. 7.1	
	UPPR BND FOR	UPPR BND FOR	UPPR IND FOR	
	OBS FALLOUTE:	IOBS FALLOUT:	OBS FALLOUT:	•
	6. 12. 16.	0. 8. 8.	; ; 3. 9. 11.!	
	1	1	1	
		!LOWR BND FOR!		
	1	1	1	
	0. 3. 6.	: 0. 1. 1.;	0. 2. 2.	
	· i	· · · · · · · · · · · · · · · · · · ·	· i	

INCREASE TIME ON LEVEL 2 TO 40.00 MINUTES

IF YOU WISH TO ANALYZE EQUIVALENT SCREENS ENTER ONE IF NOT ENTER ZERO: ?

IF YOU HAVE TIMES TO FAILURE FOR LEVEL III ENTER 1, IF NOT, ENTER ZERO:

? O REABY

INTERVAL ATOF

TIME	1	NTOF
2000.	:	709.
4000.	;	717.
6000.	:	725.
8000.	:	733.
10000.	:	740.
12000.	1	748.
14000.	1	755.
16000.	1	762.
18000.		769.
20000.	•	776.

```
IF YOU HAVE FALLOUT DATA ENTER 1, IF NOT ENTER ZERO:

IF YOU HAVE SEPARATE FALLOUT FOR PARTS AND WORKMANSHIP ENTER ONE IF YOU HAVE TOTAL FALLOUT ONLY AT EACH LEVEL, ENTER ZERO:

ENTER, IN ORDER, ACTUAL FALLOUT:
BUE TO (A) PARTS (B) WORKMANSHIP, AS PROMPTED:
FOR LEVEL 1:

FOR LEVEL 2:

FOR LEVEL 3:
```

********TEST AND PARAMETER SELECTION******

FOLLOWING ARE THE AVAILABLE SCREENS :

- 1. CONSTANT TEMPERATURE
- 2. CYCLED TEMPERATURE
- 3. RANDOM VIBRATION
- 4. SINE SUEEP VIBRATION
- 5. SINE FIXED VIBRATION

DEFAULTS ARE:

LEVEL 1 LEVEL 2 LEVEL 3

TEMP. CYCLING RAN.VIB CONST. TEMP.

(2) (3) (1)

IF YOU WISH DEFAULT SCREENS ENTER ZERO, IF NOT, ENTER 1:

?

4.3.4 Example Using the CDE Model to Evaluate Screening Results.

In this example, three levels of screens are used, based on model defaults. The stress screening flow diagram shows an expected fallout of 13 defects at Level 3. The user actually experienced 16 defects and also had times-to-failure for each defect. In this example, the times-to-failure are entered into the SSM and the CDE model is fit to the failure distribution, resulting in estimates for the number of defects entering the Level 3 screen and the screening strength at that level. In this example, the estimated number of defects is unchanged, (33), but the screening strength estimate is revised upward to 0.521 from 0.382.

EX SSM

***** SELECTION OF PROGRAM INPUTS AND OPTIONS ******

IF THE MODEL BEFAULT IS DESIRED, ENTER ZERO:

OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A GIVEN PRODUCT RELIABILITY REQUIREMENT

OPTION B OPTIMIZES PRODUCT RELIABILITY GIVEN A FIXED COST OPTION C COMPUTES TEST STRENGTHS OF EXISTING SCREENS

DESIRED SERIES HTBF OF NEW SYSTEM (OPTION & ONLY, FOR OPTIONS B OR C ENTER ZERO)

600

TOTAL PART POPULATION(NO BEFAULT AVAILABLE)
?
20000

FAILURE RATES OF 600D PARTS; 600D CONNECTIONS:

0 0

4

PART QUALITY DEFECTS AS A FRACTION OF TOTAL PARTS=

0

*******LEYEL 2******

?

?

? 0

0

0

RANDON VIBRATION, LEVEL 2 THE DEFAULT VALUES ARE: 6-LEVEL=6 G RANGE OF TIME TO BE INVESTIGATED=0 TO 10 NIN. IF YOU WISH THE DEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1: 0 ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 2 IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO: FIXED TEST COST IN DOLLARS= 30000 VARIABLE TEST COST IN DOLLARS PER HOUR= AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL= ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=

*******LEYEL 1******

```
TEMPERATURE CYCLING, LEVEL 1
    THE DEFAULT VALUES ARE:
    LOVER TEMP=-54 DES C
    UPPER TEMP=71 DEG C
    TEMP. RATE OF CHANGE=5 DE6 C/NIN
    RANGE OF CYCLES TO BE INVESTIGATED=0 TO 20
    IF YOU WISH THE BEFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:
0
    ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 1
    IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO:
    FIXED TEST COST IN BOLLARS=
20000
    VARIABLE TEST COST IN DOLLARS PER HOUR=
    AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT DETECTED AT THIS LEVEL=
0
    ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS=
0
```

PROSRAM DATA

NPARTS	LEVELS	(PDEF X NPARTS)	CREAD	HIBF
20400	3	20.	0.0	400.
·		ASSEMBLY	DATA	
ASSENBI	Y LEVEL	EXPECTED NUMBER	OF ASSEMBLY I	DEFECTS
1			40. 20.	
2 3			10.	
		REWORK C	os1 	
	TEAET 3	?		45. 300. 990.
REDUIREMENT CAN MTBF POSSIBLE= MTBF REQUIRED=		2.9		

*******LEVEL 3******

CONSTANT TEMPERATURE, LEVEL 3 THE BEFAULT VALUES ARE: TEMPERATURE=70 DES C TIME RANGE TO BE INVESTIGATED=0 TO 48 HOURS IF YOU WISH THE DEFAULT VALUES, ENTER ZERO, IF NOT, ENTER 1: ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES: TEMP IN DEG C, TIME IN HRS: (TEMP MUST BE LESS THAM +75 DES C) 70 160 ENTER THE FOLLOWING MANUFACTURING PROCESS DATA, LEVEL 3 IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM, ENTER ZERO: FIXED TEST COST IN DOLLARS= 0 VARIABLE TEST COST IN DOLLARS PER HOUR= AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT BETECTED AT THIS LEVEL= 0 ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION OF TOTAL PARTS= 0 IF YOU WISH A TABLE OF INPUTS ENTER 1, IF NOT, ENTER ZERO:

INSTANTANEOUS ATBF FOR REMAINING FLAUS AT END OF SCREENING

			u	ORKMANSHI	P			
PARTS	÷	15.	14.	17.	18.	19.	20.	21.
0.	;	489.	489.	489.	489.	489.	489.	489.
0.	:	489.	489.	489.	489.	489.	489.	489.
1.	:	446.	445.	445.	445.	445.	445.	445.
2.	:	409.	409.	407.	409.	409.	409.	409.
3.	•	378.	378.	378.	378.	378.	378.	378.
4.		352.	352.	352.	352.	352.	352.	352.
5.	:	328.	328.	328.	328.	328.	328.	328.

IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER ZERO IF YOU WISH TO ENTER A SMALLER PROBABILITY (FOR A MARROWER INTERVAL) ENTER ONE:

0

TEST DESCRIPTION PARAMETER VALUE

			Pi	ARAMETE	R VALUE		
TEST SEQUENCE	E 	TYPE	NO. 1	NO. 2	NG. 3	#0. 4	TOTAL COST(\$
LEVEL NO. 1							22371.
TEST NO.	2	CYT	71.00	-54.00	5.00	20.00	22371.
LEVEL NO. 2							36031.
TEST NO.	3	RVIB	6.00	7.50	0.0	0.0	36031.
LEVEL NO. 3							17283.
TEST NO.	1	CT	70.00	160.00	•.0	0.0	17283.
TOTAL COST		*****				•	75684.

INTERVAL MIBF

TIME :	MTBF
2000.;	393.
4000. ;	395.
6000. :	397.
8000. :	399.
10000. :	401.
12000. :	403.
14000. :	404.
16000. :	406.
18000. :	407.
20000. ;	409.

STRESS SCREENING FLOW DIAGRAM

	•				. 007207112
· INCUMING (•	i	: LEVEL 2 :	i LEVEL 3 i	: 001901M8 :
: #PARTS:)	:ADEF= :	:ADEF= :	:ADEF= :	IDEF P REMI!
20000		40.:	20.	10.1	3.1
	>	: ; -: :TS= :	->:);	·>:
			0.4661		
	}	;	1	:	1
	,	IDEF PASSED:	:DEF PASSED: : 23.:		
	}	: 23	23.1	20.:	392.
	•			~	
		;	:	:	
		:	; ,,	i	
	_	V	v	y	
	;	:	1	: :	
	;			: EXPECTED :	
	;	FALLOUT: :	: FALLOUT: :	: FALLOUT: :	
	:	PRT UKH TOI!	PRI WKW TOT:	! PRT UKM TOT!	
	:		: 3. 17. 20.:	• • • • • • • • • • • • • • • • • • • •	
		:		1	
	-	• • • • • • • • • • • • • • • • • • • •	:UPPR BND FOR:		
	:	UBS PHEEDUIT.	: :	1 PACTORIA	
	1	23. 40. 55.	9. 30. 33.	5. 22. 24.	
	;	LOUR BND FOR:	LOUR BND FOR	LOWR BND FOR	
	1	OBS FALLOUT::	OBS FALLOUT:	: OBS FALLOUT::	
	;	7 19 21 1	; 0. 6. 9.;		
		. J. 12. 21.i	1 0. 0. 7.1	; v. 3. 4.;	

REFERENCES

- 1. R. E. Schafer, L. E. James, et al. "Electronic Equipment Screening and Debugging Techniques", Hughes Aircraft Company, Ground Systems Group, Fullerton, CA., RADC-TR-78-55, March 1978. AD# A053 561.
- 2. C. M. Ryerson, "Summary of Math Models for Reliability Screening and Related Product Assurance", Hughes Aircraft Company, Culver City, CA., Report No. FR-80-04-636, February 1980.
- 2. C. M. Ryerson, "Principles of Screening and Cost Effective Product Assurance", Hughes Aircraft Company, El Segundo, CA., Report No. FR-79-04-1191, November 1979.
- 4. C. M. Ryerson, "Reliability CREDIT", Hughes Aircraft Company, Culver City, CA., Report No. TIC 20-42-732, May 1973.
- D. Edgerton Jr., "Stress Screening Studies", Hughes Aircraft Company, Canoga Park, CA., Report No. TIC 5150.76/501, June 1976.
- 6. R. L. Baker, T. Drnas, "Stress Screening Experiment, Phase One", Hughes Aircraft Company, Culver City, CA., Report No. P76-385, October 1976.
- 7. R. W. Burrows, "Long Life Assurance Study for Manned Spacecraft Long Life Hardware", Vols. 1-5, Martin Micrietta Corporation, Denver, Colorado, December 1972.
- 8. F. Kube, G. Hirschberger, "An Investigation to Determine Effective Equipment Environmental Acceptance Test Methods", Grumman Aerospace Corporation, Report No., ADR 14-04-73.2, April 1973.
- 9. "Navy Manufacturing Screening Program", NAVMAT P-9492, May 1979.

```
IF YOU HAVE FALLOUT NUMBERS ENTER 1, IF NOT, ENTER ZERO:
0
    IF YOU WISH TO ANALYZE EQUIVALENT SCREENS ENTER ONE
    IF NOT, ENTER ZERO:
0
    IF YOU HAVE TIMES TO FAILURE FOR LEVEL III ENTER 1,
    IF NOT, ENTER ZERO:
1
    ENTER NUMBER OF FAILURES DURING FINAL SCREEN:
7
16
    ENTER FAILURE TIMES (NOURS), IN ORDER, AS PROMPTED:
?
8
?
14
?
20
7
27
?
34
41
54
61
68
77
86
96
107
118
129
141
    THE FAILURE TIMES INDICATE THAT THE ESTIMATED NUMBER
     OF DEFECTIVES ENTERING THE SCREEN IS
      AND THE ESTIMATED SCREENING STRENGTH 1S 0.521.
```

READY

- W. Silver, "Proposed Recommended Practices in Applying Broadband Vibration Screening to Electronic Hardware", Westinghouse Electric Corporation, Baltimore, Md., The Journal of Environmental Sciences, pp. 9-11, Jan.-Feb. 1981.
- 21. A. Bezat, L. Montague, "The Effect of Endless Burn-in on Reliability Growth Projections", Proceedings of the 1979 Annual Reliability and Maintainability Symposium, pp. 392-397.
- 22. K. W. Fertig, V. K. Murthy, "Models for Reliability Growth During Burn-in: Theory and Applications", Proceedings of the 1973 annual Reliability and Maintainability Symposium, pp. 504-509.

- 10. C. M. Ryerson, "Relating Factory Test Failure Results to Field Reliability, Required Field Maintenance, and to Total Life Cycle Costs", Hughes Aircraft Company, Culver City, CA., Report No. TIC 72-05, June 1972.
- J. R. Anderson, "Environmental Burn-in Effectiveness", McDonnell Aircraft Company, St. Louis, Mo., Report No. AFWAL TR-80-3086, August 1980.
- 12. "Environmental Stress Screening Guidelines", The Institute of Environmental Sciences, Library of Congress", Catalog Card No. 62-38584, 1981.
- 13. L. E. James et al, "Microcircuit Cost Factors", Hughes Aircraft Company, Fullerton, CA., Report No. FR 81-16-326, February 1981.
- 14. "Optimum Burn-in Determination", Tracor Sciences and Systems, Arlington, VA., Document No. 9229, November 1979.
- 15. P. L. Shove, "The Effect of Screening and Burn-in on Electronic Reliability", Admiralty Surface Weapons Establishment (UK), Report No. TR-72-46, (AD915959), November 1972.
- 16. C. S. Murphy, "A Guide-line Document for Early Life Failure Screening Procedures on GW Equipment", Sperry Gyroscope (UK), Report No. TR 591, September 1977.
- 17. C. M. Ryerson, "Principles of Manufacturing Data Management", Hughes Aircraft Company, Report No. FR 81-01-812, May 1981.
- 18. C. M. Ryerson, "Card Level Acceptance Testing", Hughes Aircraft Co., Paper presented at 6th Aerospace Testing Seminar, Los Angeles, March 1981.
- 19. K. L. Wong, "Unified Field (Failure) Theory-Demise of the Bathtub Curve", Hughes Aircraft Company, Proceedings of the 1981 Annual Reliability and Maintainability Symposium, pp. 402-406.

.....

The values shown in Table A.2 were obtained.

Table A.2 Screening Strength Constants for Data Taken from Raw Data.

		Constant	
G Level	В	С	D
1	6.006	.500	.201
2	4.004	.500	.401
3	3.003	.770	.401
4	2.279	.268	.720
5 \	4.004	.500	.801
6	2.697	.551	.751

A.1.3 <u>Single Model Based on Averaged Table Data</u>. Since C = .500 occurred frequently, SAS NLIN programs were run with C fixed at .500. The resulting B and D values were nearly linear as functions of g. The lines

B = -.375 g + 5.047

D = .0863 g + .273

were fitted by use of SAS.

A.1.4 First Model Based on Weighted Averages of Table Data. In the Grumman tests there were 19 detectable type I faults and 12 detectable type II faults. It was therefore decided to weight the averages of the individual percents of detected faults by using factors of 19/31 and 12/31, respectively.

Since the graph of time versus screening strength for 5 g vibration level was somewhat different in shape than the graphs for other g levels and since 1g and 2g are relatively low, the values were found for 3, 4, and 6 g.

APPENDIX A

DEVELOPMENT OF SCREENING STRENGTH EQUATIONS

- A.1 Screening Strength Model for Random Vibration. Below are the steps used to obtain a single model for the screening strength of random vibration tests. Report ADR 14-04-73.2 by the Grumman Aerospace Corporation (Grumman Report, Ref. 8) supplied the raw data for the model.
- A.1.1 Models Fitted to Data Taken from Graphs in Grumman Report. First, approximately fifteen ordered pairs (t, SS) were read for each of the 4 and 6 g vibration levels from the graphs. Type I and type II faults were averaged within each g level. The two resultant curves were analyzed and a model of the form

SS = D
$$(1 - \exp(-t^C/B))$$
.
B, C, D constants

was chosen for further analysis. The SAS NLIN program was used to find the best values of B, C, and D. The following constants were obtained and very good fit was exhibited.

Table A.1. Screening Strength Constants for Data Taken from Graphs.

	G-L	G-Level			
Constant	4 g	6 g			
В	6.557	5.302			
С	.935	.806			
D	.496	.728			

A.1.2 Models Fitted to Data Taken from Tables and Averaged. Since the Grumman report did not indicate how the screening strength curves were obtained from the raw data it was decided to fit a model to the data from Tables 6 and 7. Due to randomness, some of this data was not increasing with g. Wherever this occurred, an average failure value was used for both g levels. Also, the average values 2.5, 7.5, 17.5, and 42.5 were taken for t, time.

Again, SAS NLIN was used for fitting

Preceding page blank

155

was monotone increasing with g.

A.1.5 Final Model Based on Weighted Averages of Table Data. Due to experience with the nonweighted averages, C was fixed at .500 and SAS NLIN was used to find the best corresponding values of B and D for 3, 4, and 6 g. As before, these values were nearly linear as functions of g. The lines

B = .266 g + 1.402

D = .144 g - .0862

were fitted using SAS.

Table A.5 Comparison of Single Model with Weighted Average Table Data.

g level	Time, In Minutes					
16461	2.5	7.5	17.5	42.5		
3	#1177 #2210	.246	.294	.328		
4	#1232 #2258	.328	.400	.455 .452		
6	#1319 #2307	.466 .452	.585 .613	.689 .677		

#1. Model value.

#2. Weighted average of table data.

A.2 Screening Strength Model for Swept Sine Vibration. Data was obtained from tables 3 and 4 of the Grumman Report. Since there were 19 detectable type I faults and 20 detectable type II faults, a weighted average was used for screening strength at each value of g and t. Average times were also taken. This averaged table data follows in Table A.7 where it is compared to screening strength values from the models for individual g levels and the single model which has parameters time (t) and g levels.

The values for constants for B, C, and D were computed with SAS NLIN when SS was fitted to the table data for swept sine. They were used for computation of the individual model data in Table A.7 Constant values are shown in Table A.8.

Following are comparisons of this model with the averaged table data.

Table A.3. Comparison of Single Model with Table Data.

g level	Time, in minutes					
	2.5	7.5	17.5	42.5		
1	#1: .103	.159	.213	.270		
	#2: .042	.042	.084	.167		
2	#1: .137	.210	.277	.348		
	#2: .167	.250	.250	.292		
3	#1: .177	.267	.349	.431		
	#2: .271	.292	.355	.428		
4	#1: .222 #2: .311	.333	.428 .445	.520 .501		
5	#1: .277	.407	.516	.614		
	#2: .311	.375	.465	.627		
6	#1: .342	.494	.614	.714		
	#2: .350	.493	.638	.706		

#1: SS = D (1 - exp (-t^C/B))
#2: averaged table data.

Screening Strength Constants for Data from Tables Using Weighted Average. Table A.4.

		Constant	
g level	В	C	ם
3	3.003	.500	.401
4	2.536	.240	.711
6	3.244	.€21	.712

 $SS = D (1 - exp (-t^{C}/B))$

Parabolas were fitted through the B and C values as functions of g level. A half parabola was estimated through the D values. This approach did not yield an SS model which

Table A.7 Comparison of Table Data with Single and Individual Models.

	Time, in minutes				
g lev	el	2.5	7.5	17.5	42.5
1.5	Table	.0	.077	.180	.231
	Single Model	.051	.102	.151	.190
	Individual Model	.057	.113	.167	.208
3.0	Table	.077	.128	.205	.256
	Single Model	.075	.150	.222	.280
	Individual Model	.068	.136	.203	.256
5.0	Table	.103	.205	.359	.538
	Single Model	.107	.213	.317	.398
	Individual Model	.178	.356	.530	.668
10.0	Table	.154	.385	.564	.692
	Single Model	.185	.370	.551	.695
	Individual Model	.186	.372	.554	.698

Single Model:

SS = D
$$(1 - exp (-t^c/B)$$

C = .800

$$B(g) = .0176 g + 7.097$$

$$D(g) = .0635 g + .1065$$

"Compute.fort" was run to compare the resulting single model to individual model and table data. See Table A.7.

Table A.6 Comparisons of Single Model with Models Fitted for Individual g Levels.

g		Time, In Minutes						
level	10	15	20	30	40	50		
3	#1: .261 #2: .264	.291	.311	.336	.352	.363		
4	#1: .353 #2: .354	.577 .3×8	.395	.420	.438	.452		
6	#1: .516 #2: .507	.576 .564	.614	.656 .652	.678 .670	.691 .704		

#1: Models fitted for each g level.

#2: Single model:

Note that the values on the charts correspond closely and that the single model exhibits other desired properties. SS is monotone increasing in t and 0<D<1, t>o, C>0, B>0.

But 0 < D < 1 for $.6 \le g \le 7.5$. (.5986... < g < 7.543...) and B > 0 for g > 0.

The final screening strength model is,

SS = D (1 - exp (t.
$$^{5}/B$$
)), t>0
B = .266 g + 1.402, 0.6 < g < 7.5
D = .144 g - .0862

Due to experience with other SS functions, C was fixed at .8 and SAS NLIN was run again. See Table A.9

It appeared that the 5 g constants were aberrant so lines were fitted to the remaining values of B and D as functions of g. These were

$$B(g) = .0176 g + 7.097$$

$$D(g) = .0635 g + .1065$$

A.3 Screening Strength Model for Sine Fixed Frequency Vibration. Raw data was obtained from Table 5 and Figure 9 of the Grumman Report. In the case where table data exhibited non-monotonicity (reversals) in g, the average was taken and used for both values. There were 19 detectable type I faults and 20 detectable type II faults so a weighted average was used. Average times were also taken. This averaged table data follows in Table A.10 where it is compared to screening strength values from the single model for various g levels and the models for individual g levels.

Table A.10 Comparison of Table Data, Single Model, and Individual Models for Sine Fixed Frequency.

	Time, Minutes				
1e\	3 /el	2.5	7.5	17.5	42.5
1.5	Table	.0	.0	.0	.0
	Single Model	.054	.066	.077	.090
3.0	Table	.0	.051	.103	.103
	Single Model	.068	.084	.097	.113
	Individual Model	.051	.063	.073	.086
5.0	Table	.128	.154	.154	.154
	Single Model	.091	.111	.129	.150
	Individual Model	.109	.133	.154	.179
5.6	Table	.154	.205	.231	.231
	Single Model	.112	.136	.157	.183
	Individual Model	.156	.187	.215	.247
10.0	Table	.154	.179	.256	.282
	Single Model	.180	.217	.250	.288
	Individual Model	.171	.207	.240	.276
12.0	Table	.230	.230	.286	.336
	Single Model	.240	.288	.329	.376
	Individual Model	.208	.250	.287	.329

Single Model:

$$SS = D (1 - exp (-t^{C}/B)$$

B = -.4187g + 8.620

D = .04354g + .3235 C = .200

Table A.8 Values for Constants for Individual Models at Four g-Levels.

g Level	В	С	D
1.5	7.007	.800	.221
3.0	8.809	.600	.401
5.0	14.242	.789	.727
10.0	9.064	.954	.703

Table A.9 Constants for B and D with Fixed at .800:

g	В	D
1.5	7.007	.221
3.0	7.2917	.2734
5.0	14.253	.7127
10.0	7.248	.745

The single model

SS = D
$$(1 - \exp(-t^{C}/B)$$

C = .800

B = .0176 g + 7.097

D = .0635 g + .1065

was selected for 0 < t < 60.0 and 0 < g < 12.0.

SS is monotone increasing in t for positive B, C, and D. C is always positive. B and D are positive for positive g. Also, 0 < D < 1 for g < 12.0.

Lines were fitted through B and D as functions of g. They are:

$$B = .4187g 8.620$$

$$D - .04354g + .3235$$

The single model for sine fixed frequency,

SS - D
$$(1 - \exp(-t^{C}/B))$$

C = .200

B = .419g + 8.620

D = .0435g + .324

t>0 and 0 < g < 15.5 was selected. SS is monotone increasing in t for positive B, C, and D. C is always positive. D is positive for positive g. B is positive for 0 g 15.5. B is monotone decreasing in g so 1 - exp $(-t^C/B)$ is monotone increasing in g. Thus, with D also increasing in g, SS is increasing in g. Also, 0 < D < 1 for 0 < g < 15.5.

A.4 <u>Screening Strength Models for Temperature Screens.</u>
Following is a description of the method used to obtain the screening strength equations for temperature screens. The temperature equation is an adaptation of it.




Figure A-1. Cycles as a Function of Equipment Complexity (Ref NAVMAT P-9492)

The values for constants for B, C, and D were computed by SAS NLIN when SS was fitted to the table data. The values are shown in Table A.11. They were used for the computation of the individual model data on Table A.10.

Table A.11. Values for Constants for Individual Models at Five g-Levels.

g level	В	С	D
3.0	7.007	.440	.201
5.0	6.006	.200	.601
6.5	4.004	.200	.601
10.0	5.005	.200	.801
12.0	4.004	.200	.801

Since C = .200 occurred frequently, C was fixed at .200 and the program run again on the 3g data. Fixing C at .200 yielded the constants

B = 8.800 and D = .401

for the 3g individual model. Thus for C = .200 the constants are:

Table A.12. Values for B and D with C Fixed at 0.200.

g	В	D
3.0	8.800	.401
5.0	6.006	.601
6.5	4.004	.601
10.0	5.005	.801
12.0	4.004	.801

C/minute or less and temperature extremes within -55 deg. C to + 75 deg. C.

Only slight modifications are necessary to adapt the SS equation for temperature cycling to constant temperature. For constant temperature DT becomes 1.0 and Ncy = 0.0. Replacing Ncy is $T = (time\ in\ hours)$ also to the 0.5 power. The range is computed from 25 deg. C.

The revised model gives reasonable solutions for its wide range of valid input parameters, exhibits consistency for constant temperature and temperature cycling, and is of the same general form as previously accepted test strength equations without exhibiting their inconsistencies. Figures 1.5 and 1.6 show the screening strengths for the temperature equations.

For the initial analysis, data was obtained from the temperature cycling curves of NAVMAT P-9492, shown above as Figure A.1. Comparisons of areas under the curves, reductions of failure rates, and other forms of analysis were used to obtain data points. The widely used 5 deg. C/minute rate of temperature change and 100 deg. C temperature range were assumed.

An exponential function was fit to the data. However, examination of a grid of screening strength values computed using this equation for typical ranges of the input parameters indicated that the computed screening strengths were higher than generally accepted test strengths.

Following extensive analysis, a set of subjective, but widely acceptable, screening strength values was fixed for 10 deg. C to 110 deg. C, range from 2 to 18 deg. C/minute temperature rate of change, and 5, 10, and 20 cycles. Curves were sketched through the set of points and additional data points were read from the graph. An equation which closely fit these data points and exhibits other desired properties follows:

SS = D
$$\left(1.0 - \exp(-0.0023 \times (\ln(e + DT))^{2.7} \times Ncy^{.5} \times R^{.6})\right)$$
 (A-1)

D = 0.85

DT = temperature rate of change (deg. C/min)

1 < DT < 20 (see below)

Ncy = number of repeated cycles

R = temperature range (deg. C) = high temperature - low temperature

high temperature < 75 deg. C; low temperature > -55 deg. C

SS = screening strength

Examination of a grid of screening test strength points computed using the above equation revealed reasonable values for reasonable values of the input parameters.

Since extremely low rates of change do not yield real temperature cycling stress, the equation is not to be used for DT less than 1 deg. C/min. If low rates of change for screening strength should be computed use the modifications for constant temperature given below.

Also, the data considered did not include extremely high rates of change or extremely large ranges. Therefore, the equation is only proposed for rates of change of 20 deg.

If it is desired to make inferences on one or the other of SS or p this can be done as shown in the following example:

Example Suppose that the planned values of p, SS are respectively, 0.005, 0.70 and that N = 10,000 "parts".

After an assembly level temperature cycling screen X = 17 dropouts are observed.

The planned mean number of drop-outs = μ_p = 10,000 (0.005) (0.70) = 35 and the lower and upper bounds from the adaptive routines are (20, 51) and since 17 does not lie between 20 and 51 (inclusive) the screen has not behaved as planned. Assuming the planned p = 0.005 is about correct = μ_p obs. drop-outs = 17 = NpSS. This means SS = 17/50 = 0.34.

This estimated screening strength is considerably different than 0.70 and an adjustment in the screening parameters is indicated. If a confidence interval on the true SS (assuming p = 0.005 is correct) is desired it can be obtained from a confidence interval for μp . Based on X=17 a 0.99 confidence interval is (see page 190, Handbook of Probability and Statistics, Chemical Rubber Co., 1966 Cleveland, Ohio 44114 for ready to use tables)

$$P(8.2 < \mu < 30.7/X=17, p=0.005)=0.99$$

Dividing each endpoint by Np = 50

$$P(0.164 < SS < 0.614/X=17, p=0.005)=0.99$$

and (0.164,0.614) is and 0.99 confidence interval for SS.

The SDO model has, in addition to the expected total dropouts (and the accompanying 0.99 bounds) the similar numbers for part/component dropouts and workmanship/manufacturing defects separately. Thus, if the user can classify failures into two categories: parts/components versus workmanship/manufacturing separate checks can be made of the expected dropouts as described in the above example.

B.1.2 Adaptive Screening for Unit/System Level Screens: In a unit/system level screen, failures that are precipitated will be repaired; an entire unit or system will not be discarded. Thus a model is needed to compute the expected number of failures in the selected test time T. In Ref. 22, a Chance Defective Exponential (CDE) time-to-failure distribution was introduced:

P (unit lifetime
$$< t$$
) = $\left[exp - (a_0 t + a_1 (1 - e^{-a_2 t})) \right]$, $t > 0$, $a_0, a_1, a_2 > 0$

APPENDIX B

STATISTICAL ASPECTS OF ADAPTIVE SCREENING

B.1 Adaptive Screening One of the cardinal "rules-of-thumb" of stress screening is that a screen should never be selected or applied without an idea of its screening strength (SS = probability of detecting a latent defect given that a latent defect is present).

In order to monitor and control a stress screening program, even one consisting only of a single screen, it is necessary to compare the actual results of the screen to the planned results. The results of a screen are commonly of two forms:

- i) number of dropouts/Jailures
- ii) times to failure

The first is usually called "attribute" data and the latter is called "variables" data.

B.1.1 Adaptive Screening for Dropout/Failure Data:

Suppose that prior to the running of a given screen the planned (from, say, the screening strength equations) SS has been determined; suppose also the same is true of the incoming latent defect rate p. Further, let N denote the known or estimated total number of opportunities for latent defects to occur (usually parts, connections, solder joints, etc.). The probability distribution of X, the number of drop-outs, is

$$P(X=x) = {N \choose x} = (pSS)^{x} (1-pSS)^{N-x}$$
, that is

X has a binomial distribution. Since pSS is usually quite small (e.g. < 0.01) and N quite large (e.g. > 1000) the Poisson distribution is used (in the adaptive routine of the SDO model):

$$P(X=x)=(e^{-\mu} \mu^X)/x!$$
 $\mu=NpSS$.

The SDO adaptive routine uses the planned values (from the main program) for p and SS to compute NpSS $\equiv \mu_{\rm p}$ and using a computer routine prints out the upper and lower bounds on the total OBSERVED number of drop-outs based on a 0.99 probability interval. That is, if the observed number of drop-outs (symbolized by X above) is outside the bounds, the screening is not behaving as planned.

APPENDIX C

THE CHANCE DEFECTIVE EXPONENTIAL (CDE) MODEL

The CDE Model:

$$\vec{F}_{s}(t)=P(\text{unit life >t})=\exp\left[-(a_{0}t+a_{1}(1-e^{-a_{2}t}))\right]$$
 (C-1)

is extremely attractive. It arises from reasonable physical considerations and it can furnish a direct (unconfounded with p) estimate of screening strength (SS).

Actually the CDE of C-1 involves two assumptions that need not be made and that do not seem to improve it's tractability. The assumption that the probability distribution of n (the random number of latent defects) is Poisson (with mean a = Np) may be replaced by the exact binomial distribution:

$$P(n) = {n \choose n} p^n (1-p)^{N-n}$$
 (p = the probability of a latent defect)

Also it was assumed that the total failure for all of the good parts (of which there are actually N-n) is a constant a_0 . If we write a_0' for the failure rate of a single good part and remove both of these assumptions.

$$\overline{F}_{s}(t) = \left[(1-p) e^{-a_0't} + pe^{-a_2t} \right]^{N}$$

The form (C-1) of the CPE has three unknown parameters $a=(a_0,\,a_1,\,a_2)$ while the "exact" CDE above has four parameters — or does it? The parameter N is known so that the only unknown parameters are a_0^+ , a_0^- , p_0^-

A quantity of interest is the probability that a defective unit (symbolized by D) will live through the test i.e. (if t= unit life), P(t > T/D), it can and has been shown that:

$$P(t>T|D) = \frac{e^{-\left[a_0^T + a_1 (1-e^{-a_2^T})\right]} - e^{-\left[a_1 + a_0^T\right]}}{(1-e^{-a_1})}$$
 (C-2)

The screening strength (SS) per latent defect is

Preceding page blank

It will be assumed, as in Ref. 22, that the unit/system failure process is a Nonhomogeneous Poisson Process (NHPP) with the mean value function (say M(t)) of the CDE:

M(t)=Expected \hat{r} of occurrences in $(0,t)=a_0t+a_1(1-e^{-a_2t})$

The CDE arises naturally: assuming that a group of N parts contains n < N latent defect parts with constant failure rate a_2 ; a large number (N-n) of good parts with constant failure rate (for) the totality of good parts) a_0 ; and expected number of latent defect parts $a_1 = Np$ (p = the) incoming latent defect rate) then the probability of survival of a system comprised a total of N parts (given n latent defective parts) is P (system live > t/n bad parts)

 $= (e^{-a_0 t}) [e^{-a_2 nt}]$

Multiplying by probability of n latent defective parts, namely

and summing out n, the unconditional survival distribution is

P(unit life time >t)
$$= \bar{F}_s(t) = \exp{-\left[a_0t + a_1(1 - e^{-a_2t})\right]}$$

Since $a_1 = Np$, $a_0 = N \lambda g = failure rate of a good part, <math>a_2 = k\lambda g$ (latent defect failure rate),

PLANNED values of
$$a = (a_0, a_1, a_2)$$
, say $\underline{a}^* = (a_0^*, a_1^*, a_2^*)$

can be obtained. The planned expected number of occurrences in a screen of length T is

$$M(T) = a_0^{\frac{1}{2}} T + a_1^{\frac{1}{2}} (1 - e^{-a_2^{\frac{1}{2}}})$$

and this is the value computed by the adaptive routine at the unit/system level screens.

When the actual failure times (during the unit/system level screen) are available, which is usually very costly, the parameter vector a might be estimated and more extensive data analysis performed. This topic is discussed in the Appendix C. At this point such data analysis is too costly and intractable for the adaptive routine.

maximizing vector \hat{a} are said to be the maximum likelihood estimates (MLE's). On the other hand one might differentiate (C-4) or its logarithim with respect a_0 , a_1 , a_2 , and iteratively solve three equations in three unknowns.

There are non-trivial problems with either approach, starting points are required and these are not easy to come by. Also the orders of magnitude of a_0 , a_1 , a_2 , are quite different which causes other problems. Usually good starting points are obtained by using another method of estimation. For example the moment estimates of a say \overline{a} (\overline{a}_0 , \overline{a}_1 , \overline{a}_2) could be used as starting points or in the worst case they could be used as estimates directly. Unfortunately the moments of the CDE, even the first (the mean) are intractable. All this discussion leaves aside the important question: over the space of all possible observed data $\{t_{\underline{i}}\}$ for which sets of $t_{\underline{i}}$ will the maximum of (C-4) exist and/or be unique?

However, assuming a user can obtain estimates of a which to him are satisfactory the direct estimate of SS can be obtained, namely, $_{1-e}$ - \hat{a}_2T

In fact, there is another approach to estimating a. It is the non-linear squares approach using the observed cumulative failures as the dependent variable and fitting the observed cumulative failures to the mean value function,

$$M(t) = a_0 t + a_1 (1-e^{-a_2 t})$$

From a purely statistical standpoint this method is not as satisfying as the maximum likelihood method. Indeed the method considered here would better be called "pseudo" least squares. The UCLA BIOMED CAL non-linear least squares rogram (BMDO7R) seems to have problems of convergence and starting points as well.

Thus, if a can be estimated the component screening strength can be estimated directly (i.e. without being confounded with the incoming latent defect rate p.)

In fact the only method of <u>estimating</u> SS directly (other than the above method) which is known is that of "seeding" latent defects so that the 'number initially present is known. This latter approach has serious shortcomings. For example some latent defects are impossible to seed or perhaps a better word would be impossible to "simulate".

Unfortunately, obtaining estimates of the vector a in the CDE model is difficult even though Fertig (Ref. 22) presented some successful cases.

The likelihood function (i.e. the joint probability density of the failure times) is

$$\prod_{j=1}^{N} (1 - F(T_j; \underline{a}) \prod_{j=1}^{T_j} (a_0 + a_1 a_2 e^{-a_2 t_{ij}})$$
(C-4)

where: N = number of systems under test (screen)

 T_i = length of test for jth system

 r_j = number of failures observed on the jth system

 t_{ij} = the ith the failure time (i=1,...,r_j) on the jth system

$$t_{ij} \le t_{i+1,j}$$
, $i = 1,..., r_{j}-1$

 $1-F(T_i;\underline{a}) = \overline{F}_a(T)$ given in (C-1)

Usually the N systems are all on the same screen and hence $T_{j} \equiv T$ for all j. It is also not uncommon that N = 1.

In any case, based on the failure times the function (in C-4)) can theoretically be evaluated by optimization techniques to find the vector $\hat{\mathbf{a}} = (\hat{\mathbf{a}}_0, \hat{\mathbf{a}}_1, \hat{\mathbf{a}}_2)$ which makes (C-4) the largest, i.e., maximizes (C-4). The components of the

APPENDIX E

LONG TERM FIELD RELIABILITY IMPROVEMENT THROUGH NATURAL LATENT DEFECT REDUCTION

If N represents the total number of opportunities (parts, solder joints, connections et. al.) for a latent defect and if p is the probability of occurrence of a latent defect, then when an assembly, unit or equipment has been constructed the probability that exactly n of the N opportunities represent latent defects is given by the binomial distribution:

$$P(n) = {N \choose n} p^n (1-p)^{N-n}$$

which, because N is usually large and p usually small, is well-approximated by the Poisson distribution.

However, the major point of consideration is the behavior of n (the number of latent defects) and p (the latent defect rate or probability of occurrence) as the unit is operated for a long time in the field. Indeed suppose each time the unit fails, with constant rate $(N-n)\lambda g$ for the good "parts" and constant rate $nk\lambda g$ for the bad "parts", that it is repaired with a good "part" with probability 1-p and repaired with a bad (latent defect) "part" with probability p. That is, it is assumed that the repairs are made at the same (latent) () fect rate as that which previously existed (when the unit was built). The factor k > 1 is the ratio of the latent defect failure rate to the good part failure rate.

It can be shown that as t (operating time)
$$\rightarrow \infty$$

$$P(n) = {N \choose n} (p^*)^n (1-p^*)^{N-n} \qquad (E-1)$$

where
$$p^* = \frac{p}{k(1-p) + p} \approx \frac{p}{k}$$

This does not mean that the random number of latent defects, n, will approach a constant and stay there; it means that n will vary, with mean Np*. It also means that the long-run latent defect probability is p*.

Note also that since k > 1, p* < p always.

Preceding page blank

APPENDIX D

APPROXIMATION OF SCREENING STRENGTH USING OBSERVED MTBF

Here it is assumed that, at the equipment or system level, estimates of the MTBF with and without a particular "screening sequence" (perhaps consisting of only one screen) are available.

Let N be the number of opportunities (parts connections) for the occurrence of a latent defect in an equipment or system. Then, in terms of expected values, the system failure rate at time t = 0 and prior to a screen is

$$\lambda_{u.s.} = N (1-p)\lambda_g + Npk\lambda_g$$
 (D-1)

where: k > 1 is the factor which when multiplied by the non-defective part failure rate yields the latent defect part failure rate; p is the latent defect occurrence probability (rate) and u.s. represents unscreened.

After the screen, in terms of expected values the equipment/system failure rate is

$$\lambda_s = N \left[(1-p)(1-SS) \right] \lambda_g + Npk\lambda_g (1-SS)$$
 (D-2)

where: SS is the screening strength of the screen. Using (D-1) and (D-2)

$$SS = (\lambda_{u.s.} - \lambda_{s}) / (\lambda_{u.s.} - N\lambda) \qquad \lambda_{s} > N\lambda$$

The largest SS can be is when $N\lambda=\lambda$; then SS is one. The smallest SS can be is when $N\lambda+0$ and then it is $1-(\lambda_{\rm S}/\lambda_{\rm U.S.})$

$$= 1 - \frac{\text{MTBF}_{\text{u.s.}}}{\text{MTBF}_{\text{s}}}.$$

Example: Suppose that two pieces of electrical equipment have MTBF's (field observed) of 100 and 250, respectively, and that the first (100 hr. MTBF) has been unscreened while the latter (250 hr. MTBF) was subjected to a 15 min. 6g (RMS) random vibration screen. Then the strength of that screen, namely SS, is at least 1-100/250 = 0.6.




Figure E.1. Decreasing Failure Rate with Time, 2,000 Parts




Figure E.2. Decreasing Failure Rate with Time, 10,000 Parts




Figure E.3. Decreasing Failure Rate with Time, 20,000 Parts

Example: Suppose H = 2000, p = 0.005, $\lambda g = 10^{-7}$ and $k = 2x10^{3}$.

$$p^* = \frac{0.005}{1990 + .005} = 2.5 \times 10^{-6}$$

An important question is: how long does it take to approach (E-1). The mathematical result requires $t \to \infty$. The accompanying three figures give an idea of the rate of decrease for nine typical cases: p = .901, .005 and .01,

p = 0.001, 0.005, and 0.01

N = 2000, 10,000, and 20,000

$$\lambda_g = 10^{-7}$$

$$k\lambda g = 2 \times 10^{-4}$$

The data in the three figures were derived from a simulation program which simulated failures of both good and bad parts and replacement of the failed part from populations containing p fraction defective.

•	
w	
Constants	
=	
=	
- 4	
-	
ູ	
=	
0	
ပ	
_	
_	
_	
~	
-	
-	
•	
·	
⊂	
-	
-	ı
77	i
SSM Internal	
63	
_	
•	
Ľ.	

ABLE	
_	
—	
⋖	

Description	Internal Value	Lines in Program Where Appears
If two (MTBF, cost) pairs differ by less than this amount during the optimization one of them is eliminate, from consideration	0.00001	Program PREFIX.SDO.FORT, line: MAIN 200
Number of divisions in the range of the parameter to be optimized upon.	S	Program PREFIX.SDO.FORT, line: MAIN 190 (Note: Arrays will need to be made extremely large if this is increased).
Multipliers which yield failure rates of latent defective parts and workmanship (multiplied times failure rate of good parts or workmanship).	(parts) 2×10 ³ (wkm) 1×10 ³	Program PREFIX.SDO.FORT, lines: MAIN 2220 MAIN 2230
Repair costs: Assembly Unit System	\$45 \$300 \$990	Program SDO.FORT, lines: DATA 890 DATA 910 DATA 930
Percent of test time considered labor time. Assembly Unit	15\$ 15\$ 100\$	Program SD01.FORT, lines: SSPR200 through SSPR1100 (each test can be handled separately).

APPENDIX P

MODEL COMPUTER PROGRAM LISTINGS

The three computer programs comprising the SSM are,

- 1) PREFIX
- 2) SDO1
- 3) ADAPT

Listings of those programs are contained in this appendix. Below is a table of internal constants, identifying the values assigned to the constants and the line number in the program where that constant can be found. This enables the user to modify the program by altering the constants to more closely fit the users own hardware characteristics, production processes and screening conditions.

Preceding page blank

PROGRAM LISTING FOR PREFIX. SDO. FORT

TABLE F.1 SSM Internal Constants (Continued)

Detection Probability (probability of detection is inherent in screening strength equations)	Internal Value	Lines in Program Where Appears Program SD01.FORT, line: DATA 390
Maximum duration of suggested improved streen in "Adapt" Constant Temtrature Cycled Temp.	240 hours 40 cycles 60 min.	Program ADAPT.FORT, lines: SOLV220 SOLV250 SOLV280
No. of levels	3	Program PREFIX.SDO.FORT, lines:
Number of Rework Cycles	1	(Requires fairly extensive rewriting)
Starting points for 2XSSQ	Computed from model data is expected values for a ₁ , a ₂	Program ADAPT.FORT, lines: OPT180-190
Convergence Criterion and Options for 2XSSQ	See documentation for 2XSSQ.	Program ADAPT.FORT, lines: OPT100-170

	READ (S.#) BHIN11(KZ), BHAX12(KZ)	MAIN S
	BMINIE(KZ)=0.	MAIN 57
	IF (OPTC.EQ.1.0) BMIN12(KZ)=BMAX12(KZ)	MAIN SE
,	BMAX11(KZ)=BMIN11(KZ)	MAIN 59
	GO TO 186	MAIN 60
44	IF (ISCR(KZ).NE.2) GO TO 80	MAIN 61
••	WRITE (4,410) KZ	MAIN 62
	IF (OFTC.EQ.1.) 60 TO 70	MAIN AS
	WRITE (6.420)	MATH A4
	READ (5.#) IDCYT	MATH AS
		MATH AA
	IF (IDCYT.NE.0) GO TO 70 CMAX21(KZ)=71.0	MATU AT
	PMTM91/471#71 A	MATN 48
	CHIN21(KZ)=71.0 CHAX22(KZ)=-54.0	MATH AC
		HATH DY
	BMIN(22(KZ)=-54.0	. HAIN /0
	BMAX23(KZ)=5.0	MAIN /1
	OH1N23(KZ)=5.0	MAIN 72
	BRAX24(KZ)=20.0	MAIN 73
	UTINE3(KZ)=5.0 BMAX24(KZ)=20.0 BMIN24(KZ)=0.0	MAIN 74
	IF (QPTC.EQ.1.0) BMIN24(KZ)=BMAX24(KZ)	, HAIN 75
	GO TO 188	MAIN 76
70		
	READ (5.*) BMAXZI(KZ).BMAXZZ(KZ).BMAXZ3(KZ).BMAXZ4(KZ)	MAIN 78
	BNIH24(KZ)=0. IF (OPTC.EQ.1.0) BNIH24(KZ)=BNAX24(KZ) ENTH21(KZ)=RNAX21(KZ)	MAIN 79
	IF (OPTC.EQ.1.0) BMIN24(KZ)=BMAX24(KZ)	HAIN 80
	CHINZI(KZ)=CHAXZI(KZ)	MAIN 61
	BHIN23(KZ)=BHAX23(KZ) BHIN23(KZ)=BHAX23(KZ)	MATH AZ
	PHTHOUGH TO TERMAYOUTE TO	MATN AT
	BMIN22(K2)=8MAX22(K2) BMIN23(K2)=8MAX23(K2) GO TO 180 IF (ISCR(KZ).NE.3) GO TO 120 LATITE (6,440) KZ	MATH 84
20	TE LEGGINZ) WE IN CO. TO NO.	MATH AE
-	LITTE (A. AAA) MT	MATH BA
	78 (0070 FO 1 A) CO 70 AA	MATH 87
	17 (DF)C.24.1.07 (G) G 70	. HAIN 0/
	WRITE (6,450)	MA 514 66
	REAU (5;+) IURY	
,	IF (IDRV.NE.3) GO TO 90	
	GTAX31(KZ?=0.0	
	EMIN31(KZ)=6.0 BMAX32(KZ)=10.0	
	BMAX32(KZ)=10.0	MAIN 93
		MAIN 94
	IF (OPTC.EQ.1.0) BMIN32(KZ)=BMAX32(KZ)	MAIN 95
	00 10 100	MAIN 96
10	HRITE (6,460) READ (5,4) BHAX31(KZ), PHAX32(KZ) IF (8MAX31(KZ).LE.7.5) GO TO 100 PHAX31(KZ).Z S	MAIN 97
	READ (5,*) BMAX31(KZ), BMAX32(KZ)	MAIN 98
	IF (8MAX31(KZ).LE.7.5) GO TO 100	MAIN 99
	BHAX31(KZ)=7.5 LPITE (6.470)	MAIN100
	LETTE (6,470)	MAIN101
	GD YO 110	
LOG		MAIN103
	IP (BHAX31(KZ):5E.U.6) GO TO 110 EMAX31(KZ)=0.6	MAIN104
		: -: -: -: -: -: -: -: -: -: -: -: -: -:
110	EMIN32(KZ)=0.0	
	Billinger Parameter and the second se	MAIN106
	THE COORD FOR A SAME MANAGEMENT AND ANALYSIS OF THE COORDINATE OF	MAIN107
	IF (OPTC.EQ.1.0) BMIN32(KZ)=BMAX32(KZ) GO TO 180 IF (ISCP(KZ).ME.4) GO TO 150	MAIN108
	WU 1U 150	MAIN109
128	IF (ISCR(KZ).NE.4) GO TO 150	MAIN110

TE (ORTE ED) \ 60	TO 130 MAIN
IF TUPIC.EU.1.7 GO	TO ADV
MERITE (6.500)	TAIN THE THE TAIN THE TAIN THE TAIN THE TAIN THE
MEAD (5.0) IDSSV	TO 130 MAIN
IF (ID55V.NE.0) 60	TO 130 MAIN
BMAX41(XZ)=6.0	THE PARTY NAMED IN THE PARTY NAM
BMINAL(KZ)=6.0	MAIN
214X42(KZ)=10.0	MAIN
BMIN-11KZ)=0.0 BMIN-2(KZ)=10.0 BMIN-2(KZ)=0.0	MAIN
IF (OPTC.EQ.1.0) M	HTMA2(KZ)#RMAX42(KZ) MAIN
CO TO 180	MAIN
WRITE (6.510)	MAIN
BEAR IS AL BMAYATIS	YTI MMAUAGINTI MATI
TF (BMAYA)(KZ).LF.	14.0) GO TO 140 MAIN
BMAX41(KZ)=14.0	MATA
WRITE (6.520)	MATE
MAJIE (4)3647	
BRIME(RZ)=0.0	MAI MAI MAI MAI
IF (OPTC.EQ.1.0) B	HINGS(KZ)=BMAXGS(KZ) MAI
CO 10 188	TIA 1
IF (ISCR(KZ).NE.S)	ED TO 190 HAIF
1217E (6.538) KZ	MAI
IF (OPTC.EQ.1.) GO	TO 160 HAII
WITE (4.540)	HAI
READ (S.W) TOSEV	MAT!
TE (TOSEV NE A) CO	TO 160 HAI
BMAVET (V 7 1-4 A	MATI
8HAX51(KZ)=4.8 EHIN51(KZ)=4.8 EHIN52(KZ)=10.0 EHIN52(KZ)=0.8	MAXI
CHILDELKE JOB. W	MAI
UNAX32(KZ)=10.0	
IF (OPIC.EQ.1.0) a	HINS2(KZ)=8HAX52(KZ) HAI
CO TO 180	MAZI
MEND (2.4) BMAX21()	KZ),BMAX52(KZ) MAI
IF (DTAX51(KZ).LE.	15.5) 60 TO 170 MAI
WITE (4.540)	MASI
IF (OPTC.EQ.1.0) B	MINS2(KZ)=8HAXS2(KZ) MAII KZ) MAII
BHT2851(KZ)=8MAX51(KZ) MAT
WITE (6.570) KZ	MAI HAI MAI MAI
PPAG (S.W) ATACKET	MAT
LOTTE (A. ERA)	MA T
0510 (5 4) 814(47)	
MEAD (3.4) BIRINE!) BIA(KZ)=CPHR HAII
Th (BTM(M5), 88.0.0) DIMEKS)=CPTK
B2(KZ)=0.	
WRITE (6.590)	
READ (5.+) B3(KZ)	HAX
MITE (6,600)	MAI MAI HAI HAI HAI
READ (5.+) ADEF(KZ	MAI ADEF(1)=.002
IF (ADEF(1),EQ.0.0) ADEF(1)=.002 MAI
IF (ADEF(2).EQ.0.0) ADEF(2)=.001 MAI
IF (ADEF(3).EQ.0.0) ADEF(3)=.0005 MAT
CONTINUE	HAI
00 200 IIS=1.3	The state of the s
A	
	and the second of the second o

the second of the second water to the second of the second

200		
	WRITE (2,#) ISCR	MAIMIS/U
	WRITE (8,0) F	MAIN1680
	00 220 INDEX=1.H	Main1690
	00 220 INDEX2=1.5	MAIN1700
	OUTB1=1000.	MAIN1710
•	DLP3231000.	MAIN1720
	IF (ISCR(INDEX).EQ.INDEX2) GO TO 210	MAIN1730
	LETTE (10,*) DUMB1.0UMB2	MAIN1 740
	CO TO 220	MATHITED
210		MATULTO
	HRITE (10,*) Ala(INDEX), Bla(INDEX)	MATUS 336
\$50	CONTINUE URITE (11.610) P	MAINIT//U
		MAIN1760
	WRITE (9.620) R1.R2	MAIN1790
	DU 230 I=1,3	MAIN1800
	MALIE (12.*) BUNXII(I).BUINII(I)	UNTLITOID
	HRITE (12,*) BRAXIZ(1),BRINIZ(1)	WINTOSA
	WRITE (12,*) BMAX21(I),8MIN21(I)	MAIN1830
	WRITE (12,*) BMAX22(I),BMIN22(I)	MAIN1840
	WRITE (12, #) BMAX23(I), BMIN23(I)	MAIN1850
	LRITE (12,*) BMAX24(I),BMIN24(I)	MATHIAM
	WRITE (12,*) BMAX31(I),BMIN31(I)	MATN1876
		MATHI
		LINTINGO
	WRITE (12,#) BMAX41(I),EMIN41(I)	MAINIOYU
	WRITE (12,*) BMAX42(I),BMIN42(I)	MAIN1900
	MATIE (15'4) BUXX21(1)'BUIN21(1)	MATHIATO
	WRITE (12,*) BMAX52(I),BMIN52(I)	MAIN1920
230	CORTINUE	UNTHTA20
	LRITE (4.*) NCYC, M, NPARTS, CREQO, E, ITV, XMTBF, CPHR	MAIN1940
	WRITE (4.630) WRITE (4.8) POEF	
	LRITE (4,#) POEF	MAIN1960
		Main197J
243	WRITE (4.*) ADEF(IX)	MAINI 980
	WITE (4,630)	MAIN1990
	00 260 IX=1,M	MAIN2000
	00 250 IU#1.5	MAIN2010
250		MAIN2020
260	CONTINUE	MAIN2030
	GO TO 300	MAT1:2040
270	LRITE (6,640)	MATN2050
	WITE (6.650)	MATN2060
	DEAD (6.8) YMYRE	MATH2070
	IF (XHTBF.EQ.0.) GO TO 280	MATN20A0
	CRECD=0.	MATN2000
		MATMETON
280	WRITE (6,660)	MAIN2110
504	READ (5.*) CREGO	MATMETAU
		MATMATTA
-		MATMET 70
	CREGU=1.E10	MAINZ140
	OPTC=1.0	MAINZI50
296	1277E (6.670)	DOLSMIAN
	READ (5,*) NPARTS	
	HRITE (6,680) READ (5,00) XLAMPI,XLAMCI TE (MIAMPI EG 0 0) XLAMPIRI E-7	MAIN2180
	READ (5,*) XLAMP1,XLAMC1 IF (XLAMP1.EG.0.0) XLAMP1=1.E-7	MAIN2190
	IF (XLAMP1.EQ.0.0) XLAMP1=1.E-7	MAIN2200

	IF (XLAHC1.EQ.0.0) XLAHC1=1.E-10	MAINEE10
	XLAMP2=2.E3#XLAMP1	MAINZZZO
•	XLANC2=1.E3=XLANC1	MAIN2230
	HOPE21.6HHPARTS	MAIN2240
	and the second s	MAINE 250
• •	WITE (6.690)	
•		MAIN2270
c ·	The state of the s	1-21-6-7-0
•	liZITE(6,586) READ(5,≈)CPHR	MATINE COO
•		MAIH2300
	Grim = 34.	LINE TIPE SAA
700	CO TO 10	UMAINS 310
300	STOP	MAIN2320
C		MAIN2330
310	FORMAT (1X///14X,8('#'), TEST AND PARAMETER SELECTION',8('#')///	
320	FORMAT (1X//SX, 'FOLLOWING ', ' ARE THE AVAILABLE SCREENS : '//SX, 'I	
	1 CONSTANT', TEMPERATURE'/SX,'2. CYCLED TEMPERATURE'/SX,'3. RA	
	200H VIBRATION'/SX,'4. SINE SHEEP',' VIBRATION'/SX,'5. SINE FIXE	
	3 VIERATION'//)	08ESHIAM
330	FCRMAT (5X/5X, 'DEFAULTS ARE: '/10X, 'LEVEL 1',16X, 'LEVEL 2',10X, 'LE	
	IEL 3'/6X, 'TEMP. CYCLING', 7X, 'RAN.VIB', 7X, 'CONST. TEMP.'/11X,'(2)'	
	214X,'(3)',14X,'(1)'///)	MAINZ410
340	FORMAT (5X, 'IF YOU HISH DEFAULT SCREENS ENTER ZERO, IF NOT, ', ' EN	-
	1ER 1:')	MATHE430
350	FORMAT (1X//5X, 'ENTER YOUR SCREEN SEQUENCE AS FROMPTED USING ", 'N	
	INDERS FROM ABOVE LISTING: '/SX, 'IF YOU GO NOT HISH TO SCREEN ', 'AT	
	2A PARTICULAR LEVEL, ENTER ZERO: 1)	MAIN2460
360	FORMAT (1X, FOR LEVEL', 12, THE SCREEN NUMBER DESIRED IS:)	MAIN2470
370	FCRMAT (1X///24X,8('#'),'LEVEL',I2,8('#')///)	Maini2480
380	FORMAT (5X, 'CONSTAINT TEMPERATURE, LEVEL', 12)	MAIN2490
390	FORMAT (5X, 'THE DEFAULT VALUES ARE: '/SX, 'TEMPERATURE=70 DEG C'/5X	
	1'TIME RANGE TO BE INVESTIGATED=0 TO 48 HOURS'/5X, IF YOU WISH THE	
	COEFAULT VALUES, ENTER ZERO, IF NOT, ', 'ENTER 1:')	MAIN2520
400	FORMAT (5X, 'ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES: '/5X, '	
	TEMP IN DEG C. '. TIME IN HRS: '/5X, '(TEMP MUST BE LESS THAN +75 DE	
	\$ C)')	MAIN2550
410		MAIN2550
420	TORMAT (5%, THE DEFAULT ', 'VALUES ARE: '/5%, 'LOWER TEMP=-54 DEG C'	
	15X, 'UPPER TEMP=71 DEG C'/5X, 'TEMP. RATE OF CHANGE=5 DEG C/MIN'/5)	
	E'RANSE OF CYCLES TO BE', ' INVESTIGATED=0 TO 20'/5X, 'IF YOU HISH T	
	SE DEFAULT VALUES ', 'ENTER ZERO, IF NOT, ENTER 1:')	MATH2600
430	FORMAT (5X, 'ENTER, IN ORDER, SEPARATED BY CONTAS OR SPACES: '/5X, '	
	1PPER TEMP., LOWER TEMP., TEMP. RATE OF CHANGE, NO.', ' OF CYCLES: '/	
	2, 'I TEMPERATURE RANGE MUST BE WITHIN -55 TO +75',' DEG C'/5X, 'AND	
	SATE OF CHANGE BETWEEN 1 AND 20 DEG C/MIN)')	MAINZ640
440	FCRMAT (5X, 'RANDOM VIERATION, LEVEL', 12)	MAINZ650
450	FORMAT (5X, 'THE DEFAULT VALUES', ' ARE: '/5X, '8-LEVEL=6 G'/5X, 'RANK	
	1 OF TIME TO BE INVESTIGATED=0 TO 10 MIN. 1/5X, IF YOU MISH THE DEF	
•	ZULT VALUES ENTER ZERO, IF NOT, ENTER 1:1)	MAINI2680
440	FORMAT (5X, 'ENTER, IM ORDER, SEPARATED BY COMMAS OR SPACES: '/5X, '	
	1 LEVEL, ', ' TIME IN MIN: '/SX, '(G LEVEL MUST BE BETWEEN .6 AND 7.5	
4 ===		MAIN2710
470	FORMAT (5X. 'G-LEVEL OUT OF ALLOHABLE RANGEPARAMETER SET AT 7.5'	
	1' 6.')	MAINE730
480	FORMAT (5X. 'G-LEVEL OUT OF ALLOHABLE RANGEPARAMETER ', 'SET AT (
	16 G.'1	MAIN2750

```
FORMAT (5X, 'SINE SHEEP VIBRATION, LEVEL', 12)
        FORMAT (5X, 'THE DEFAULT VALUES ARE: '/5X, 'G-LEVEL=6 6'/5X, 'RANGE ', MAIN2770
      1'OF TIME TO BE INVESTIGATED=0 TO 10 MIN. '/SX, 'IF YOU', ' MISH THE DMAIN2780
      SEFAULT VALUES, ENTER ZERO, IF NOT, ENTER 1:')
       FORMAT (5X, 'ENTER IN ORDER, SEPARATED BY COMMAS OR SPACES: '/5X, 'G-MAIN2800
      LLEVEL, TIME IN MIN: '/SX,'(G LEVEL BETHEEN 0 AND 10)') MAIN2810
FORMAT (5X,'G-LEVEL OUT OF ALLOHABLE RANGE--', 'PARAMETER SET AT 14MAIN2820
                                                                                            MAIN2830
530
       FORMAT (5x. 'SINE-FIXED FREQ. VIBRATION, LEVEL',12)
                                                                                           MATN2840
       FORMAT (5%, THE DEFAULT VALUES ARE: '/5%, 'G-LEVEL=6 G'/5%, 'RANGE CFMAIN2850
540
      1',' TIME TO BE INVESTIGATED=0 TO 10 MIN'/5X,'IF YOU WISH THE ','DEMAIN2860
      RFAULT VALUES ENTER ZERO, IF NOT, ENTER 1:')

FORMAT (5X,'ENTER, IN ORDER, SEPARATED BY COMMAS OR SPACES:'/5X,'GMAIN2860
1-LEVEL, TIME IN MIN:'/5X,'(G-LEVEL BETHEEN 1 AND 10)')

FORMAT (5X,'6-LEVEL OUT OF ALLOHABLE RANGE--','PARAMETER SET AT 15MAIN2900
550
                                                                                           MAIN2910
      1.5 6'1
       FORMAT (1X/5X, 'ENTER THE FOLLOWING MANUFACTURING PROCESS DATA',
                                                                                         '. MAIN2920
570
      1LEVEL'.12//5X.'IF MODEL DEFAULTS ARE DESIRED FOR ANY ITEM. ENTER ZMAIN2930
                                                                                           MAIN2940
      2ERO: '//SX, 'FIXED TEST COST IN DOLLARS=')
       FORMAT (5X, 'VARIABLE TEST COST IN OCLLARS PER HOURS')
                                                                                            MAIN2950
       FORMAT (5X, 'AVERAGE COST IN DOLLARS FOR REPAIR OF DEFECT', DETECTHAIN2960
      IED AT THIS LEVEL=')
       FORMAT (5X, 'ASSEMBLY DEFECTS AT THIS LEVEL AS A FRACTION ', OF TOTMAIN2980
      1AL PARTS=')
                                                                                           MAIN2990
410
       FORMAT (1X,F4.1)
                                                                                           MAIN3000
       FORMAT (2(1X,F10.6))
620
                                                                                           MATM3010
430
       FORMAT (1X)
                                                                                           MAIN3020
      FORMAT (5X///14x,8('*'),' SELECTION OF PROGRAM INPUTS AND ','OPTIMAIN3030 10RS ',8('*')//5X,'IF THE HODEL DEFAULT IS DESIRED, ENTER ZERO:'//SHAIN3040 2X,'OPTION A FINDS OPTIMAL TEST SEQUENCE TO ACHEIVE A',' GIVEN PRODMAIN3050
      SUCT'/SX,' RELIABILITY REQUIREMENT'//5X, 'OPTION B ', 'OPTIMIZES PRODMAIN3060
      AUCT RELIABILITY GIVEN A FIXED COST'//5X, OPTION C COMPUTES TEST STMAIN3070
      SRENGTHS OF EXISTING SCREENS'//)
                                                                                           MAIN3080
       FORMAT (1X/5X, 'DESIRED SERIES HTBF OF NEW SYSTEM (OPTION A ', 'ONLYMAIN3090
      1.FOR OPTICHS & OR C '/SX. 'ENTER ZERO)')
       FCRHAT (1X/5X, COST BUDGET(OPTION B ONLY, ', FOR OPTION A OR C ENTERAIN3110
      18 ZERG)')
                                                                                           MAIN3120
470
       FORMAT (IX/SX, 'TOTAL PART POPULATION(NO DEFAULT AVAILABLE)')
                                                                                           MAIN3130
       FORMAT (12/5%, 'FAILURE RATES OF GOOD PARTS; GOOD CONNECTIONS=') MAIN3140 FORMAT (12/5%, 'PART QUALITY DEFECTS AS A FRACTION OF TOTAL', 'PARTMAIN3150
480
490
                                                                                           MATN3160
       ENO
                                                                                           MAIN3170
```

PROGRAM LISTING FOR SDO1. FORT

DIMENSION N(5), +CT(5,5), 1CR1(5,5), CR2(5,	ADEF(5), F(1	1,4,5), R1(11,4,5), R		izah Izah
2(3), P(11,4,5),					MAI
+TIME(3,5), 3 T35(20,1500),	94004V(11 A #		1 AMPNIS 17		MAI
3 /35(20,1900), / 4 AMIN12(3), AMA)	/ARKAILLL1793	TITL AMAYS	OF AUTHORITY))) ANAVAT(14/1) AMAVAT(MAI
53). AMINE3(3), /					
63), MIN32(3), A					
73), AMINS1(3), A					
DATA NEITSITCITS					
DATA PARRAY/220				• • • • • • • • • • • • • • • • • • • •	
DATA P.F.R1,R2/6	380*1.0/				MAIN
DATA N/5+5/					MAIN
COPPION ISCR	•	• • •			MAIN
CALL DATA INCYC.	M, POEF, CREQO	.E.ITV,N.AD	EF,CPHR,P,F	,R1,R2,CR1,CR	TAMX,S
intef, Level, Ityp,	AMAX11, AMIN1	I,AHAX12,AH	IN12,AMAX21	,AMINZ1,AMAX2	AIAMA , S
ema, esxama, ssrim	A, PSXAMA, ESMI	EXAHA, PSHIM	1,AHIN31,AF	A.SEMIMA,SEXA	HAXHAI
341,Amin41,Amax42	XAMA, SPHIMA, 1	51,AMIN51,A	enima, sexam	2,NPARTS)	MAIN
READ (2,*) ISCR				• • • • • • • • • • • • • • • • • • • •	MAIN
MRITE (2,*) M,NP	'ARTS, POEF, AD				1 444
READ (13,+) XNOP	,XLAHP1,XLAH	PS,XLAMC1,X	LATILZ		· · · · · · · · · · · · · · · · · · ·
LL=0					HALP
ADIN=0.0					MAIN
00 10 I=1.M					LIMATE
AOIN=AOIN+AOEF(I	D .				HALF
DIN=ADIN+POEF IF (XMTBF.EQ.0.0					LWTH
FRF=1./XHTBF	11 60 10 20				HATE
					MATN
	4.4				10021
FRM=0.0 OPTS=0.0					MATN
OPT5=0.0					LINETL
OPTS=0.0 OPTS2=0.0					MAIN
OPT5=0.0					MAIN
OPTS=0.0 OPTS2=0.0 HOURS2=0.0				• • • • • • • • • • • • • • • • • • • •	MAIN MAIN MAIN
OPTS=0.0 OPTS2=0.0 HOURS2=0.0 SREGD=XHTBF DO 100 I1=1,M FI1=N(I1)				• • • • • • • • • • • • • • • • • • • •	MAIN MAIN MAIN MAIN MAIN
OPTS=0.0 OPTS2=0.0 MOURS2=0.0 SREGO=WHTBF DO 160 I1=1.M FI1=N(I1) DO 170 I2=1.NI1				• • • • • • • • • • • • • • • • • • • •	MAIN MAIN MAIN MAIN MAIN MAIN
OPTS=0.0 OPTS2=0.0 HOURS2=0.0 SREGD=XHTBF DO 180 II=1.M FII=M(II) DO 170 I2=1,HII LL=LL+1					MAIN MAIN MAIN MAIN MAIN MAIN MAIN
OPTS=0.0 OPTS=0.0 OPTS2=0.0 HOURS2=0.0 SREGD=WHTBF DO 160 II=1.M PII=N(II) DO 170 I2=1,NII LL=LL+1 MV=0					MIAN MIAM MIAM MIAM MIAM MIAM MIAM MIAM
OPTS=0.0 OPTS=0.0 OPTS2=0.0 HOURS2=0.0 SREGD=XHTBF DO 180 I1=1.M FIL=N(I1) DO 170 I2=1,HI1 LL=LL+1 MY=0 READ (10,+,END=3					MIAN MIAM MIAM MIAM MIAM MIAM MIAM MIAM
OPTS=0.0 OPTS2=0.0 HOURS2=0.0 SREGD=WHTBF DO 180 I1=1.M PI1=N(I1) DO 170 I2=1,HI1 LL=LL+1 HV=0 READ (10,*,END=3 GO TO 40					MIAN MIAM MIAM MIAM MIAM MIAM MIAM MIAM
OPTS=0.0 OPTS=0.0 MOURSE=0.0 SREGD=NHTBF DO 180 [1=1,M F'11=N(I1) DO 170 [2=1,NI1 LL=LL+1 HV=0 READ (10,0,END=3 GO TO 40 A1=0.0					MIAN MIAM MIAM MIAM MIAM MIAM MIAM MIAM
OPTS=0.0 OPTS=0.0 OPTSZ=0.0 HOURSZ=0.0 SREGD=XHTBF DO 180 I1=1.M HI=M(I1) DO 170 I2=1,HI1 LL=LL+1 HV=0 READ (10,+,END=3 GO TO 40 B1=0.0					MIAN MIAH MIAH MIAH MIAH MIAH MIAH MIAH MIAH
OPTS=0.0 OPTS=0.0 HOURS=0.0 SREGO=XHTBF DO 180 I1=1.M FII=N(II) DO 170 I2=1,HII LL=LL+1 MY=0 READ (10,0,END=3 GO TO 40 A1=0.0 B1=0.0 DO 90 KK4=1,ITV					MIAH MIAH MIAH MIAH MIAH MIAH MIAH MIAH
OPTS=0.0 OPTS2=0.0 HOURS2=0.0 SREGD=WHTBF DO 180 I1=1.M PI1=N(I1) DO 170 I2=1,HI1 LL=LL+1 MV=0 READ (10.0,END=3 GO TO 40 A1=0.0 B1=0.0 DO 90 KK4=1,ITV DO 90 KK3=1.ITV					MAIN MAIN MAIN MAIN MAIN MAIN MAIN MAIN
OPTS=0.0 OPTS=0.0 MOURS2=0.0 SREGD=WHTBF DO 180 I1=1,M P'11=N(I1) DO 170 I2=1,NI1 LL=LL+1 MV=0 READ (10,**,END=3 GO TO 40 A1=0.0 B1=0.0 DO 90 KK4=1,ITV DO 70 KK2=1,ITV					HIAN HAIN HAIN HAIN HAIN HAIN HAIN HAIN
OPTS=0.0 OPTS=0.0 HOURS2=0.0 SREGD=WHTBF DO 180 I1=1.M FI1=N(II) DO 170 I2=1,HI1 LL=LL+1 HV=0 READ (10,0,END=3 GO TO 40 A1=0.0 B1=0.0 DO 90 KK4=1,ITV DO 70 KK2=1,ITV DO 60 KK1=1,ITV					MAIN MAIN MAIN MAIN MAIN MAIN MAIN MAIN
OPTS=0.0 OPTS=0.0 MOURS2=0.0 SREGD=WHTBF DO 180 I1=1,M P'11=N(I1) DO 170 I2=1,NI1 LL=LL+1 MV=0 READ (10,**,END=3 GO TO 40 A1=0.0 B1=0.0 DO 90 KK4=1,ITV DO 70 KK2=1,ITV					MAIN MAIN MAIN MAIN MAIN MAIN MAIN MAIN

CALL SCREEN (NCYC, M.N. P.	dep.din.adep.parray.f.rl.r2.ct.crl.cr2.ss.smain
	in,0.0, tine,nparts,xnop,xlamp1,xlamp2,xlamchain
11.XLAMC2.X)	MAZN
T35(LL.HV)=35	MAIN
TS(LL,NV)=SH	MAIN
TCI LL, MY 1=TCOST	MAIN
CONTINUE	MAIN
CONTINUE	MAIN
IF ((I2-1)+(I2-3)+(I2-4	
CONTINUE	MAIN
CONTINUE	MAIN
CONTINUE	MAIN
DO 110 I=1,NCYC	MAIN
PARRAY(1,11,12)=1.0	MEM
CONTINUE DO 110 I=1,NCYC PARRAY(I,II,I2)=1.0 N1(LL)=MY	MAIN
-, ,, -, -, -, -, -, -, -, -, -, -,	I PA A IV
K1=M1(LL-1)	MAIN
60 TO 140	MAIN
K1 =K	MAIN
K2=H1(LL)	MAIN
MSEG=K1=K2	MAZN
00 150 J1*1,K1	MATH
70 186 1941 VA	22.2
W#T35(LL.J2)#(1.0-T55(L)	L-1.J1))+735(LL-1.J1) .
100011 1 10 1.45 mm.	F-T191114(99(FF-T1911)
U-13(LL-1,J1)+(1,-755(L)	L-1.J1))#735(LL.J2)#75(LL.J2) MATH
V=TC(LL-1,J1)+(1,-T55(L)	L-1,J1))#T35(LL,J2)#T3(LL,J2)
V=T3(LL-1,J1)+(1T35(L) V=TC(LL-1,J1)+(1T35(L) NF(LL)=NF(LL)+1	(\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
AALC(FF-1'17)+(1'-122(F	(\$\(_1\) (\$\(
V=TC(LL-1,J1)+(1,-TSS(L) NF(LL)=NF(LL)+1	L-1,J1)PCTS(LL,J2)PCT(LL,J2) HAIN L-1,J1)PCTS(LL,J2)PCT(LL,J2) HAIN HAIN HAIN
Y=TC(LL-1,J1)+(1,-T55(L) HF(LL)=HF(LL)+1 JJ=HF(LL) SEQ1(JJ)=J1	(3L,1) (
Y=TC(LL-1,J1)+(1,-T55(L) HF(LL)=HF(LL)+1 JJ=HF(LL) SEQ1(JJ)=J1	(SL,1) (ET#(SL,1) (ET*(SL,1) (ET#(SL,1) (ET#(SL,1) (ET*(SL,1) (ET*(SL,
Y=TC(LL-1,J1)+(1,-TSS(L) HF(LL)=NF(LL)+1 JJ=NF(LL)	Car
Y=TC[[.].]])*(1,-TSS([NF([L]); J=NF([L]) SE([]])=J1 Y=(L])=JS TS](JJ)=JS TS](JS](JS)=JS TS](JS](JS)=JS TS](JS](TS](TS](TS](TS](TS](TS](TS](TS](TS](T	Cal
TSS:(_1,_1);(1,-TSS(L) WF(LL); WF(LL); TV((JJ); TV((JJ); TSS((JJ); TSS((JJ); MERCELL; TSS((JJ); TSS((JJ)	L-1,J1)PET#(SL,J2)PET#(SL,J1)PET##(SL,J1)PET#(SL,J1)PET#(SL,J1)PET#(SL,J1)PET#(SL,J1)PET##(SL,J1)PET
TSS:(_1,_1);(1,-TSS(L) WF(LL); WF(LL); TV((JJ); TV((JJ); TSS((JJ); TSS((JJ); MERCELL; TSS((JJ); TSS((JJ)	L-1,J1)PET#(SL,J2)PET#(SL,J1)PET##(SL,J1)PET#(SL,J1)PET#(SL,J1)PET#(SL,J1)PET#(SL,J1)PET##(SL,J1)PET
Y=TCT(L-1,J)+(1,-TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(J)=J2 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=V TSS1(JJ)=W CONTINUE CALL RANK (TS1,TC1,TSS1)	L-1,J1)PET=(SL,J2) MAIN L-1,J1)PET=(SL,J2) MAIN HAIN HAIN HAIN HAIN HAIN HAIN HAIN H
Y=TCT(L-1,J)+(1,-TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(J)=J2 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=V TSS1(JJ)=W CONTINUE CALL RANK (TS1,TC1,TSS1)	L-1,J1)PET#(SL,J2)MIN L-1,J1)PET#(SL,J2)MIN L-1,J1)PET#(SL,J2)MIN MAIM MAIM MAIM MAIM MAIM MAIM MAIM M
Y=TCT[L-1,J]*(1,-TSS(L) NF(LL)*NF(LL) J=NF(LL) SEQ1(J)*J) TV1(JJ)*J TS1(JJ)*U TC1(JJ)*V TS31(JJ)*W CONTINUE CALL RANK (TS1,TC1,TSS1, QC=0.0	L-1,J1)PSS(LL,J2)ET=(SL,J2) MAIN NIAM (SL,J1)PTS(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAIN
V=TCT(L-1,J)+(1TSS(L) MF(LL)=MF(LL)+1 JJ=MF(LL) SEQ1(JJ)=J1 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=W TSS1(JJ)=M CONTINUE CALL RANK (TS1.TC1.TSS1: QC=0.0 QS=0.0 K=0	L-1,J1)PTSS(LL,J2)HTS(LL,J2) HAIM HAIM HAIM HAIM HAIM HAIM HAIM HAI
V=TCT(L-1,J)+(1TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(JJ)=J2 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=W TSS1(JJ)=M CONTINUE CALL RANK (TS1,TC1,TSS1, QC=0.0 QS=0.0 K=0 DO 160 I=1,NSEQ	L-1,J1)PSS(LL,J2) MAIN HIAM HIAM HIAM HIAM HIAM HIAM HIAM HIAM
V=TCT(L-1,J)+(1TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(J)=J2 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=V TSS1(JJ)=W CONTINUE CALL RANK (TS1.TC1.TSS1: QC=q.0 QS=0.0 K=0 DO 140 I=1,NSEQ IF ((TS1(I).EQ.0.0).OR.)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN L-1,J1))*T3S(LL,J2)*TC(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAIN
V=TCT(L-1,J)*(1,-TSS(L) NF(LL)*NF(LL)*) J=NF(LL) SEQ1(J)*J; TV1(JJ)*J; TV1(JJ)*J; TC1(JJ)*V TSS1(JJ)*W CONTINUE CALL RANK (TS1.TC1,TSS1: QC=0.0 QS=0.0 K=0 DO 160 I*1,NSEQ IF ((TS1(I).EQ.0.0).OR.IF ((TS1(I).EQ.0.0).OR.IF)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI
V=TCT(L-1,J)+(1TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(J)=J2 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=V TSS1(JJ)=W CONTINUE CALL RANK (TS1.TC1.TSS1: QC=q.0 QS=0.0 K=0 DO 140 I=1,NSEQ IF ((TS1(I).EQ.0.0).OR.)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN L-1,J1))*T3S(LL,J2)*TC(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI
V=TCT(L-1.J1)*(1TSS(L) NF(LL)=NF(LL)*) J=NF(LL) SEQ1(JJ)=J1 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=V TS31(JJ)=W CONTINUE CALL RANK (TS1.TC1.TSS1. QC=Q.0 QS=0.0 K=Q DO 160 I=1,NSEQ IF ((TS1(I)-QS)/TS1(I). IF ((TS1(I)-QC)/TC1(I).) IF ((TC1(I)-QC)/TC1(I).)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN L-1,J1))*T3S(LL,J2)*TC(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAIN
V=TC(L-1,J)+(1TSS(L) NF(LL)=NF(LL)+1 J=NF(LL) SEQ1(JJ)=J2 TS1(JJ)=U TC1(JJ)=U TC1(JJ)=W TSS1(JJ)=H CONTINUE CALL RANK (TS1,TC1,TSS1,QC=0,0 QS=0.0 K=0 DO 160 I=1,NSEQ IF ((TS1(I),EQ.0.0),OR. IF ((TS1(I),QS)/TS1(I),I IF ((TG1(I),QC)/TC1(I),I QC=TC1(I)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI
V=TCT(L-1,J)+(1TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(JJ)=J TV1(JJ)=J TS1(JJ)=U TC1(JJ)=W TSS1(JJ)=W CONTINUE CALL RANK (TS1.TC1.TSS1: QC=q.0 QS=0.0 K=0 OO 160 I=1,NSEQ IF ((TS1(I)-QC)/TC1(I).! QC=TC1(I) QC=TC1(I) QS=TS1(I) K=K+1 K=K+1	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI
V=TC(L-1,J)+(1TSS(L) NF(LL)=NF(LL) J=NF(LL) SEQ1(JJ)=J2 TY1(JJ)=J2 TS1(JJ)=U TC1(JJ)=V TSS1(JJ)=W CONTINUE CALL RANK (TS1.TC1.TSS1: QC=0.0 QS=0.0 K=0 DO 160 I=1.NSEQ IF ((TS1(I).EQ.0.0).OR.: IF ((TS1(I)-QS)/TS1(I).! IF ((TC1(I)-QC)/TC1(I).! QC=TC1(I) QC=TC1(I) K=K+1 TC(LL,K)=TC1(I)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAIN
V=TC(L-1,J)+(1TSS(L) NF(LL)=NF(LL)+1 J=NF(LL) SEQ1(JJ)=J1 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=W TSS1(JJ)=M CONTINUE CALL RANK (TS1.TC1.TSS1.QC=0.0 QS=0.0 K=0 DO 160 I=1.NSEQ IF ((TS1(I)-QC)/TC1(I).I IF ((TC1(I)-QC)/TC1(I).I QC=TC1(I) QS=TS1(I) TS(LL,K)=TC1(I) TS(LL,K)=TS1(I) TS(LL,K)=TS1(I)	L-1,J1))*TSS(LL,J2)*TS(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI
V=TC(L-1,J)+(1TSS(L) NF(LL)=NF(LL)+1 J=NF(LL) SEQ1(JJ)=J1 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=W TSS1(JJ)=M CONTINUE CALL RANK (TS1,TC1,TSS1,QC=0,0 05=0.0 K=0 00 160 I=1,NSEQ IF ((TS1(I)-QC,0.0),OR.,IF ((TS1(I)-QC)/TC1(I),IGC=TC1(I),QC=TC1(I),IGC=T	L-1,J1))*TSS(LL,J2)*TS(LL,J2) HAIN L-1,J1))*TSS(LL,J2)*TC(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI
V=TC(L-1,J)+(1TSS(L) NF(LL)=NF(LL)+1 J=NF(LL) SEQ1(J)=J TV1(JJ)=J TV1(JJ)=J TV1(JJ)=U TC1(JJ)=W TSSI(JJ)=M CONTINUE CALL RANK (TS1,TC1,TSS1,QC=0,0 QS=0.0 K=0 00 160 I=1,NSEQ IF ((TS1(I)-QC)/TS1(I),I QC=TC(II) QS=TS1(I) K=K+1 TC(LL,K)=TC1(I) TSS(LL,K)=TS1(I) SEQ(LL,K)=SEQ(II)	L-1,J1))*T3S(LL,J2)*T3(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAIN
V=TC(L-1,J)+(1TSS(L) NF(LL)=NF(LL)+1 J=NF(LL) SEQ1(JJ)=J1 TV1(JJ)=J2 TS1(JJ)=U TC1(JJ)=W TSS1(JJ)=M CONTINUE CALL RANK (TS1,TC1,TSS1,QC=0,0 05=0.0 K=0 00 160 I=1,NSEQ IF ((TS1(I)-QC,0.0),OR.,IF ((TS1(I)-QC)/TC1(I),IGC=TC1(I),QC=TC1(I),IGC=T	L-1,J1))*TSS(LL,J2)*TS(LL,J2) HAIN L-1,J1))*TSS(LL,J2)*TC(LL,J2) HAIN HAIN HAIN HAIN HAIN HAIN HAIN HAI

	·		
	TSS1(I)=0.	MAIN	
	SEQ1(1)=0	MAIN	
	TV1(I)=0	MAIN	1070
160	CONTINUE	MAIN	1080
170	CONTINUE	MAIN	1040
180	CONTINUE	MAIN	
	CALL SEARCH (LL.K.CREGO.SREGO,SEQ.TV.TC.TSS.TS.IARRAY.TCMIN.TSMAX		
	IDIN.X)	MAIN	
	CALL REPORT (M, MCYC, M, ISCR, POEF, DIN, ADEF, CPHR, P, F, R1, R2, CT, CR1, CR	2MAIN	1130
	1, IAPRAY, A1, 81, ITV, TCMIN, TSMAX, NPARTS, XNOP, XLAMP1, XLAMP2, XLAMC1, XL	AMAIN	1140
	AMA, 25HIMA, 25AMA, 15HIMA, 15AMA, 1HIMA, 1HAMA, 1HIMA, 1HAMA, X, 5HI S	XMAIN	1150
	323,Amin23,Amax24,Amin24,Amax31,Amin31,Amax32,Amin32,Amax41,Amin41	,MAIN	1160
	(SCHIMA, SCHAMA, ICHIMA, ICXAMA, SCHAMA	MAIN	
	DEBUG SUBCHK	MAIN	1175
	ENO	MAIN	1180
	SUBMOUTINE SCREEN (NCYC,M,N,PDEF,DIN,ADEF,P,F,R1,R2,CT,CR1,CR2,SS	,SCRE	10
	15H.TCOST.11.12.SCOST.TCMIN.FLAG.TIME.NPARTS.XNOP.XLAMP1.XLAMP2.XL	ASCRE	
	ZHC1,XLAHC2,X)	SCRE	30
	DIMENSION X(11,4,5), P(11,4,5), F(11,4,5), R1(11,4,5), Q(20),	SCRE	40
	11SCR(3), TIME(3,5), TCOSTL(5,5), COSTL(5), N(5), CT(5,5), CR1(5,5)SCRE	50
	2, ADEF(5), CR2(5,5), SCOST(5,5),R2(11,4,5)	SCRE	60
	CONTON ISCR	SCRE	70
	PLEFT=PDEF	SCRE	80
	<pre>IF (FLAG.GT.0.) WRITE (13,#) TIME(1,ISCR(1)),TIME(2,ISCR(2)),TIME</pre>	(SCRE	90
	13.ISCR(3))	SCRE	100
	<pre>IF (FLAG.GT.O.) WRITE (2,*) P(1,1,ISCR(1)),P(1,2,ISCR(2)),P(1,3,I</pre>	SSCRE	110
	¹(q(3))	SCRE	120
	NCYC1=NCYC+1	SCRE	130
	DO 10 I=1,NCYC1	SCRE	140
	00 10 J=1,H	SCRE	150
		SCRE	
	00 10 K=1,NJ	SCRE	170
10	X(I,J,K)=0.0	SCRE	180
	X(1,1,1)=ADEF(1)+PDEF	SCRE	190
	90 50 J*1.n	SCRE	200
	(L)N=LN	SCRE	210
	00 50 K=1,NJ	SCRE	220
	IP (1) 20,20,40	SCKE	530
20	IF (J-1) 50,50,30	SCRE	
30 .	CALL MEAN (XNOP, XLAMC1, X(1, J-1, N(J-1)), TIME(J-1, N(J-1)), P(1, J-1, N	SCRE	250
	1J-1)),FALL)	SCRE	260
		SCRE	
	X(1,J,K)=X(1,J-1,N(J-1))-FALL+ADEF(J)	SCRE	
		SCRE	
99	The state of the s	SCRE	
	PLEFT=PLEFT*P(1,J,K-1)	SCRE	
40	GO TO SO	SCRE	
79	CALL MEAN (XMOP, XLAMCI, X(1, J, K-1), TIME(J, K-1), P(1, J, K-1), FALL)	SCRE	330
	PLEFT=PLEFT*P(1,J,K-1)	SCRE	340
20	X(1,J,K)=X(1,J,K-1)-FALL	SCRE	
50	CONTINUE	SCRE	
_	IF (FLAG.6T.O.) WRITE (2,*) X(1,1,1),X(1,2,1),X(1,3,1)	SCRE	
C	IF (FLAG.GT.O.) WRITE(6,4000)((X(1,J,K),J=1,M),K=1,5)	SCRE	
	IF (FLAG.GT.0.) WRITE (2,*) X(1,1,5),X(1,2,5),X(1,3,5),PLEFT	SCRE	

	SUR:0.	SCHE	
	00 100 I=1.NCYC	SCRE	420
	X(I+1,1,1)=0.0	SCRE	430
	PA AA '-1 M	4000	
•	M.I wild J.	SCRE	450
	MJ=M(J, MJ=M(J, OO GC K=2,NJ MT=1.1.1EX(T=1.1.1)A(1=B(T.1.K1)BF(T.1.K1)B(1=B1(T.1.K1)BX(T.1.K	SCRE	460
40	X(I+1,1,1)=X(I+1,1,1)+(1-P(I,J,K))+F(I,J,K)+(1-R1(I,J,K))+X(I,J,K	ISCRE	470
••	88 88 1-1 11	***	480
	MisMf 33	SCRE	490
	DO 90 Kal Mi	SCRE	500
	78 (X(T.J.X) 17 1 0) 40 TO 40	SCRE	510
	77 (L FG 1 AND K FG 11 GO TO 90	SCRE	520
	78 (J 87.1 AND K 80 11 60 TO 70	SCRE	530
	TP (1.69 1 AND K GT 1) GO TO AO	SCRE	540
	TF (J.EG.1.AMD.K.EQ.1) GO TO 90 IF (J.EG.1.AMD.K.EQ.1) GO TO 90 IF (J.GT.1.AMD.K.EQ.1) GO TO 70 IF (J.GT.1.AMD.K.ET.1) GO TO 80 ED TO 90	SCRE	550
70	X(I+1,J,1)=P(I+1,J-1,N(J-1))=X(I+1,J-1,N(J-1))+(I-P(I,J,1))=(I-F(
, •		SCRE	
	1,J,1))#(1-R2(I,J,1))#X(I,J,1) GO TO 90	SCRE	
86	W	ecne	200
94	IRRITIANS DESCRIPTION OF THE PROPERTY OF THE P	374E 2008	270
90	IR2(I,J,K))*X(I,J,K) CONTINUE	SCRE	410
100	CONTINUE	SCRE	910
C 100	CURTINUE	SCHE	020
C	CONTINUE IF (FLAG.6T.0.) HRITE(6,4001)((X(2,J,K),J=1,M),K=1,5) SURTEO.O DO 110 I=1,NCYC NM=N(H) SURTSUM+X(I,M,M) CONTINUE DOUT=SUM	SCKE	0.00
	501-0.0	SCRE	040
	OO IIO I*I,NCYC	SCRE	650
	MITTH (II)	SCRE	000
•••	SUNESUNEX LANGENT	3CRE	0/0
110	CONTINUE	SCRE	500
	SM=1./((XMOP-CLEFT)=XLAMC1+(FLOAT(MPARTS)-PLEFT)=XLAMP1+CLEFT=XLA		
	1C2+PLEFT=XLAMP2)	nauke eene	710
		SCRE	710
	33#1.0-0001/01N	SCRE	770
	APORTALA	SCRE	740
٠			
	00 120 J=1.H	BCDE	74.0
	TCOST=0.0 00 120 J=1.M 00 120 K=1.5	SCRE	770
120	DC 120 K*1,5 SCOST(J.K)=0.0	SCHE	700
154		SCRE	700
	IF(FLAG.NE.0.0) 60 TO 140 DO 130 I=1.NCYC	SCRE	
	CR=CR1(11,12)=F(1,11,12)+CR2(11,12)*(1.8-F(1,11,12)) COST=CT(11,12)+CR*(X(1,11,1)-X(1,11,5)) ACOST=ACOST+COST 60 TO 170	SCAE	A1 A
	COQTACT! T1 . T2 \action (\cdot T . T1 . T \action (\cdot T . T1 . T \action T . T1 .	SCRE	820
130	ACCOTACCOCT	SCRE	840
	60 70 170	SCRE	450
140	00 160 J=1,M	SCRE	840
***	00 160 J=1,H 00 160 K=1,S	SCOR	870
	M0401-A A	SCAE	440
		SCOE	200
•	NO 160 Tel MENO	SCRE	970
	00 150 I=1,MCYC SUNTS1=SUNTS1+(1P(I,J,K))#X(I,J,K) SUNTS2=SUNTS2+X(I,J,K)	37.7E	914
	SUITS2*SUITS2*X(I,J,K)	SCAE	710
150	SUNTSERSUNTSERX(I,J,K) CONTINUE	SCRE	760
	IF (ISCP(J).NE.K) 60 TO 160 IF (P(1,J,ISCR(J)).GT.0.999) 60 TO 160	SCRE	770
	SCOST(J,K)=SUNTS1=CR2(J,K)+CT(J,K)	SCRE	
	anna i a iti i mani 44 met a lei i i i i i i i i i i i i i i i i i i	3-KE	700

TERRETATERSTANCES () V)		SCRE
SUMTC=TCOST		SCRE
60 70 190		
		3CXE
17 ((DIN-DOUT).88.1.0)		3CKE
DELTA=1.0		SCRE
TCOST=ACOST/DELTA		SCRE
RETURN		SCRE
DEBUG SUBCHK		SCRE
END	the state of the s	
	3 700 1400 000 744 1	~~E
SUDMUUTINE WANK (TS1,T)	1,T551,H5EQ,SEQ1,TV1)	TANK
INTEGER#2 TV1(17000),50	(91(17000) R	YANK
DIMENSION TS1(17000), 1	(91(17000) R C1(17000),TSS1(17000) R	PANK
NE=NSEQ		MAN
M1=N2	R	MAK
M1=INT(M1/2.)		
IF (M1.EQ.0) GO TO 50		
AF 1811.E4.07 WO 10 50		INTE
HI=M2-HI	' e e e e e e e e e e e e e e e e e e e	IANK
J=1		MANK
7- 1		MAN
Ll=I+MI	· · · · · · · · · · · · · · · · · · ·	MAN
IF (TC1(I).LE.TC1(L1))	60 TO 40 R	
Al=TC1(I)		MANK
B1=TS1(I)		PANK
C1=7351(I)	· · · · · · · · · · · · · · · · · · ·	ANK
A2=3EQ1(I)		ANK
B2=TV1(I)		CAPTER.
7C1(I)::::1(L1)		ANK
TS1(I)=TS1(L1)		ANK
TSS1(1)=TSS1(L1)		ANK
SEQ1(I)=SEQ1(L1)		ANK
TV1(I)=TV1(L1)		
		ANK
TC1(L1)=A1		MIK
T\$1(L1)=81		ANK
TSS1(L1):=C1		ANK
SEQL(L1)=A2	R	ANK
TV1(L1)=82		ANK
I=I~H1		
IF (I.6E.1) 30 TO 30	R	444
	and the second of the second o	ANK
J=J+1	R	ANK
IF (J.LE.H1) 60 TO 20		ANK
60 TO 10	R1	ANK
RETURN		ANK
END	interior to the contract of th	ANK
SUBROUTINE SPANCE ITTEM	o, crego, srego, seq, tv, tc, tss, ts, iarray, tchinsi	
1,TSMAX,DIN,X)		EAR
INTEGER T,5,51,52		EAR
INTEGER*2 TV(20,300),SE		EAR
DIMENSION TC(20,1500),	TS(20,1500), IARRAY(20), X(11,4,5)	EAR
+,T33(20,1500)		EAR
PLACE=SREQD		
00 10 I=1.NO		E 44
TCTOT=TC(LL,I)=DIN=TSS(31 7)	EAR
1616151616161A11701N91331	LL:1/	EAR
TOTAL TIPESCO		
TC(LL,I)=TCTOT		EAR
TC(LL,I)=TCTOT CONTINUE OTCHIN=TC(LL,NO)		EAR EAR

	DTSHAX=TS(LL,HO)	SEAR	13
•	IF (CBEOD) 30.30.40	3EAK	- 44
	IF (SWEGO) 160.160.60	35 ~~	•
	Kalad	35-00	•
	IP (C(LL X) - C(C(U)) 80 80 70	36~4	•
	K=1	SEAR	10
	IF (TS(LL,K)-SREQD) 100,80,80	SEAR	1
	S1=SEQ(LL.K)	SEAR	14
1	T=TV(LL,K)		
	ZARRAY(LL)=T	SEAR	21
	TCHIN=TC(LL.K)	SFAR	2
		2510	2
		SEAR	•
	60 TO 110	SEAR	
	KsK-1	MASE	٤:
	IF (K) 140,140,50	JEAR	6
	Kakal	SEAK	•
	IF (K-NO) 70,70,146	SEAR	
	T=LL-1	SEAR	2
	IF (1-1) 150.150.150	JEAR	٠,
	3=5EQ(I,31)	SEAR	3
	T=TV(I,S1)	SEAR	3
	32*31	SEAR	3
	\$1=\$	SEAR	3
	IARRAY(I)=T		
	I=I-1	SFAP	3
		SFAR	3
	WRITE (6:180)	8540	7
		SEAR	1
	SREQD=TS(LL,NO)	9540	7
	GO TO 20	SEAR	7
	TANKAT(T)=2	JEAR	~
	60 TO 170	JEAR	7
	##11E (0.500)	- SEAR	-
	STOP	. SEAR	
	DEBUG SUBCHK		
	CONTINUE	SEAR	
	SHEAD=PLACE		
	RETURN	SEAR	
			4
	FORMAT (/lx.'REQUIREMENT CANNOT BE MET'/lx)	SEAR	5
	FORMAT (/1x, 'REQUIREMENT CAN BE HET WITHOUT TEST SCREENS')	SEAR	5
	0.0	SEAR	5
	SUBROUTINE SSPROB (K1,K2,K3,K4,I1,I2,F,NCYC,CT,A1,B1,ITV,HOURS,F)		
	1, Time, amaxii, aminii, amaxii, aminii, amaxii, aminii, amaxii, aminii, amaxii, aminii, amaxii, aminii, aminii		
	PARIMA, 19XAMA, SENIMA, SEXAMA, 1ENIMA, 1EXAMA, PSKIMA, PSXAMA, ESKIMA, ESS	LISSPR	!
	(SENIMA, SEXAMA, IENIMA, SEXAMA, SAMINA, SAMINA, SAXAMAE	SSPR	•
	DIMENSION P(11,4,5), CT(5,5), TIME(3,5)	SSPR	•
	60 TO (10,70,160,220,280), I2	SSPR	!
	CONTINUE	SSPR	
r	EST ONE: CONSTANT TEMPERATURE(CT)		
• •	RR=((AMAX11-AMINI1)+K1+AMINI1+ITV-AMAX11)/(ITV-1.)	SSPR	
	RR=485(RR-25.)	SSPR	
			_
			_
	DT=ALOG(EXP(1.)+1.)	SSPR	_
	UI-ALW3(6AF11.771.7	2217	

	RHCY=1.8		2214	140
	PTT=.85#() . 0-EXP(-0.0023##			
	85=1.0-PFT		SSPR	160
	TIME(II.IE)=HOURS		SSPR	170
	IF (81) 20,20,340		SSPR	180
20	60 TO (30,40.50.40). II		1300	190
30	CT(1.12)=(0.15)+HCHPS+CTHP		2222	204
~	60 TO 350		4000	200
	. 60 10 330			
44	CT(2,12)=(0.15)#HOURS#CPHR	the second secon	22m	ZZQ
	60 TO 350		SSPR	230
50	CT(3,I2)=HOURS=CPHR			
	60 TO 350		SSPR	250
40	CT(4.IZ)=HOURS=CPHR			
	60 TO 350		3500	270
70			22.00	200
ć t	PEST THOS CYCLED TEMPERATURE	(CYT)	9978	100
		(617)	33PR	270
	RR=ABS(AMAX21-AMAX22)		2200	300
	DT1=((AMAX23-AMIH23)#K3+AM	INSTRITY-AMAXSTINTITY-1.1	33FR	310
	OT=ALOG(EXP(1.)+OT1)==2.7		SSPR	320
	RHCY=((AMAX24-AMIN24)#K4+AF	HIN24#ITV-AMAX24)/{ITV-1.}	SSPR	330
	TT=1.		SSPR	340
	PFDT=.85*(1,-EXP(-,0023*RR		SSPR	
	SS=1.0-PFDT		SSPR	
			SSPR	
88	HOURS=RNCY#(4./DT+(2.=RR)/(SSPR	
	TIME(I1,I2)=HOURS		SSPR	390
	60 TO 100		SSPR	400
90	HOURS:		SSPR	410
	TIME(I1.I2)=HOURS		SSPR	420
100	IF (81) 110,110,340		SSPR	
110	60 TO (120,130,140,150), II		SSPR	
120	CT(1.12)=(0.15)=HOURS=CPHR		SSPR	
	60.70 350			
		•	SSPR	
130	CT(2,12)=(0.15)=HOURS=CPHR		SSPR	
	GO TO 350		SSPR	
146	CT(3,12)=HOURS+CPHR		SSPR	490
	00 TO 350		SSPR	500
150	CT(4,12)=HOURS#CPHR		SSPR	
	GC TO 350		SSPR	520
140	CONTINUE		SSPR	530
	EST THREE: RANDOM VIERATION		SSPR	
•	66=((AMAX31-AMIN31)=K1+AMIN	· · · == ·	SSPR	
	TT=((AMAX32-AMIN32)=K2+AMIN		SSPR	
	HOURS=TT/60.		SSPR	5/0
	98=.264#GG+1.402		33PR	360
	DO=.144#G60862	the second of	33FK	274
	PFV=00+(1EXP(-TT=+.5/88))		SSPR	600
	- 33=1.0-PFV		SSPR	610
	TIME(11,12)=HOURS	• • • • • • • • • • • • • • • • • • • •	SSPR	620
	IF (81) 170,170,340		SSPR	
170	60 TO (180,190,200,210), I1		SSPR	
100	CT(1,12)=(0.15)=HOURS	•	33PR	
•		· · · · · · · · · · · · · · · · · · ·		
	60 TO 350	the state of the s	SSPR	
199	CT(2,12)=(0.15)#HOURS	· · · · · · · · · · · · · · · · · · ·	SSPR	
	GO TO 350	•	4400	440

500	CT(3,28)=HOURS	SSPR	490
	80 TO 380	SSPR	700
210	CT(4,12)*HOURS	SSPR	710
		SSPR	720
220	CONTINUE	SSPR	730
e 1	CONTINUE TEST FOUR: SINE-SMEEP VIBRATION(SSVIB) TYPE (AMMYAR-AMTINA) TO SAMTINA DE TYPE (AMMYAR-AMTINA DE TYPE AMAYAR) / (TYPE)	1570	740
_	TT=((AMAX42-AMIN42)=K2+AMIN42=ITV-AMAX42)/(ITV-1.)	5500	750
٠	MY BRITT/AA .	4500	740
•	MCUTTY-00. 88-((AMAX41-AMING))-K1+AMINGIWITV-AMAXG1)/(ITV-1.) 880176-864-7.097 D00635-86+.1065	1500	770
•	Bas allandar ser	4400	780
٠.	ROS DATEMERA 1945	2300	790
	00=.063S=60+.1065 PLR=00=(1EXP(-TT=+.8/86))	4400	400
	\$\$=1PAR	4400	810
•		SSPR	A20
C .	TIME(II,IZ)=HOURS		
•	CARO/HODULE LEVELS IF (81, 230,230,340	4400	840
230	AP 1847 (34)(33)(374	33PR	454
240		SSPR	930
244		33FR	
	00 70 350	SSPR	
254	CT(4 T2)=(0.35)=HOURS=CPHR	33PR	550
_	60 To 350	SSPR	
C	OO TU 350 EQUIPMENT/SYSTEM LEVELS	SSPR	
500	CT(3,12)=HOURS=CPHR	55PR	910
	60 TO 350	SSPR	920
270	CT(4,12)=HOURS=CPHR	SSPR	930
	60 TO 350	SSPR	940
280	CONTINUE	SSPR	950
C	TEST FIVE: SINE-FIXED VIBRATION (SFVIB)	SSPR	760
	TT=((AMAXS2-AMINA)+(SEMINA-VTI#SEMINA-SEMINA-SEXAMA))=TT	SSPR	970
	GB=((AMAXS1-AMINS1)=K1+AMINS1+ITY-AMAXS1)/(ITY-1.)	SSPR	760
	HOURS=TT/60.	SSPR	770
	88417-6+6.620	SSPR	1000
	00=.0435=6+.324	SSPA	1010
	PURR=00#(1EXP(-TTH#.2/88))	SSPR	1020
	\$\$=1MAR	SSPR	1030
	TINE(II, IZ)=HOURS	SSPR	1040
C	CARD/HOOULE LEVELS	SSPR	1050
	IF (81) 290,290,340	SSPR	1040
270	CT(3,I2)=HOURS=CPHR 60 TO 356 CT(4,I2)=HOURS=CPHR 60 TO 356 CONTINUE TEST FIVE: SINE-FIXED VIBRATION (SFVIB) TT=((AMAXS2-AMINS2)=K2+AMINS2=ITV-AMAXS2)/(ITV-1.) 684((AMAXS1-AMINS1)=K1+AMINS1=ITV-AMAXS1)/(ITV-1.) HOURS=TT/60. 884-A1946+0.620 504-A1946+0.620 605-A1946+0.620 606-A1946+0.620 607-A1946+0.620 607-A1946+0	SSPP	1070
300	CT(1,12)=(0.15)=HOURS=CPHR	SSPR	1080
	90 T0 359 CT(2,22)=(0,15)**HOURS**CPHR	SSPR	1090
210	61181481-14.731-MOK3-CLUK	33FK	7700
	GO TO 350 EQUIPMENT/SYSTEM LEVELS CT(3.12)=HOURS*CPMR	SSPR	1110
C	EQUIPMENT/SYSTEM LEVELS	SSPR	1120
329	CT(3,I2)=HOURS=CPHR	SSPR	1130
	CT(3,12)=HOURS+CPHR 80 TO 350	SSPR	1140
330	CT(4,12)=HOURS*CPHR	SSPR	1150
,	80 TO 350 CT(I1:I2)=81#HOURS+A1 CONTINUE	SSPP	1160
340	CT(I1,I2)=81+HOURS+A1	SSPR	1170
350	CONTINUE	SSPR	1180
	00 360 I=1,NCYC P(I,II,I2)=SS IF (HOURS.EQ.0.0) P(I,II,I2)=1.0 RETURN	SSPR	1190
	P(1,11,12)=55	SSPR	1200
340	IF (HOURS.EQ.0.0) P(I,I1.I2)=1.0	SSPR	1210
	RETURN	SSPR	1220
	RETURN		

```
SUBRUITINE REPORT (MINCYCINISCRIPDEFIDINIADEFICPHRIPIFIRIARE,CTICREM) 10
      IR1.CR2.IAPRAY.A1.81.ITV.TCHIN,TSHAX,NPARTS,XNOP,XLAHP1,XLAHP2,XLAHREPO
                                                                                   20
      ECI, XLAMCE, X, AMAXII, AMINII, AMAXIE, AMINIE, AMAXEI, AMINEI, AMAXEE, AMINEREPO
                                                                                   30
      32, AMAXE3, AMINE3, AMAXE4, AMINE4, EKAMA, ERITHA, ESXAMA, ESMIMA, ESXAMA, SE
      (Serima, Sexama, Ienima, Iexama, Sahima, Sexama, 14mima)
                                                                            REPO
                                                                                  50
       PEAL LCOST(5)
                                                                            REPO
       DIMEMSION AMAXIL(3), AMINIL(3), AMAXIZ(3), AMINIZ(3), AMAXZ1(3), AREPO
                                                                                   70
      HINER(3), AMAX22(3), AMINER(3), AMAX23(3), AMINER(3), AMAX24(3), AREPO
2MINER(3), AMAX31(3), AMIN31(3), AMAX32(3), AMINER(3), AMAX41(3), AREPO
                                                                                   80
                                                                                   90
      SMINHL(3), AMAX42(3), AMINH2(3), AMAX51(3), AMIN51(3), AMAX52(3), AREPO 100
                                                                            PEPO 110
     DIMENSION NP(5,5,5), N(5), P(11,4,5), F(11,4,5), ISCR(3), 1R1(11,4,5), R2(11,4,5), CR1(5,5), CR2(5,5), CT(5,5), SCOST(5,5), 2TEST(5), IR(5), IARRAY(20), ANP(5,5,5), AOEF(5), TIME(3,5),
                                                                            REPO 120
                                                                            REPO 130
                                                                            REPO 140
      +X(11,4,57
                                                                            REPO 145
                                                                            REPO 150
                            DATA NP/125+1/
                                                                            REPO 160
                                                  _____
      DATA LCOST/S=0./
DATA TEST/'CT ','CYT ','RVIB','SSVB','SFVB'/
                                                                            REPO 170
                                                                            REPO 180
      DATA ANP/125+0./
1=0
DO 130 I1=1,M
                                                                            REPO 190
                                                                            REPO 200
                                                                            REPO 220
      10
      IF (IR(K-1)) 30,30,20
                                                                            REPO 320
      MP(I1,I2,4-K)=INT(FLOAT(IR(K-1))/(FLOAT(ITY))==(3-K)+.999999)
20
                                                                            REPO 330
      60 TO 40
NP(I1,I2,4-K)=ITV
                                                                            REPO 340
30
                                                                            REPO 350
40
      CONTINUE
                                                                            REPO 360
      60 TO 120
                                                                            REPO 370
  88
      DO 70 K=2,4
      DO 70 K=2,4
IR(K)=NOO(IR(K-1),ITV=+(4-K))
                                                                            REPO 390
      IF (IR(K-1)) 60,60,50

NP(II,IZ-5-K)=INT(FLOAT(IR(K-1))/(FLOAT(ITV))**(4-K)+.999999)
                                                                            REPO 400
50
      50 TO 70

NP(II,I2,S-K)=ITV

CONTINUE

GO TO 120

DO 110 4-0 7
                                                                            REPO 410
                                                                            REPO 420
                                                                           REPO 430
70
                                                                            REPO 440
                                                                           REPO 450
80
      00 110 K=2,5
                                                                           REPG 460
      00 110 K=2,5
IR(K)=M00(IR(K-1),ITV++(5-K))
7E (7E(K-1)) 100 100 00
                                                                           REPO 470
      IF (IR(K-1)) 100,100,90

MP(I1,I2,6-K)=INT(FLOAT(IR(K-1))/(FLOAT(ITV))==(S-K)+,999999)
                                                                            REPO 460
98
                                                                            REPO 490
      60 TO 110
                         REPO 500
      HP(11,12,6-K)=ITV
100
                                                                           REPO 510
110
      CONTINUE
      60 TO 120
                                                                           REPO 530
     CALL SSPROB (NP(II,I2,1),NP(I1,I2,2),NP(II,I2,3),NP(II,I2,4),II,I2REPO 540
1.P.NCYC.CT.A1.81.ITV.HOURS.CPHR.TIME,AMAX11(II),AMIN11(II),AMAX12(REPO 550
```

```
EII).AMIN18(II).AMAX21(II).AMIN21(II).AMAX22(II).AMIN22(II).AMAX23(REPO 560
    311).AMIN23(11),AMAX24(11).AMIN24(11),AMAX31(11),AMIN31(11),AMAX32(REPO 570
    411), AMIN32(11), AMAX41(11), AMIN41(11), AMAX42(11), AMIN42(11), AMAX51(REPO 580
    SII), AMINS((II), AMAXS((II), AMINS((II))
                                                           REPO 590
     CONTINUE
                                                           PFP0 600
     CALL SCREEN (MCYC,M,M,PDEF,DIN,ADEF,P,F,R1,R2,CT,CR1,CR2,S,SM,FCOSREPO 610
    17, 11, 12, SCOST, TCHIN, 1.0, TIME, NPARTS, XNOP, XLAMP1, XLAMP2, XLAMC1, XLAMREPO 620
    2C2.X1
                                    . .... REPO 630
     00 140 I1=1.H
                                                           PFPO 640
                   DO 140 I2=1.5
                                ..........
                                                           REPO 450
     LCOST(I1)=LCOST(I1)+SCOST(I1,I2)
140
                                                           BEPO 660
     IQEO
                REPO 670
     HRITE (6.260)
                                                           DEBO AAD
                   00 250 Il=1.M
                                                           DEPO A90
     AMP(I1,4,1)=((AMAX41(I1)-AMIM41(I1))MMP(I1,4,1)+AMIM41(II)#ITV-AMAREPO 700
    1X41(I1))/(ITV-1.)
                                                           REPO 710
     AMP(II.1.1)=((AMAX11(II)-AMIN11(II))*MP(II,1,1)+AMIN11(II)*ITV-AMAREPO 720
    1X11(I1))/(ITV-1.)
                                                           REPO 730
     AMP(II,1,2)=((AMAXI2(II)-AMINI2(II))*MP(II,1,2)+AMINI2(II)*ITV-AMAREPO 740
    1x12(11))/(1TV-1.)
                                                           REPO 750
     AMP(II,5,1)=((AMAX51(II)-AMIN51(II))=MP(II,5,1)+AMIN51(II)=ITV-AMAREPO 760
    1X51(I1))/(ITV-1.)
                                                           REPO 770
     1X52(11))/(1TV-1.)
                                                           REPO 790
     AMP(I1.2.1)=(AMAX21(I1)-AMIN21(I1))=MP(I1.2.1)+AMIN21(I1)=ITV-AMAREPO 800
    1x21(11))/(1TV-1.)
                                                           PEPO ALO
     AMP(I1,2,2)=((AMAX22(I2,-AMIN22(I1))+MP(I1,2,2)+AMIN22(II)+TTV-AMAREPO 820
    1x22(11))/(TTV-1.)
                                                           SEPO A30
     1X23(11))/(ITV-1.)
                                                           REPO 850
     ANP(I1,2,4)=((AMAX24(I1)-AMIN24(I1))****(I1,2,4)**AHIN24(I1)**ITV-AMAREPO 860
    1X24(I1))/(ITV-1.)
                                                           REPO 870
     AMP(I1,3,1)=((AMAX31(I1)-AMIN31(I1))*MP(I1,3,1)+AMIN31(I1)*ITV-AMAREPO 880
    1X31(11))/(1TV-1.)
                                                           BEPO 890
     000 099MA-VTIW([I]:SWIMA+(2.5.1) PWP([I]:SWIM32(II) PTV-AMAREPO
    1x32(11))/(1TV-1.)
                                                           BEPO 916
     AMP(II,4,2)=((AMAX42(II)-AMIM42(II))*MP(II,4,2)+AMIM42(II)*ITV-AMAREPO 920
    1X42(II))/(ITV-1.)
                                                           REPO 930
     KTT=2
                                                           REPO 940
     IF (ISCR(II).EQ.2) KTT#4
                                                           REPO 950
                                       WRITE (13,*) AMP(I1, ISCR(I1), KTT)
                                                           8FP0 960
                                        DO 250 I2=1.5
                                                           REPO 970
                                          60 TO (150,160,170,180,190), IZ
                                                           PEPO 960
                                    150
     IF
       005 OT 00 (0.93.(5,1,11)9MA)
                                      PEPO 990
       TO 220
                                                           REP01000
160
     IF
       (AMP(11,2,3),EQ.0) 60 TO 200
                                                           REP01010
       TO 220
     60
                                                           REP01020
                                         .
                                              . . . . . .
170
     IF
       (AMP(11,3,2).EQ.0) GO TO 200
                                                           #FP01030
       TO 220
                                                           REPO1040
180
     IF
       (AMP(11,4,1).EQ.0) 60 TO 200
                                    #EP01050
     60 TO 220
                                                           REPO1060
190
     IF (AMP(I1,5,1).EQ.0) GO TO 200
                                                           REPO1070
     60 TO 220
                                       .
                                                           #EP01080
200
     DO 210 K=1,4
                                                           REPO1650
210
     ANP( 11, 12, K)=0.
                                                           REPO1100
```

228	IF (I1-I9) 240,240,230 MRITE (6,270) II,LCOST(II) IF (ISCR(II).NE.Z2) GO TO 250	REP01110
230	WRITE (6,270) II.LCOST(II)	REP01120
240	IF (ISCR(I1).NE.I2) GO TO 250	REP01130
_	MRITE (6,280) I2, TEST(I2), (AMP(II, I2,K),K=1,4),SCOST(I1,I2)	REP01140
250		PERO1150
		BEBOILE
	BARLIN MINNEY	REPULLOU
		REP01170
_	RETURN	REP01180
C		
260	FORMAT (1X///////29X, 'T E S T D E S C R I P T I O N'/39X, 'PA	
	IAMETER VALUE'/10X,'TEST SEGUENCE',5X,'TYPE',2X,'NO. 1',2X,'NO. 2'	,REP01210
	22X, 'NO. 3',2X, 'NO. 4',2X, 'TOTAL COST', '(\$)'/7X,66('_')//)	REPO1220
270		REP01230
280		REP01240
290	FORMAT (' ',7X,67('_')//' ',8X,'TOTAL',' COST',41X,'\$',F12.0//' '	
• • •	1410 1941 1121 1 410 1941 111	REP01260
	END	REP01270
	•	
	SUBROUTINE DATA (NCYC,M,PDEF,CREGO,E,ITV,N,ADEF,CPHR,P,F,R1,R2,CR	
	1.CR2,XMTBF, LEVEL, ITYP, AMAXII, AMINII, AMAXI2, AMINI2, AMAX21, AMIN21, A	
	nima, sexama, lenima, lexama, pshima, psxama, esnima, esxama, sskima, ssxas	
	32, Amax41, Amin41, Amax42, Amin42, Ahax51, Amin51, Amax52, Amin52, NPART5)	
	DIMENSION H(5), ADEF(5), P(11,4,5), F(11,4,5), R1(11,4,5),	DATA 50
	l CR1(5,5), CR2(5,5), AMAX11(3), AMIN11(3), AMAX12(3), AMIN12(3),	ADATA 60
	2MAX21(3), AMIN21(3), AMAX22(3), AMIN22(3), AMAX23(3), AMIN23(3),	ADATA 70
	3MAX24(3), AMIN24(3), AMAX31(3), AMIN31(3), AMAX32(3), AMIN32(3),	
	4MAX41(3), AMIN41(3), AMAX42(3), AMIH42(3), AMAX51(3), AMIH51(3),	
		DATA 100
		DATA 110
		DATA 120
• •	IF (PDEF) 10,10,20	DATA 130 DATA 140
10	PDEF=0.001=HPARTS	DATA 140
	GO TO 30	DATA 150
20	POEF*POEF*NPARTS	0ATA 150 0ATA 160
30	no en 1-1'u	DATA 170
	READ (4,#,2H)=40) ADEF(I) TE (ADEF(I)) 40.40.50	DATA 180
		DATA 190
46	ADEF(I)=.005=HPARTS	DATA 200
	80 10 9B	DATA 210
50	ADEF(I)=ADEF(I)=HPARTS	DATA 210 DATA 220
60	ADEF(I)=ADEF(I)=NPARTS CONTINUE	DATA 230
	HEITE (6.470)	DATA 240
	SEAS (E M) TYANIE	DATA 250
	IF (ITABLE.LT.1) 60 TO 90	DATA 240
	17 (1/ABCE: C1:17 GU 10 70	DATA 260
	IF (CREOD.GE.9.E9) GO TO 70	DATA 270
	IF (CREWIGE, 7.27) GU /U /U	DATA 280
		DATA 290
	60 IU 60	DATA 300
_70	RELIZ (0,400) REARIS, IT, PUEP	DATA 310
80	KRITE (6.510)	DATA 320
	MRITE (6,530) (I,ADEF(I),I=1,M)	DATA 330
90	00 148 I1=1,M	DATA 340
		DATA 350
		DATA 360
	IF (P(1.I1,I2)) 100,100,120	DATA 370
100	00 110 I=1,NCYC	DATA 380
	The same accordance and the same same same same same same same sam	DELETE

110	P(I,II,I2)=1.0	DATA	390
	60 TO 146 80 136 I=1,NCYC	DATA	410
20	00 130 1=1,NC1C	DATA	410
30	P(I,II,I2)=P(1,II,I2)	DATA	420
140	CONTINUE 00 196 11=1,H	DATA	730
	00 170 11=1;n	DATA	450
	00 190 12=1,5 READ (8,+,END=150) F(1,I1,I2)	. DATA	444
	REAU (OIM)ERUPIDO / P(I)II)IE/	DATA	470
50	Th (1,11,17,15) 130,120,170	, UAIA	7/0
.50	00 160 I=1,NCYC	DATA	400
	F(I.1.12)=0.0	DATA	77U
	P(I,2,I2)=0.0	DATA	500
4.4	P(I,3,I2)=0.0	DATA	210
	F(I,4,I2)=0.0	DATA	320
-	60 TO 190 DO 180 I=1,NCYC F(I,II,I2)=F(1,II,I2)	. UAIA	230
70	DO 100 1=1,NGTC	. UATA	
180	P(1;11;2)=P(1;11;12)	DATA	550
90	CONTINUE DO 290 II=1,M DO 290 IZ=1,5	DATA	200
	DO 290 II*1,n	DATA	570
	00 270 IZ*1,5	DATA	580
	00 290 12=1,5 READ (9,*,END=200) R1(1,I1,I2),R2(1,I1,I2)	DATA	590
	#F (#4(4)41)46// EUO/EUO/EEO	VAIA	900
00	DO 210 I=1.NCYC	DATA	610
:10	R1(I,I1,I2)=0.5	DATA	620
	, 60 TO 240	DATA	630
20	00 230 I=1,NCYC	DATA	640
:30	_ R1(I,II,I2)=R1(1,I1,I2)	DATA	650
:40	GO TO 240 DO 230 I=1,NCYC R1(I,II,I2)=R1(I,II,I2) IF (R2(1,II,I2)) 250,250,270	DATA	660
:50 .	DO ZBO IVI.NETE	DALA	6/U
:60	R2(1,11,K2)=0.5	DATA	680
	60 TO 290	DATA	690
70	DO 280 I=1,NCYC	DATA	700
:50	R2(I,I1,K2)=0.5 80 TO 290 DO 280 I=1,NCYC R2(I,I1,I2)=R2(I,I1,I2)	DATA	710
: 90 .	CONTINUE 00 430 II=1,H	DATA	720
	DO 430 I1=1,H	DATA	730
	00 430 12=1,5	DATA	740
	00 430 I2=1,5 READ (4,*,EMD=300) 82,83 IF (82) 300,300,350 GD TO (310,320,330,340), I1	DATA	750
	IF (82) 300,300,350	DATA	760
500	GO TO (310,320,330,340), I1	DATA	. 770
310	CR1(1,12)=0.0	DATA	780
	GO TO (310.320,330,340), I1 CR1(1,I2)=0.0 GO TO 340 CR1(2,I2)=0.0 GO TO 340 CR1(3,I2)=0.0 GO TO 340 CR1(4,I2)=0.0	DATA	790
3 29	CR1(2,I2)=0.0	DATA	800
	60 TO 360	DATA	810
330	CR1(3,I2)=0.0	DATA	820
	60 TO 360	DATA	830
340	CR1(4,I2)=0.0	DATA	640
		VA . A	030
350	CR1(I1,I2)=82 IF (83) 370,370,420 GO TO (360,390,400,410), I1	DATA	860
360	IF (B3) 370,370,420	DATA	870
370	GO TO (380,390,400,410), I1	DATA	880
380	CR2(1.12)=45. 80 TO 430	DATA	890
	80 70 430	DATA	900
390	CR2(2, 12)=300.	DATA	710
	60 TO 430	DATA	920

	60 TO 430		DATA 940
410	CKELAITE 1-0.0		UAIA 734
	60 TO 430		DATA 960
420	CR2(11,12)=83 CONTINUE		DATA 970
430			DATA 960
	IF (ITABLE.LT.1) GO TO 440		
			DATA1000
	MRITE (6.540) MRITE (6.490) (J.CR2(J.1) DO 450 I=1.HCYC	.J=1,H)	DATALOLO
440	DO 450 I=1,HCYC	A CONTRACTOR OF THE CONTRACTOR	DATA1020
-			DATA1030
	NJ=N(J)		714741760
	DO 450 J=1,M NJ=N(J) DO 450 K=1,NJ		DATA1050
	F(I,J,K)=F(I,J,K)		DATA1060
	R1(I,J,K)=R1(1,J,K)		DATA1070
450		the second contract of	DATALOSO
	00 460 IZ=1,M		DATA1090
c •	TEST ONE: CONSTANT TEMPERATE	DF	DATAILOS
- '	READ (12.*) AMAX11(12),AM	TN11(12)	DATA1110
	PPAR (19,41 AMAVISTER AM	IN11(12) TN19(T7)	DATALLEO
c 1	READ (12,*) AMAX12(1Z),AM1 TEST TWO: CYCLED TEMPERATURE		
- 1			DATA1130
	READ (12:#) AMAX21(1Z),AM1		DATALISO
	READ (12.*) AMAX22(12),AM		DATALISO
	READ (12,*) AMAX23(1Z),AM1		DATA1160
	READ (12.*) AMAX24(IZ),AMI		DATA1170
C T	EST THREE: RANDOM VIBRATIC		DATA1180
	READ (12,*) AMAX31(1Z),AM1		DATAL190
	READ (12, #) AMAX32(IZ),A"		DATALEGO
C T	TEST FOUR: SINE-SHEEP VIBRAT		DATA1210
	READ (12,#) AMAX41(IZ),AM	INGL(IZ)	DATA1220
_	READ (12,+) AMAX42(12),AM		DATA1230
C T	'EST FIVE: SINE-FIXED VIBRA1	TION	DATA1240
	READ (12,#) AMAX51(IZ),AM1	TN51(IZ)	DATA1250
	READ (12,+) AMAX52(12),AM1	IN52(IZ)	DATA1260
460	CONTINUE		DATA1270
	RETURN		DATALZEG
Ç			DATA1290
470		SH A TABLE OF INPUTS ENTER 1, IF MOT,','	
	1EHTER ZERO: ')		DATA1310
480	FORMAT (' ',5X,17,5X,11,4)	X,F13.0,12X,'NA',13X,'NA')	DATA1320
490	FCRMAT (17X, LEVEL', 13,30)	K,F10.0)	DATA1330
500		OGRAM DATA'/' ',80('_')/' ',7X,'MPARTS',	
		ARTS)',6X,'CREGD',10X,'HTBF'/' ',80('-')	/DATA1350
	2/1		DATA1360
510	FORMAT (1X////33X, ASSET	"BLY DATA"/" ",80("_")/" ",8X,"ASSEMBLY	LDATA1370
	1EVEL',2X,' ',2X,'EXPECTED	NUMBER OF ASSEMBLY DEFECTS'/' ',8X,14('	
	2'),5X,35('_')//)		DATA1390
520	FORMAT (' ',5X,17,5X,11.4X	<pre><,f13.0,2x,f13.2,5x,2x,f13.0)</pre>	DATA1400
530	FOPMAT (' ',11X,12,27X,F9.		DATA1410
540		(','COST '/' ',80('_')//)	DATA1420
-	EHO	• • • • • • • • • • • • • • • • • • •	DATA1430
	SUBROUTINE HEAN (XN, XLAMB,	XNP, T, OHSS, FALL)	MEAN 10
	IF (0755.GT.0.999) GO TO 1		MEAN 20
	IF (T.LE.1.E-9) GO TO 10		MEAN 30
	A0=XN#XLAMB		MEAN 40
	A1*XNP	· · · · · · · · · · · · · · · · · · ·	MEAN 50

	RK=-ALOS(OHSS)/(XLAHS+T)																			MEAN	68	
	AZ=RK+XLAMB	• •	• •	٠.	•	 ٠.	٠.	•	•		٠	•	• •	•	•	• •	•		•	HEAN	70	
	PALL=AUDT+AID(1EXP(-A2DT																					
		,,					٠.		• •	•	•	• •	٠	•		٠.	4	•				
	60 TO 20					-						•	٠.				•	• • •	• •	MEAN	144	
16	FALL=0.0													٠			٠					
20	RETURN																					
	ENO																			HEAN	120	

PROGRAM LISTING FOR ADAPT. FORT

```
DIMEMSION ADEF(5), ISCR(3), TIME(3), TB(3), COME(3), ON(3), PFALL(MAIN 1, 171, MTALL(3), AFALL(3), APFALL(3), AMFALL(3), F(3), MARK(3), MARK(MAIN 2, 1813), EL(3), PBL(3), BU(3), PBU(3), HBU(3), TSL(3), AT(3), MAIN 3, AMTOF(7,7), FREM(7), MREM(7)

FLAGEO.0 MAIN 50

READ (2,4) ISCR.M.MPARTS.POEF,ADEF

READ (1,7) ISCR.M.MPARTS.POEF,ADEF

READ (1,7) ISCR.M.MPARTS.POEF,ADEF
      MAIN
                                                                           MAIN
                                                                           MAIN 100
                                                                           HAIN 110
                                                                           MAIN 120
10
      CC::TINUE
                                                                           MAIN 130
      #2A0 (2.#) CCME(1),COHE(2),COME(3)
                                                     MAIN 140
      READ (2.4) OH(1).OH(2).OH(3),PLEFT
                                                                           MAIN 150
      171TE (6,260)
                           MAIN 160
      Ct:3=(Ct:(3)-PLEFT)
                                                      MAIN 170
      DO 20 KK#1.7
                                                                           MAIN 180
      PREMIKKIS(AMAXIO., PLEFT-4.+FLOAT(KK)))
                                                                           MAIN 190
      INSMIKE JERNANICO., OHS-4. *FLOAT(KL))
                                                                           MAIN 200
                                                                           MAIN 210
      ANT3F(KK,KL)=(XNOF-LREM(KL))=XLANC1+(FLOAT(NPARTS)-PREM(KK))=XLANPMAN 220
     ATTOCKER DE MANGE PREMIUK DE MALAMPS
      AMTEFICK, XL)=1./AMTBF(KK,KL)
                                                                           MAIN 240
20
      CONTINUE
      CONTINUE
MRITE (6,270) WIEH
                                                                           MAIN 250
                                                                           HAIN 260
      00 30 KX=1,7
                                                                           MAIN 270
      LMITE (6.280) PREH(KK),(AMTBF(KK,KL),KL=1,7)
30
                                                                           MAIN 280
      WAITE (6,270)
                                                                           HAIN 290
      READ (5.4) INTER
IF (INTER.GT.0) GC TO 40
                                                                           MAIN 300
                                                      HAIN 310
      PER=.99
                                                                           MAIN 320
      GO TO 50
                                                                           HAIN 330
40
      WITE (6,300)
                                                                           MAIN 340
      READ (5.4) PER
                                                                           MAIN 350
50
      MITE (6,310)
                                                                           MAIN 360
      CO 60 K=1.3
                                                                           HAIN 370
      F(K)=CC.IE(K)-ON(K)
                                                                           MAIN 380
60
      CONTINUE
                                                                           MAIN 390
      PFALL(1)=IFIX((PDEF*(COME(1)-ON(1)))/COME(1))
                                                                           MAIN 400
      MFALL(1)=CCME(1)-OM(1)-PFALL(1)
                                                                           MAIN 410
      PFALL(2)=IFIX((FDEF-FFALL(1))+(COME(2)-ON(2))/COME(2))
                                                                           MAIN 420
      MFALL(2)=CCME(2)-CM(2)-PFALL(2)
                                                                           MAIN 430
      FFALL(3)=IFIX((PDEF-PFALL(1)-PFALL(2))+(CCME(3)-CM(3))/CCME(3))
                                                                           MAIH 440
      MTALL(3)=COME(3)-CH(3)-PFALL(3)
                                                                           MAIN 450
      IF (FLAG.GT.0.0) PLEFT=POEF-PFALL(1)-PFALL(2)-PFALL(3)
                                                                           MAIN 460
      HLEFT=CH 31-PLEFT
                                                                           MAIN 470
      MOSTE (6,320)
                                                                           MAIN 480
      MITE (6.330)
                                                                           MAIN 490
      MRITE (6,320)
                                                                           MAIN 500
      MRITE (6.350)
                                                                           MAIN 510
      MRITE (6,560) HPARTS, ADEF(1), ADEF(2), ADEF(3), PLEFT
                                                                           MAIN 520
      INITE (6.370)
                                                                           MAIN 530
      MITTE (6,380)
      RITEF=( XHOP-HLEFT ) #XLAHCL+( FLOAT( NPARTS) - PLEFT) #XLAMP1+HLEFT#XLAMCHAIN 550
```

12+PLEFTWXL	AMP2	MAIN !
RMTBF=1./R	NTBF	MAIN !
1271TE (6.3	HTBF 90) PDEF,TS(1),TS(2),TS(3),HLEFT	MAIN :
WRITE (4.3	40)	MAIN !
LRITE (6.4	661	MATM
LETTE	00) 10) ON(1),ON(2),ON(3),RHTBF	MATM
IMPTO (4 1	10) Out 1) Out 2) Out 3) Muist	MATM
MICIE (4)2		
SRITE (6,3		LINTH (
KRITE (6.4	20)	LINTL (
LRITE (6,4	20)	MAIN (
WRITE (6,4	301	MAIN (
MRITE (6,4	40)	MAIN (
WITE (6,4		MAIN 6
1271TE (6.4	50)	MAIN (
WITE (6.4	70)	MAIN '
MRITE (6.4	· · · · · · · · · · · · · · · · · · ·	MATM '
	••••••••••••••••••••••••••••••••••••••	MATM
AT 16 1017	50)	MATER S
DC 90 [7s]	,3 (F(IJ),2\:IJ),B'(IJ),PER) (PFALL(IJ),PBL(IJ),PBU(IJ),PER)	MAIN .
CALL BOURD	(F(IJ),21:IJ),Br(IJ),PER)	TAIN :
CALL BOUND	(PFALL(IJ),P8L(IJ),P8U(IJ),PER)	HAIN ?
CYLL EGIND	(%FALL(IJ),KDL(IJ),MBU(IJ),PER)	MAIN 7
CONTINUE	90) PFALL(1),HFALL(1),F(1),PFALL(2),HFALL(2),F(2),PFALL(MAIN 7
LTITE (6,4	90)	MAIN 7
13),#FALL(3	;,F(3)	MAIN :
TRITE (6.4	60)	MAIN &
SRITE 16.5	20)	MATN A
LETTE (A.S	10)	MATN A
151778 (4 A	10)	MAIN &
UNTER 14 A	60) 90) PBU(1),KBU(1),BU(1),PBU(2),KBU(2),BU(2),PBU(3),KBU(DALTH C
1),89(3)	,	HAIN C
KRITE (6.4	60)	MAIN &
MITTE (6,5	<u> </u>	MAIN 8
ERITE (6,5	10)	MAIN 8
\$ 127E (6,4	50)	MAIN &
LRITE (6,4	50) 90) PBL(1),KBL(1),BL(1),PBL(2),KBL(2),BL(2),PBL(3),KBL(1	MAIN 9
11.36(3)		MAIN 9
WRITE 16.4	50)	MAIN 4
177TE (6,4		MAIN C
IF (FLAG.G	7.0.0) 60 TO 180	MATH S
CO TO 90		MATN C
CALL THE C	AMD NOADTE DIEET ANIET VIAMOT VIAMOT VIAMOT VIAMOT	MATEL O
IMPTE IA E	CNOP,NPARTS,PLEFT,ON(3),XLAMP1,XLAMP2,XLAMC1,XLAMC2)	MATE A
		HATH ?
MEAU (3,7)	1AUAPT LT.1) GO TO 220	MALIN S
IP TIAUAPT	LT.1) GO TO 220	MAIN 9
FRITE 16.5	101	MAIN1
FEAD (5,#)	00) IFALL 97.0) GO TO 120	MAIN1
IF (IFALL.	FT.03 GO TO 120	MAIHIC
LATTE (6,5	50) AFALL(1),AFALL(2),AFALL(3)	MAIN10
READ (5,*)	AFALL(1), AFALL(2), AFALL(3)	MAINIO
ICUE=0	.3	MAINIO
CC 110 Ta1	3	MATNI
MARK(T)=n	The state of the s	MATHI
TR (ARALLA		
CONTINUE	().LT.BL(I)) MARK(I)=1	MATURE
	73 1 M 180 (A 1 . M 180 (3)	HAINIC
CONTINUE	(1)+MARK(2)+MARK(3)	MAINL

TE (MACKY IS A) CA TA 944	r.e)) 60 TO 140	MA TM
PALL METAN (MINU PANE AL TE	APALL, F, TIME, XLAMP1, MPARTS)	MATN
CALL NOTCE (HARKICOME) ON, 15,	WANTELL LITTE IN THE THE WALLS !	MA TAP
PLAS-1.0	Secure and the second s	MALIN.
MAITE (0,500)		LINTL.
GO 10 70		LWTL'
M27110 18.4/01		DEATH.
IFH=0	1	MAIN:
00 130 I=1.3		MAIN:
MRITE (6,550) I		MAIN
READ (S.W) AFFALL(T).AMFALL()	I)	MAIN
AFAILIT1R3PPALLIT1AAUPALLIT1	· · · · · · · · · · · · · · · · · · ·	MALN.
CONTINUE		MATH
TCHES		MATN
CO TO 144		MA TM
60 10 100		MA TH
An 1/4 1s1'2		TIALIT.
IF (APPALL(I).GE.PBL(I)) GO	TO 150	MALN.
PFALL(I)*APFALL(I)		HAIN
MFALL(I)=AMFALL(I)		MAIN
MARKFU(I)=1		MAIN
IF (AMFALL(I), GE, MBL(I)) GO	TO 160	HAIN
MFALL(T) EAUFALL(T)	** ** *	MATM
BEALLY THANKALLY		MA TO
PTALLUI I PAPTALLUI I		MA TAI
PARKARITAT		HALIN
AFALLII)=PFALLII)+HFALLII)	and the second second second	MAIN
CONTINUE	PH(3)	MAIN
IPH=MARKPH(1)+MARKPH(2)+MARK	PH(3)	MAIN
IF (IFM.EQ.0) GO TO 240		MAIN
CALL KUFLOW (MAPKPW, COME.ON.	PH(3) T3,AFALL,F,TIME,XLAN/4,MPART5,	MAIN
FLAG#1.8		MAIN
LTITE (6.560)		MAIN
GO TO 70		MAIN
7# (TPU (T.1) 60 TO 200		MATH
NA 16A 191.1		MATH
MARKET INCHARACTURE IN		MATU
MARK (J)=MARKPM(J)	A REAL PROPERTY OF THE PROPERT	MATE
CONTINUE	$(\mathbf{r}_{i}, \mathbf{r}_{i}, r$	LINTH
CO 210 Ja1.3		HATN
IF (MARK(J).LT.1) GO TO 210	and the second s	MAIN
CALL SOLVE (J. ISCR. TS. TSI. AT)	MAIN
CCTITUE		MAIN
LETTE (6.590)		HAIN
READ (5.4) IEQ		MAIN
IF (1E2.LT.1) GO TO 230		MAIN
CALL FOUTY (TEQ)		MATN
	and the second of the second o	MATH
MILE 1014347	$(\mathbf{v}_{i},$	MATE
KIRU (D)FI ALUTP		UNTN
. IF FTC1517.LT.1) 60 TM 240		MAIN
1 12000 10 10 10 10		MAIN
XIP=QI(2)+ADEF(3)		MAIN
CALL RUFLOW (MARKPW, COME, ON, FLEGE1.0 LETTE (6.560) GO TO TO IF (IPW.LT.1) GO TO 200 DO 190 J=1.3 MARK(J)=MARKPW(J) CONTINUE DO 210 J=1.3 IF (MARK(J).LT.1) GO TO 210 CALL SOLVE (J, ISCR, TS, TS1, AT CC'TTINUE LETTE (6.590) READ (5,*) IEQ IF (IEQ.LT.1) GO TO 230 CALL ECUTV (IEQ) LETTE (6.250) READ (5,*) ICUMF IF (ICULE, LT.1) GO TO 240 XIPPON(2)+ADEF(3) CALL FILME (NPARTS, XLAMP1, XN	ip,T3(3),TIME(3))	
X:P=CN(2)+ADEF(3) CALL FTIME (NPARTS,XLAMP1,XN STOP	ip,TS(3),TIME(3))	MAIN
	ip,TS(3),TIME(3))	
		MAIN

```
JS AT END OF SCREENING'///28X,' WORKMANSHIP')
FCRMAT (1X,' PARTS [',7(4X,F5.0)/1X,72('-'))
FCRMAT (1X,F7.0,1X,'[',7(4X,F5.0))
                                                       ..... MALN1660
270
                                                                            MAIN1678
280
                                                                            MATH1680
     FORMAT (1X/////5X,'IF YOU WISH A .99 PROBABILITY INTERVAL, ENTER MAIN1690
1,' ZERO'/5X,'IF YOU WISH TO ENTER A SMALLER FROSABILITY (FOR',' A MAIN1700
290
      FORMAT (5X. ENTER PROBABILITY DESIRED: )
      SHARROHER INTERVAL) '/SX, 'ENTER GHE: ')
                                                                            MAIH1710
300
                                                                            MAIN1720
      FORMAT (//////25X, 'STRESS SCREENING FLOW DIAGRAM'//)
310
                                                                            MAIN1730
320
      FORMAT (1x,5(12('-'),3X))
                                                                            MAIN1740
      FORMAT (1X," INCOMING | ',3X," LEVEL 1 | ',3X," LEVEL 2 | ',3X, MAIN1750
330
     If LEVEL 3 |'.3X,'| OUTGOING |')
                                                                           MAIN1750
                                          340
      FORMAT (1X.5('|',10X,'|',3X))
                                                                            HAIH1770
350
      FORMAT (1X, '| #PARTS: | ',3X,3('| ADEF= ',4X,'|',3X), '| DEF P REM: | 'MAIH1780
                                                                            MAIN1790
      FORMAT (1x,'|',210,'|',3x,3('|',F10.0,'|',3x),'|',F10.0,'|')
360
                                                                           MAIN1800
370
      FCRMAT (1x.4('|',10x,'|-->'),'|',10x,'|')
380
      FCRMAT (1X, 1 #DEFECTS: 1',3X,3('|TS= |1',3X),'|','DEF W REM: |MAIN1820
                                                                            MAIN1830
      FCRMAT (1X, 1, F10.0, 1, 3X,3(1, F10.3, 1, 3X), 1, F10.0, 1)
390
                                                                            MAIN1840
      FCCMAT (1X,'|',10X,'|',3X,3('|DEF PASSED|',3X),'|HTBF: |')
FCCMAT (1X,'|',10X,'|',3X,4('|',F10.0,'|',3X))
400
                                                                            MAIN1850
410
                                                                            MAINIE60
      FCRMAT (21X.3(')',14X))
420
                                                                            MAIH1870
430
      FCRMAT (21X,3('V',14X))
      FORMAT (15%,3(14('-'),1%))
FORMAT (15%,3('| EXPECTED |',1%))
FORMAT (15%,3('|',12%,'|',1%))
440
450
                                                                            MAIN1900
                                 FALLOUT: [',1X))
460
      FCRHAT (15X,3(')
470
                                                                            MAIN1920
      FCRHAT (15X,3(') PRT NKH TOTI',1X))
420
                                                                            MAIN1930
490
      FORMAT (15X,3('[',3(F4.0),'[',1X))
                                                                           MAIN1940
500
      FORMAT (15X,3('|LCAR END FOR!',1X))
      FORMAT (15X,3('|C35 FALLOUT:|',1X))
510
      FORMAT (15X,3('|UPFR BND FOR!',1X))
520
                                                                           MAIN1970
      FORMAT (1X///5X, 'IF YOU HAVE FALLOUT METBERS ENTER 1, IF NOT', ', MAIN1980
530
     LENTER ZERO: ')
      FORMAT (5X, IF YOU HAVE SEPARATE FALLOUT FOR PARTS AND ', WORKMANSHAIN2000
     THIP ENTER CHE'/SX, 'IF YOU HAVE TOTAL FALLOUT CHLY AT', ' EACH LEVELMAINCOLD
     2, ENTER ZERO: ')
                                                                           MAIN2026
      FORMAT (5X, ' ENTER THE THREE ACTUAL FALLOUT MARBERS, IN GROER, ', 'MAIN2030
550
     IBY LEVEL: ')
                                                                           MATH2040
      FORMAT (1X////24X, 'STRESS SCREENING RESULTS: '///)
560
                                                                           MAIN2050
      FORMAT (5%, 'ENTER, IN ORDER, ACTUAL FALLCUT: '/5%, 'DUE TO (A)', 'MAIN2060
      PARTS (B) MCCKMANSHIP, AS PROMPTED:')
FCMMAT (5X, FOR LEVEL', 12, ':')
                                                                           MAIN2070
                                                            . . .
      FORMAT (1X/5X, 'IF YOU WISH TO AMALYZE EQUIVALENT SCREENS ', 'ENTER MAIN2090
     1 CHE'/6X,'IF NOT, ENTER ZERO:')
                                                                           MAIN2110
      SUBCCUTINE BOURD (X.EL, BU, PER)
                                                                           EOUN 10
      DIMENSION B(2), PR(2)
      IF (X.LE.O.) GO TO 50
                                                                                 30
      PR(2)=(1.-PER)/2.
                                                                           RUCE
      PR(1)=PER+PR(2)
                                                                           BOUN
      X1=5*X
                                                                           EOU:1
C
                                                                           BCUN
                                                                                 70
                            CO 40 I=1,2
                                                                           BOUN
      B(I)=(((FLOAT(I-2)*2.58*SGRT(2.))+SGRT(2.*2.58**2+4*X1))/2)**2
```

LO	IF (B(I).LT.0.5) GO TO 20	BOUN	100
	CALL MOCH (X1.B(I).P.IER)	BOUIL	110
	P=P-P2(I)	BOUN	120
	8138(I)+0,305	BOUN	130
	CALL MICH (X1.81,P1,IER)	BOUN	140
	P1*P1-F7(I)		150
	BH=C(I)-(P+0.005)/(P1-P)	BOLDI	160
	IF (ABS(QN-B(I)), LE. 0.0005) GO TO 30	BOUN	170
	A/ TieMi	BOUN	• • •
	GO TO 10	BOUR	
20	6(I)=0.0	BOUN	
-	CO TO 40	BOUN	
30	D(I) = E1(BOUN	
48	CONTINUE	BOUN	
+0	AL -01 AL 01 TO THE LANGUE AND A LANGUE AND) BOUN	
	BL=FLUAT(IFIX((ATAXI(BL)),2.)-2.1/2.) IF (B(1),LE.2.4) BL=0. BU=FLOAT(IFIX(B(2)/2.+0.9)) IF (BU.LE.0.) BU=0.) BOOM	
	11 (8)11.12.2.4) 8137.	BOUN	
	EUSPLOAT(IPIX(B(Z)/2.40.4)	BOUN	200
	IF (8U.LE.O.) 8U=0.	BOUN	270
	GO TO +0	DOWN	
50	8 L=0.	BOUN	290
	eu=o.	BOUN	300
60	RETURN	BOUN	31^
	취원	BALAL STATE	320
	SUCROUTINE HEAN (N.XLAMS, XMP, T.OMSS, F	ALL) MEAN	10
	IF (0:35.GT.0.999) GO TO 10	MEAN	20
	AORITALUES	HEAN	30
		HEAN	40
	RK=-ALCS(CHSS)/(XLAHS+T)	HEAN	50
	A2=RK#XLAtts	MEAN	60
	FALL=AGHT+A1H(1EXP(-A2HT))	MEAN	70
	GO TO 20	HEAN	
10	F :L: =0.0	MEAN	
20	RETURN	MEAN	100
	EIE	MEAN	
	SUBROUTINE HUFLON (HARK, COME, ON, TS, AF		
	CIMENSICH MARK(3), CCME(3), ON(3), TS		
	86 16 7-1 1		
	TT (WIRWITT 17 11 40 40 40 14	*****	
	TR/ T1=1811/171/0000/71		
10	CONTINUE	NUFL	
	IF (ILPRK(1).LE.0) GO TO 20		-
	# AFF#FFME(1)#(1 _TE(1))		
	PLACE=COME(1)#(1TS(1)) COME(2)=COME(2)+(PLACE-ON(1))	NUFL	
	CN(1)=PLACE	NUFL	
	f(1)=CC:1E(1)-CH(1)		
20	IF (MARK(2).LT.1) GO TO 30	HUFL	110
20	TS(2) #AFALL(2)/COME(2)	NUFL	120
		NUFL	130
30	CHSS=1TS(2)	NUFL	. 190
	C'LL MEAN (NPARTS, XLAM31, COME(2), TIME		150
	PLACE=CONE(2)-F(2)	NOFL	160
	COME(3)=COME(3)+(PLACE-OME2))	NUFL	
	CH(2)=PLACE	NUFL	
	IF (MARK(3).LT.1) GO TO 40	NUFL	
	TS(3)=AFALL(3)/CCME(3)	HUFL	
43	C155=1T5(3)	na n	. 210

	CALL MEAN (MPARTS.XLAMBI.COME(3).TIME(3).OMSS.F(3))		. 624
	CH(3)=COHE(3)-F(3)	MUTL	, 23q
	BETI INM	NUPL	. Z90
	######################################	-	250
	Sta		
	SURROUTINE SOLVE (J. ISCR. TS. TS1.AT)	POLA	10
	SHE SUEROUTINE SOLVE (J.ISCR.TS.TS1.AT) OINCHISION ISCR(3), TS(3), TS1(3), AT(3), PARAM(3.5.4) REWIND 12	SOLY	' 20
	REMIND 12	SOLV	30
	MSMATM AS	WALV	40
	00 10 1H=1.3	. 3027	
	DC 10 KB1-5	3067	
	DO 16 H=1.4	_ 20f7	' . 6 0
	00 16 H=1,4 IF ((K.NE.2).AND.(H.GT.2)) GO TO 10 READ (12.0) PARAM(IN.K.H).PARAM(IN.K.H)	SOLV	70
	ar in the state of	TO U	80
10	CONTINUE	2C.FA	. 1 0
	DO 20 NB1.3	3UL1	700
	Mark 9	SOLV	110
	TO A COMMENT OF ALL MANA	ent V	120
	HHTT2 IF (ISCR(N).EQ.2) HHTT4		
	PARAM JIADGRUM MENTATUM		
20	CONTINUE	. 30LY	_ T#0
	IT#O	20FA	124
	CALL F (J.C1,IT,PARAH,TS,TS1,ISCR,T1.THEN)	SOLV	140
	white is in the state of the st		174
	I7=1	POLA	1/0
	T1=AT(J)	20LV	190
	CALL F (1.C1.TT.WARANATSATSLATSCHATLATNEW)	BULY	170
	TC=TEFB(1)	SOLV	200
	IG=ISCR(J) GO TO (30,40,50,50,50), IG IF (TNEM.GT.240.) TNEW=240. MRITE (4,70) J.TNEW	4014	210
	60 10 (30,40;50;50;50), 10		
30	IF (TNEW.GT.ZGG.) THEW=ZGG.	SOLA	220
	MITE (6,70) J.TNEH	SOLV	Z30
•	MRITE (6,70) J,TNEW GO TO 60 IF (THEM.GT.40.) THEM=40.	SOLV	240
60	TE (THEU ST AS) THEWAS.	SOLV	250
•	LISTER AS A TIMELS	COLV	240
	SO TO 60 IF (THEH.GT.60.) THEH=60.	20FA	2/0
50	IF (THEN.GT.60.) THEW=60.	SOLV	_28 0
	LETETE (6.90) J. THEN	SOLV	290
60	CONTINUE	SOLV	300
•	RETURN	en v	310
	RETURN		720
:		. 30LY	320
;		SOLV	330
70	FORMAT (1X//5X, 'INCREASE TIME ON LEVEL', IZ, 'TO ', F10.2, 'HOURS.'	150LV	340
10	FORMAT (1X//SX, 'INCREASE NUMBER OF CYCLES ON LEVEL', 12, ' TO ', F10		
	1977)	SOLV	340
	FORMAT (1X//SX, 'INCREASE TIME ON LEVEL', 12, 'TO ', F10.2, 'HINUTES		370
10	LCSURT (IXXX2X), INCREASE LIBE ON FEAST, 151, 10 , 1910-51, UTHOLES	. 20FA	3/0
	1//)	SOLV	
		KOI V	390
	SUPPORTING F ().C1.TT.PARAN.TS.TS1.TSCP.T1.THEW)		10
	SUPPOUTINE F (J.Cl.IT, PARAH, TS.TSL.ISCR.TL.TNEH) DIMENSION PARAH(3,5.4), ISCR(3), TS(3), TS(3)		20
	DESCRIPTION PARAMETER TO LOCATE TO TOTAL TO THE PARAMETER		
	IS=ISCR(J)	. <u>P</u>	30
	CO 10 (10,50,80,80,80), 16	,	40
LO	IF (IT.GT.0) 60 TO 20	. F	50
	TIKE=PARAM(J,1,2)		60
	TIME=PARAH(J,1,2) ST=TS(J)		70
	\$T=TS(J)	. 💆 🕠	70
	5D TO 30		80
20		P .	90
	60 TO 40 0:495(25 -840)H((.1.11)	•	TAA
30	R=ASS(25PARAM(J,1,1))		110
-	BOALBRIDGE LLS L		120

	C1=(-ALOG(1ST/.45)/(RHH.6HD1	'002.70T3HE00.5))	130
44			140
50	IF (17.67.8) 60 TO 60		150
	HCY=PARAM(J.2.4)		160
	\$T=T3(J)	the second secon	
	\$T=TS(J) 63 TD 70	· · · · · · · · · · · · · · · · · · ·	
40 -			180
	PETI (2)	4(3)14)14(444.3)VCT1445	190
70	PERCAMI I. 2 11-MADAMI I 2 21	P(J),1))#T1##.5)/C1)##2	200
••	STULL STEEL LANGUAGE STEEL	ere en	210
	61-146611 67/46711 J161311		220
	RETURN	442.74NCY44,51)	230
80			240
	1 -1 WENTER 31730M 31151		
			260
	IG=ISCR(J) GO TO (90,90,90,100,110), IG D=.144*PARAH(J.3,1)0862		270
	GO TO (90,90,90,100,110), IG		280
90	D=.194#PARAM(J.3,1)0862		290
	£-4-3		300
	GO TO 120		310
100	C=.0635"PARAM(J,4,1)+.1065		320
	E=0.6		330
	60 TO 120		
110	D=.04354PAPAH(J,5,1)+.324		350
	E=0.2	And the second of the second o	360
129	IF (IT.GT.0) GO TO 130		370
	C1=-ALCG(1,-ST/D)/THME		380
	RETURN		300
130	THEIR((TIWERCON(ISCR(J) , PARAM	(J.ISCR(J),1)))/C1)##(1./g) #	: 70
	RETURN	· • · • · • · • · • · • · • · • · • · •	400
	85	7	410
	FUNCTION CON (I, PARAH)	to the contract of the contrac	920
•	Libita volas	CON	10
•	GD TO (40.46.10.20.30). I		. 20
10	CCM=(.266*P/RAM+1.402)++(-1)	CON	30
	60 TO 46		40
20	CCM=(.0176#PARAM+7.097)##(-1)	CON	50
	62 TO 40	CON	60
30	COM=(419#PARAM+8.420)##(-1)	CON	70
43	RETURN	CCN	80
••	ES	CON	90
	SUBROUTTHE EQUIV (HEG)	CON	100
	DIMENSION P(5,3,2), ISCR(2)	IUPS IUPS	10
10	LAITE (6.130)	Equi	20
••	FLAG=0.	EQUI	30
C	, ,	Ediz Ediz	40
•	LRITE (6,140)	EQUI	50
	READ (5,*) ISCR(1)	EGUI	60
	##ITE (6,150)	EGUI	70
	READ (5,*) ISCR(2)	EQUI	80
C	ueun 131=1 T3P4(5)	EQUI	90
~	80 70 7-1 0	EQUI	100
	CO 70 I=1,2	EGUI	110
29	GO TO (20,30), I	ECUI	120
60	1717E (6.160)	ECUI	130
	M=ISCR(I)	IUPS	140
	CO TO (40,50,60,60,60), M	EQUI	150

20	HRITE (6,170)	100	160
	H=ISCR(I) E0 60 TO (40,50,60,60,60), H E0	HIT	180
40	katar (**180)	TUE	190
•	READ (5,*) P(1,1,1),P(1,2,1)	IUC	200
	GO TO 70	IUE	210
50	171TE (6,190) EG	UI	220
	NRITE (6,190) EG READ (5,*) P(2,1,1),P(2,2,1),P(2,3,1) EG	IUK	230
	69 10 70	w	241
40	MRITE (6,200)	IUK	250
	NRITE (6,200) EG READ (5,*) P(ISCR(I),1,1),P(ISCR(I),2,1) EG	IUK	260
70	Cuit I I NOS	•••	6/4
C		UI	280
	K#1 EC CALL SSF (ISCR(1). X. ₹, X, FL/G, GTS) EC L#3TF (A. 210) GTS	ZUI	290
	CALL SSF (ISCR(1).X.4,X,FL/G,GTS)	IU	300
	K=2 EG	UI	320
	X1=1. EG	MI.	330
	120	ΩI.	340
	J=0 EG CALL SSF (7SCR(K),K,P,X,FLAG,GTS) EG TE (FLAG GT) GO TO 110	717	350
	- 11 11 LAGIGITAL A TO 10 144	~-	~~
	HT=1SCR(2) EG 60 TO (80,90,100,100), MM EG LESTE (4,220) V	NIT.	3/4
80	KRITE (6,220) X EG	HIT	200
••	GO TO 120	XIT	400
90	GO TO 120 EQ	IUK	410
	GO TO 120	UI	420
100	KRITE (6,240) X	UI	430
110	FLAS=0. EQ	UI	440
120	M:1 E (6,250)	UI	950
	READ (5,*) L EQ IF (L.GT.0) GO TO 10 EQ	NI.	460
	IF (L.GT.0) GO TO 10	UI	470
		UI	480
<u>c</u> .	EG	UI	490
C	FORMAT (1X/1X, FOLLOWING ARE THE SCREEN EQUATIONS AVAILABLE: '/1X, 'EQ		
130			
	11. CCMSTANT TEMPERATURE'/IX,'2. TEMPERATURE CYCLING'/IX,'3. RANEG COOM VIERATION'/IX,'4. SINE SHEEP VIDRATION'/IX,'5.',' SINE FIXEDEG		
		UI	
140	FORMAT (1X, 'ENTER NUMBER FROM ABOVE LIST CORRESPONDING TO GIVEN ', EQ	NIT.	550
		UI	
150	FORMAT (1X, 'ENTER HAMBER FROM ABOVE LIST CORRESPONDING TO ', 'DESIREG		
		UI	
160	15D SCREEN:') EQ FORMAT (1X/1X, 'ENTER PARAMETERS FOR GIVEN SCREEN:') EQ FORMAT (1X/1X, 'ENTER BADIMETERS FOR DESIRED SCREEN:'/2X, 'ENTER PERFOR	UI	590
170	FORMAT (1X/1X, 'ENTER PARAMETERS FOR DESIRED SCREEN; '/2X, 'ENTER ZEREG	UI	600
	10 FCR PARAMETER TO BE FOUND: 1) EQ	UI	610
180	FORMAT (1X/1X, 'ENTER ADSOLUTE VALUE OF DIFFERENCE BETWEEN', 'TEMP EQ		
		UI	
190	FORMAT (1X/1X, 'ENTER RANGE IN DEG C'/2X, 'TEMP RATE OF CHANGE IN DEEG	UI	640
	16 C/MIN'/2X, 'AND NUMBER OF CYCLES') FORMAT (1X/1X, 'ENTER G LEVEL AND TIME IN MINUTES') FORMAT (1X/1X, 'TEST STRENGTH FOR GIVEN SCREEN=',F7.4) FORMAT (1X/1X, ' PARAMETER IN DESIRED CONSTANT TEMP SCREEN=',F10.1)EQ	UI	650
22 0 210	EDMAT (19719 ITEM TORING BY AND TIME IN HINGS)	UĮ.	900
220	FORMAT (1X/1X, FEST STRENGTH FOR GIVER SCREEN=",F7.4) FORMAT (1X/1X, PARAMETER IN DESIRED CONSTANT TEMP SCREEN=",F10.1)EQ	JI	0/Q
220	FORMAT (1X/1X, PARAMETER IN DESIRED TEMP CYCLING ', 'SCREEN=', F10.19EG		
	11)		

77

	WRITE (6.230)	55r	
	FLAG=1.	SSF	•
	RETURN	SSF	
			•
			•
	RETURN	33F	
	X1=1.	, 33F	
	J=0	\$5F	
	J=0 xi=x1-(SSF1(ICUE,1.P,X1)-GTS)/SSF1(ICUE,2,P,X1)	SSF	
	J=J+J	995	
	IF (J.GT.50) GO TO 220	-	
		337	•
	IF (ADS(XH-X1).LE.0.005) GO TO 210	35F	•
	X1=XN	SSF	
	IF (X1.LE.O.) X1=J		
	GO TO 200		
	X=X01		
٠		337	
	WRITE (6,240)	33F	
	FLAG=1.	33F	
	RETURN	55F	
	DEEUG INIT	SSF	
	* ***	SSF	•
•			:
•	FORMAT (1X. SOLUTION NOT POSSIBLE FOR DESIRED & LEVEL.)	SSF	
			٠
_	FORMAT (1X, 'SOLUTION CANNOT BE FOUND BY INTERNAL METHOD. 1/2X, 'TRY	33F	
1	LA GRID OF POSSIBLE SOLUTIONS.')	55F	
	END FURCTION SSFI (IDS,L,P,XI)	55F	
	FLUCTION SSF1 (TDS.1.P.Y1)		
		22LT	
	DIMERCION P(5.3.2)	33F1 35F1	
	DANCIGADA PISISIE)	33F 1	
	GO TO (10.20,30.30,30), IDS	35F1	
	GO TO (10.20,30.30,30), IDS T=X1	55F1 55F1	,
	GO TO (10,20,30,30,30), IDS T=X1 RETURN	55F1 55F1 55F1	
	GO TO (10,20,30,30,30), IDS T=X1 RETURN RHCY=X1	55F1 55F1 55F1 55F1	
	GO TO (10,20,30,30,30), IDS T=X1 RETURN RHCY=X1 RETURN	55F1 55F1 55F1 55F1	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2)	5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2)	5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2,2) GO TO (40,40,40,50,40), IDS	5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RHEXT=X1 RETURN T=P(IDS,2,2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402	5571 5571 5571 5571 5571 5571 5571	
	GO TO (10,20,30,30,30), IDS T=X1 RETURN RECURN RECURN T=P(IDS,2,2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BC=.264	5571 5571 5571 5571 5571 5571 5571	
	GO TO (10,20,30,30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266#X1+1.402 BC=.264 D=.144#X10862	55F1 55F1 55F1 55F1 55F1 55F1 55F1 55F1	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 DD=.144*X10862 DD=.144*	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 DD=.144*X10862 DD=.144*	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 DD=.144*X10862 DD=.144*	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 DD=.144*X10862 DD=.144*	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RHSSY=X1 RETURN T=P(IDS,2,2) GO TO (40,40,40,50,60), IDS B=.266=X1+1.402 BD=.264 D=.144=X10862 DD=.144 CZ-S GO TO 70 B=.0176=X1+7.097	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 D=.144*X10862 DD=.144 C=.5 GO TO 70 B=.0176*X1+7.097 B8=.0176	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,60), IDS B=.2660*X1+1.402 BC=.266 0=.1440*X10862 00=.144 C=.5 GO TO 70 B=.0176*X1+7.097 B8=.0176 D=.0635*X1+.1065	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2,2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BC=.264 O=.144*X10862 OD=.144 C=.S GO TO 70 B=.0176*X1+7.097 BB=.0176*X1+7.097 BB=.0176*X1+7.095 OD=.0635*X1+.1065 OD=.0635	5571 5571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECTURN T=P(IDS.2,2) GO TO (40.40,40.50,40), IDS B=.266*X1+1.402 BD=.266 D=.144*X10862 DD=.144 C=.5 GO TO 70 B=.0176*X1+7.097 BS=.0176 D=.635*X1+.1065 DD=.0635 C=.8	3571 3571 3571 3571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266*X1+1.402 BD=.266 DD=.144*X10862 DD=.144*X10862 DD=.144*X10862 DD=.144 C=.5 GO TO 70 B=.0176*X1+7.097 BS=.0176 D=.0635*X1+.1065 DD=.0635 C=.8 GO TO 70	3571 3571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266*X1+1.402 BD=.266 DD=.144*X10862 DD=.144*X10862 DD=.144*X10862 DD=.144 C=.5 GO TO 70 B=.0176*X1+7.097 BS=.0176 D=.0635*X1+.1065 DD=.0635 C=.8 GO TO 70	3571 3571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,60), IDS B=.2660*X1+1.402 BD=.266 D=.1440*X10862 DD=.144 CZ.5 GO TO 70 B=.0176*X1+7.097 B8=.0176 D=.6635*X1+.1065 DD=.0635 CZ.8 GO TO 70 B=419*X1+8.620	3571 3571 5571 5571 5571 5571 5571 5571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.2660*X1+1.402 BC=.266 0:.144*X10862 00=.144 C=.5 GO TO 70 B=.0176*X1+7.097 88=.0176 0=.635*X1+.1065 00=.0635 C=.8 GO TO 70 B=419*X1+8.620 C3=419	53F1 53F1 53F1 53F1 53F1 53F1 53F1 53F1	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECTURN T=P(IDS.2,2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 D=.144*X10862 DD=.144 C=.5 GO TO 70 B=.0176*X1+7.097 BB=.0176*X1+7.097	3571 3571 3571 3571 3571 3571 3571 3571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECTURN T=P(IDS.2,2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BC=.266 D=.144*X10862 DO=.144*X10862 DO=.144*X10862 DO=.164*X1+7.097 BS=.0176*X1+7.097 BS=.0176*X1+7.097 BS=.0176*X1+7.097 BS=.0176*D=.0435*X1+.1065 DO=.0435*X1+.1065 DO=.0435*X1+.324 DO=.0435*X1+.324	3571 3571 3571 3571 3571 3571 3571 3571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECY=X1 RETURN T=P(IDS.2.2) GO TO (40,40,40,50,40), IDS B=.266**X1+1.402 BD=.266 D=.144**X10862 DD=.144**X10862 DD=.144**X10862 DD=.144**C=.5 GO TO 70 B=.0176**X1+7.097 BS=.0176 D=.0635**X1+.1065 DD=.0635**X1+.1065 DD=.0635**X1+.1065**X1+.1065 DD=.0635**X1+.1065**X1+.1065 DD=.0635**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**X1+.1065**	3571 3571 3571 3571 3571 3571 3571 3571	
	GO TO (10.20,30.30,30), IDS T=X1 RETURN RECTURN T=P(IDS.2,2) GO TO (40,40,40,50,40), IDS B=.266*X1+1.402 BD=.266 D=.144*X10862 DD=.144*X10862 DD=.144*X10862 DD=.144*X10862 DD=.144*X10862 DD=.0635*X1+1.065 DD=.0635*X1+.1065 DD=.0635*X1+.1065 DD=.0635*X1+.1065 DD=.0635*X1+.326 DD=.0435*X1+.326 DD=.0435*X1+.326	3571 3571 3571 3571 3571 3571 3571 3571	

SSF1=0+(1EXP(-T++C/B)) RETURN		33F1	3
EIS		33F1	3
MINDOUTTINE THE CHINA HAAD	TS.PLEFT,TLEFT,XLAHP1,XLAHP2,XLAHC1,XLAH	PTUT	3
12)	131PEEP111EEP. JACHEPEJACHEPEJACHEEJACHE	TAT	. :
		. TAT	- :
10000 11 444			
LAITE (6.20)		TIME.	. '
	MC1+(FLOAT(NPARTS)-PLEFT)#XLAMP1	INT	. :
Al=TLEFT		INT	. !
AZ=(PLEFT=XLAMPZ+(TLEFT-P	LEFT) #XLAHC2 3/TLEFT	. INT .	
T=2000.	,	. INT .	
00 10 I=1.10		, INT	
E=AG+T+AI=(IEXP(-AZ+T))		, INT .	1
XCITOF=T/E		INT	1
METIC (A130) INUIDA		744	1
T=F+2000.		, INT.	1
CONTINUE		_INT	1
RETURN		, INT.	_1
		INT	1
		INT	1
FORMAT (1X//////29X,'INT	ERVAL HTBF://27X,17('-')/29X,'TIME [','	INT	1
1 HTBF'/27X,17('-'))		INT	1
FC2HAT (28X.F6.0.' 1'.F7.	0)	INT	-
E)>		INT	3
SUPPORTING FITHE (NPARTS.	XLAMB, XNP, SS, TIME)	FTIH	-
SIMPROTAN TO STY SATISFE	E DATA TO	STIM	
M(T)=40=T+A1(1-EXP(-A2+T)))	STIM	
		PTTM	
CATION THE MODITURE TYPE			
EXTERNAL AMEANY			
EXICKNAL AREANY),XJAC(200,2),XJTJ(3),HORK(413)	FTIM	
	1) 'YAYCI 500 'S 1 'YALAC 31 'HOKKI 4131	FTIM	
REALMA T(200)		PILIT	
COSTON ZSQ.A0		PTIM	
		PTIN	١,
XH=FLOAT(HPARTS)		PTIM	
RK=-ALOG(155)/(TIME+XLA		PILIT	١.
LETTE (6.10)		PTIN	,
		, PTIM	
K=24H+13		PTIM	,
	3,XMP,RK,PARM,X,F,XJAC,XJTJ,WORK,T,M,K,TI		
18)		FTIM	i i
RETURN		PTTM	
		FTIH	:
	OF FAILURES DURING FINAL SCREEN: ')	. FTIH	1
EI:D		FTIH	1 :
SUCRCUTINE OFT (AMEANY, X)	N,XLAMB,XMP,RK,PARM,X,F,XJAC,XJTJ,MORK,T,	HOPT	
1,K.TIME)		OPT	
	F(H), XJAC(H,2), XJTJ(3), HORK(K), T(H)	OPT	
COTTON ZSQ.AO		OPT	
171TE (6,20)		QPT.	
00 10 IJ=1.H		OPT	
READ (5.*) T(IJ)	· · · · · · · · · · · · · · · · · · ·	OPT	•
WRITE (17.4) T(IJ)			
CCHTTISUE		OPT	
	* * * * * * * * * * * * * * * * * * *		

	DPI DXJAC=H	110
	NSIG=4 OPT	120
	EPS=0.0 OPT	130
	DELTA=0.0 OPT	140
• •	MAXFN=500 OPT	150
	IOPT=1 OPT	160
	AC=XN=XLAMS OPT	170
•	X(1)=X(P OPT	180
	X(2)=RK+XLAMB+1.E3 OPT	190
	CALL ZXSSQ (AMEANY.H.N.NSIG.EPS.DELTA.HAXFN.IOPT.PARH.X.SSG.F.XJACOPT	200
•	1.IXJAC.XJTJ.HCRK.INFER,IER) OPT	210
•	X(2)=X(2)=1.E-3 OPT	220
•		230
٠	INCOME AN USE ASS	240
•	BOTI MILL	250
	REIGHTOPT	260
	FORMAT (5X. 'ENTER FAILURE TIMES (HOURS), IN ORDER, AS PROMPTED: ') OPT	270
	FORMAT (SX. THE FAILURE TIMES INDICATE THAT THE ESTIMATED NUMBER!/OPT	280
	15X. OF DEFECTIVES ENTERING THE SCREEN IS '.F10.0/5X.' AND THE ESCPT	290
	Additional apparents and a second sec	300
	210	310
٠		
	MALLA WALL PRICAGO TOLAGO	1 20
		1 30 1 40
		1 50
	and the control of th	1 60
٠		. 50
	and the contract of the contra	70
٠	ing the first term of the contract of the cont	1 80 1 90
		1 70
٠		100
		110
•	SELTIMANTE TO THE BANKS IN THE	
		130
	GO TO 20 AME/	1 140
	FF(I)=AC*TT(I)+XX(1)-DFLOAT(I) AME	150
		160
		170
	RETURN	
		190
	FORMAT (1X, 'NEGATIVE AS ATTEMPTED NEW EXPECTED VALUES MAY', ' BE NAME,	
		210
	ENT AME A	220

MISSION of

Rome Air Development Center

RADC plans and executes research, development, test and selected acquisition programs in support of Command. Control Communications and Intelligence (C³1) activities. Technical and engineering support within areas of technical competence is provided to ESD Program Offices (POs) and other ESD elements. The principal technical mission areas are communications, electromagnetic guidance and control, surveillance of ground and aerospace objects, intelligence data collection and handling, information system technology, ionospheric propagation, solid state sciences, microwave physics and electronic reliability, maintainability and compatibility.

そのでくとうからからできるとうちゃくこく ちゃくし なる